


# Rocky Flats Environmental Technology Site

# TYPE 1 RECONNAISSANCE LEVEL CHARACTERIZATION REPORT (RLCR)

# **BUILDING 460 CLOSURE PROJECT**

**April 20, 2005** 

**REVISION 0** 



**ADMIN RECORD** 

CLASSIFICATION REVIEW NOT REQUIRED PER EXEMPTION NUMBER CEX-005-02



# TYPE 1 RECONNAISSANCE LEVEL CHARACTERIZATION REPORT (RLCR)

## **BUILDING 460 CLOSURE PROJECT**

**April 20, 2005** 

**REVISION 0** 

Reviewed by:

Don Risoli, Quality Assurance

1) If the MI

Reviewed by:

D.P. Snyder, RISS ESH&Q Manager

Approved by:

Mike Swartz, K-H D&D Project Manager

Date: 4.20.05

Date:

## TABLE OF CONTENTS

| ABBR | REVIATIONS/ACRONYMS                              | IV |
|------|--|----|
| EXEC | CUTIVE SUMMARY                                   | V  |
| 1    | INTRODUCTION                                     | 1  |
| 1.1  | Purpose  | 1  |
| 1.2  |  |    |
| 1.3  | DATA QUALITY OBJECTIVES                          | 1  |
| 2    | HISTORICAL SITE ASSESSMENT                       | 2  |
| 3    | RADIOLOGICAL CHARACTERIZATION AND HAZARDS        | 2  |
| 4    | CHEMICAL CHARACTERIZATION AND HAZARDS            | 3  |
| 4.1  | ASBESTOS   | 3  |
| 4.2  |  | 4  |
| 4.3  |  |    |
|      | (VOCs)]  | 4  |
| 4.4  | POLYCHLORINATED BIPHENYLS (PCBs)                 | 5  |
| 5    | PHYSICAL HAZARDS                                 | 5  |
| 6    | DATA QUALITY ASSESSMENT                          | 5  |
| 7    | DECOMMISSIONING WASTE TYPES AND VOLUME ESTIMATES | 6  |
| 8    | FACILITY CLASSIFICATION AND CONCLUSIONS          | 6  |
| 9    | REFERENCES                                       | 7  |
| ATT  | ACHMENTS   |    |
| Α    | Facility Location Map                            |    |
| В    | Historical Site Assessment Report                |    |
| C    | Radiological Data Summaries and Survey Maps      |    |
| D    | Chemical Data Summaries and Sample Maps          |    |
| E    | Data Quality Assessment (DQA) Detail             |    |

#### ABBREVIATIONS/ACRONYMS

ACM Asbestos containing material

Be Beryllium

CDPHE Colorado Department of Public Health and the Environment

CERCLA Comprehensive Emergency Response, Compensation and Liability Act
DCGL<sub>EMC</sub> Derived Concentration Guideline Level – elevated measurement comparison

DCGL<sub>w</sub> Derived Concentration Guideline Level – Wilcoxon Rank Sum Test

D&D Decontamination and Decommissioning

DDCP Decontamination and Decommissioning Characterization Protocol

DOE U.S. Department of Energy
DPP Decommissioning Program Plan

DQA Data quality assessment DQOs Data quality objectives

EPA U.S. Environmental Protection Agency
FDPM Facility Disposition Program Manual
HVAC Heating, ventilation, air conditioning
HSAR Historical Site Assessment Report
IHSS Individual Hazardous Substance Site
IWCP Integrated Work Control Package

K-H Kaiser-Hill
LBP Lead-based paint
LLW Low-level waste

MARSSIM Multi-Agency Radiation Survey and Site Investigation Manual

MDAMinimum detectable activityMDCMinimum detectable concentrationNORMNaturally occurring radioactive material

NRA Non-Rad-Added Verification

OSHA Occupational Safety and Health Administration

PARCC Precision, accuracy, representativeness, comparability and completeness

PCBs Polychlorinated Biphenyls
PDS Pre-demolition survey
QC Quality Control

RCRA Resource Conservation and Recovery Act

RFCA Rocky Flats Cleanup Agreement

RFETS Rocky Flats Environmental Technology Site

RFFO Rocky Flats Field Office

RLC Reconnaissance Level Characterization

RLCR Reconnaissance Level Characterization Report

RSP Radiological Safety Practices
SVOCs Semi-volatile organic compounds
TCLP Toxicity Characteristic Leaching Procedure

TSA Total surface activity

VOCs Volatile organic compounds

#### **EXECUTIVE SUMMARY**

A Reconnaissance Level Characterization (RLC) was performed to enable facility "Typing" per the DPP (10/8/98) and compliant disposition and waste management of Building 460. Because this facility was an anticipated Type 1 facility, the characterization was performed in accordance with the Pre-Demolition Survey Plan (MAN-127-PDSP). All facility surfaces were characterized in this RLC, including the interior floors, walls, ceilings, and equipment. Environmental media beneath and surrounding the facility was not within the scope of this RLCR and will be addressed at a future date using the Soil Disturbance Permit process and in compliance with RFCA.

The RLC encompassed both radiological and chemical characterization to enable compliant disposition and waste management pursuant to the D&D Characterization Protocol (MAN-077-DDCP). The characterization built upon physical, chemical and radiological hazards identified in the facility-specific Historical Site Assessment Reports.

Results indicate that no radiological contamination exists in excess of the PDSP unrestricted release limits of DOE Order 5400.5. A asbestos survey was completed in 1994 and determined that there is Category 1 non-friable asbestos containing vinyl asbestos floor tile and mastic (1.4%) in the Room 151 area. Category 1 non-friable asbestos containing caulk was also identified on the building exterior flashing between the concrete and metal walls that contain 1.0% asbestos. However, since these materials are Category 1 non-friable ACM, asbestos abatement is not necessary prior to demolition and the demolition debris can be managed as sanitary waste. All other asbestos samples were less than CDPHE, Regulation No. 8, Part B, Emission Standards for Asbestos limits. Sampling and analysis for RCRA Metals indicated the potential for lead to be above the regulatory limit of 5 ppm. Additional sampling and analysis confirmed the paint is leadbased. However, Environmental Waste Compliance Guidance #27, Lead-based Paint (LBP) and Lead-based paint Debris Disposal, states that LBP debris generated outside of currently identified high contamination areas shall be managed as non-hazardous (solid) waste, and additional analysis for characteristics of hazardous waste derived from LBP is not a requirement for disposal. Because there were no high contamination areas in Building 460, the paint meets unrestricted release criteria and may be disposed of as nonhazardous (solid) waste. All beryllium sample results were less than 0.1 µg/100cm<sup>2</sup>. Based upon this RLCR, Building 460 is considered a Type 1 facility and can be demolished. To ensure the facility remains free of contamination and the RLC data remain valid, Level 2 Isolation Controls have been established and the facility posted accordingly.

#### 1 INTRODUCTION

A Reconnaissance Level Characterization (RLC) was performed to enable compliant disposition and waste management of Building 460. Because this facility was an anticipated Type 1 facility, a PDS characterization was performed. All facility surfaces were characterized in this RLC, including the interior and exterior surfaces of the facility (i.e.; floors, walls, ceilings and roofs). Environmental media beneath and surrounding the facility was not within the scope of this RLC Report (RLCR) and will be addressed at a future date using the Soil Disturbance Permit process and in compliance with RFCA.

As part of the Rocky Flats Environmental Technology Site (RFETS) Closure Project, numerous facilities will be removed, among these is Building 460. The location of this facility is shown in Attachment A, *Facility Location Map*. This facility no longer supports the RFETS mission and needs to be removed to reduce Site infrastructure, risks and/or operating costs.

Before the facility can be removed, a Pre-Demolition Survey (PDS) must be conducted; this document presents the PDS results. The PDS was conducted pursuant to the Decontamination and Decommissioning Characterization Protocol (MAN-077-DDCP) and the Pre-Demolition Survey Plan for D&D Facilities (MAN-127-PDSP). The PDS built upon physical, chemical and radiological hazards identified in the facility-specific *Historical Site Assessment Report for the Area 5 - Group 7 Facilities*, Dated October 2002, Revision 0.

#### 1.1 Purpose

The purpose of this report is to communicate and document the results of the RLC effort. A RLC is performed before building demolition to define the pre-demolition radiological and chemical conditions of a facility. The pre-demolition conditions are compared with the release limits for radiological and non-radiological contaminants. RLC results will enable project personnel to make final disposition decisions, develop related worker health and safety controls, and estimate waste volumes by waste types.

#### 1.2 Scope

This report presents the pre-demolition radiological and chemical conditions of Building 460. Environmental media beneath and surrounding the facility is not within the scope of this RLCR and will be addressed using the Soil Disturbance Permit process and in compliance with RFCA.

#### 1.3 Data Quality Objectives

The Data Quality Objectives (DQOs) used in designing this RLC were the same DQOs identified in the Pre-Demolition survey Plan for D&D Facilities (MAN-127-PDSP.) Refer to section 2.0 of MAN-127-PDSP for these DQOs.

#### 2 HISTORICAL SITE ASSESSMENT

A facility-specific Historical Site Assessment (HSA) was conducted to understand the facility history and related hazards. The assessment consisted of facility walkdowns, interviews, and document review, including review of the Historical Release Report (refer to the D&D Characterization Protocol, MAN-077-DDCP). Results were used to identify data gaps and needs, and to develop radiological and chemical characterization packages. Results of the facility-specific HSA was documented in a facility-specific Historical Site Assessment Report for the Area 5 - Group 7 Facilities, Dated October 2002, Revision 0. Refer to Attachment B, Historical Site Assessment Report, for a copy of the Building 460 HSAR. In summary, the HSAR identified a low potential for radiological, chemical, asbestos and beryllium hazards.

#### 3 RADIOLOGICAL CHARACTERIZATION AND HAZARDS

Building 460 was characterized for radiological hazards per the PDSP. Radiological characterization was performed to define the nature and extent of radioactive materials that may be present on, or in the facility surfaces. Measurements were performed to evaluate the contaminants of concern. Based upon a review of historical and process knowledge, building walk-downs, and MARSSIM guidance, Radiological Characterization Plans were developed during the planning phases that describe the minimum survey requirements (refer to the RISS Characterization Project files).

Radiological survey packages 460002, 460003 and 460004 were developed for the interior of Building 460. The survey packages were developed in accordance with Radiological Safety Practices (RSP) 16.01, Radiological Survey/Sampling Package Design, Preparation, Control, Implementation and Closure. All Survey Units are MARSSIM Class 3 areas due to the low potential for radiological contamination in Building 460. Total surface activity (TSA), removable surface activity (RSA), and scan measurements were collected in accordance with RSP 16.02 Radiological Surveys of Surfaces and Structures. Radiological survey data were verified, validated and evaluated in accordance with RSP 16.04, Radiological Survey/Sample Data Analysis. Quality control measures were implemented relative to the survey process in accordance with RSP 16.05, Radiological Survey/Sample Quality Control.

Four hundred and three (403) TSA measurements (285 random, 101 biased and 17 QC) and three hundred and eighty six (386) RSA measurements (285 random and 101 biased) were performed; and a minimum 5% of the interior surfaces of the facility were scanned. The RLC data confirmed that this facility does not contain radiological contamination above the surface contamination guidelines provided in the PDSP. Radiological survey data, statistical analysis results, and survey locations are presented in Attachment C, Radiological Data Summary and Survey Maps. Radiological survey unit packages are maintained in the RISS Characterization Project files. Level 2 Isolation Control postings are displayed on the building entrances to ensure no radioactive materials are inadvertently introduced into the facility.

Exterior radiological surveys for Building 460 were performed as part of the West Side Exterior PDS Report, which was approved on March 24, 2005 by DOE and CDPHE. The West Side Exterior PDS Report confirmed that the exterior surfaces of Building 460 do not contain radiological contamination above the surface contamination guidelines provided in the PDSP. The West Side Exterior PDS Report and survey data, statistical analysis results, and survey map locations are maintained in the RISS Characterization Project files.

#### 4 CHEMICAL CHARACTERIZATION AND HAZARDS

Building 460 was characterized for chemical hazards per the PDSP. Chemical characterization was performed to determine the nature and extent of chemical contamination that may be present on or in the facility. Based upon a review of historical and process knowledge, visual inspections, and PDSP DQOs, additional sampling needs were determined. A Chemical Characterization Plan (refer to RISS Characterization Project files) was developed during the planning phase that describes sampling requirements, the justification for the sample locations and estimated sample numbers. Contaminants of concern included asbestos, beryllium, RCRA/CERCLA constituents, and PCBs.

#### 4.1 Asbestos

A comprehensive asbestos inspection was conducted to determine the presence of friable and non-friable asbestos containing building material. The characterization was conducted in accordance with the PDSP. A CDPHE-certified asbestos inspector conducted the inspection and sampling in accordance with the *Asbestos Characterization Protocol*, *PRO-563-ACPR*, *Revision 1*. Building materials suspected of containing asbestos were identified for sampling at the discretion of the inspector.

A comprehensive, invasive asbestos survey was completed in 1994 and determined that there is Category 1 non-friable asbestos containing vinyl asbestos floor tile and mastic (1.4%) in the Room 151 area. Category 1 non-friable asbestos containing caulk was also identified on the building exterior flashing between the concrete and metal walls that contain 1.0% asbestos. However, since these materials are Category 1 non-friable ACM, asbestos abatement is not necessary prior to demolition and the demolition debris can be managed as sanitary waste. Since the floor tile and caulking samples were collected in 1994, no sample location maps were available for this report.

Paint samples were collected in November 2003 to determine if there is a presence of skim coat that may contain asbestos. All 2003 laboratory results were non-detect for asbestos. On this basis, no additional asbestos sampling was required or performed as part of this RLC. Asbestos laboratory analysis data and sample location maps collected in 2003 are contained in Attachment D, Chemical Data Summaries and Sample Maps.

#### 4.2 Beryllium (Be)

Based on the HSAR and personnel interviews, Building 460 was an anticipated Type 1 facility. However, the High Bay area was on the List of Known Beryllium Areas. Therefore, random and biased beryllium sampling was performed in the High Bay areas accordance with the PDSP and the *Beryllium Characterization Procedure*, *PRO-536-BCPR*, *Revision 0, September 9, 1999*. Biased sampling was performed in the Building 460 office areas. Biased sample locations corresponded with the most probable areas of dust accumulation (including beryllium dust), assuming airborne deposition. All 125 random and biased beryllium swipe sample results were less than 0.1 µg/100cm<sup>2</sup>. Beryllium laboratory sample data and location maps are contained in Attachment D, *Chemical Data Summaries and Sample Maps*.

# 4.3 RCRA/CERCLA Constituents [including metals and volatile organic compounds (VOCs)]

Based on a review of the HSAR and a facility walk-down, Building 460 contained a small organic coatings laboratory and a silver recovery operation, as well as, a machine shop. Two samples and one duplicate were taken in room 141 where the tanks were located that stored and processed chromium. Because chromium was the only chemical stored in these tanks, only sampling and analysis for RCRA Metals was performed. On this basis, no VOC and SVOC sampling was performed as part of this RLC.

The analytical (RIN#05Z0992) for the core samples reported Total Concentration for lead greater than 100 mg/kg in two of the samples taken from in front of the tanks. This would indicate the potential for lead to be above the regulatory limit of 5 ppm. However, the sample taken from behind the tank did not have this level of lead concentration. The only difference between the sample locations was the type of paint covering the floor. Therefore, two confirmatory samples (RIN#05Z1155) of the paint in front of the tank were taken. The analysis confirmed that the paint is lead-based. However, Environmental Waste Compliance Guidance #27, Lead-based Paint (LBP) and Lead-based paint Debris Disposal, states that LBP debris generated outside of currently identified high contamination areas shall be managed as non-hazardous (solid) waste, and additional analysis for characteristics of hazardous waste derived from LBP is not a requirement for disposal. Because there were no high contamination areas in Building 460, this paint may be disposed of as non-hazardous (solid) waste. Consequently, additional sampling for lead in paint in Building 460 is not required.

RCRA permitted units 39.03 and 40.08-40.15, were closed in accordance with the RCRA Closure Plan for the B460 Process Waste System (10/19/95), and the Closure Certification was signed on 9/16/96 (96-DOE-05751). The remaining portion of RCRA unit 374.3 in B460 was closed under the CDD for the 400 Area Valve Vaults. The Closure Summary Report was submitted on 6/23/03 (03-RF-00967). The RCRA permitted storage Unit 460.1, in the highbay of B460, was closed in accordance with Part X.D.1.a. – Clean Closure Option #1: Unit Review and Inspection. A PE Certification will be submitted with the Closure Summary Report. RLC laboratory sample data and location maps are contained in Attachment D, *Chemical Data Summaries and Sample Maps*.

#### 4.4 Polychlorinated Biphenyls (PCBs)

Based on the HSARs, interviews and facility walk-downs of Building 460, no PCB-containing equipment was ever present in the building, making the potential for PCB contamination resulting from spills highly unlikely. Therefore, PCB sampling was not performed in Building 460 as part of the RLC. Based on the age of Building 460 (constructed after 1980), paints used are assumed to not contain PCBs. Additionally, the building is likely to contain PCB light ballasts. All light ballasts will be inspected and if leaking or large (greater than 9 pounds) PCB ballasts are discovered, they will be removed prior to demolition and managed accordingly.

#### 5 PHYSICAL HAZARDS

Physical hazards associated with Building 460 consist of those common in standard industrial environments and include hazards associated with energized systems, utilities, and trips and falls. The facility has been relatively well maintained and is in good physical condition, and therefore, does not present hazards associated with building deterioration. However, care should be taken during demolition as Building 460 is associated with the following IHSSs, PACs and/or UBCs:

- 400-136.1, "Cooling Tower Pond East of Building 444"
- 400-157.2, "Radioactive Site South Area Active"
- 400-205, "Building 460 sump No. 3, Acid Side Active"
- 400-804, "Road North of Building 460 Active"
- 400-812, "Tank T-2 spill in Building 460 Proposed NFA in 2001"
- 400-813, "RCRA Tank Leak in Building 460 Active"
- 400-815, "RCRA Tank Leak in Building 460 Active"

Physical hazards are controlled through the Site Occupational Safety and Industrial Hygiene Program, in accordance with OSHA regulations, DOE orders, and standard industry practices.

#### 6 DATA QUALITY ASSESSMENT

Data used in making management decisions for decommissioning of Building 460, and consequent waste management, are of adequate quality to support the decisions documented in this report. The data presented in this report (Attachments C and D) were verified and validated relative to DOE quality requirements, applicable EPA guidance, and original DQOs of the project.

In summary, the Verification and Validation (V&V) process corroborates that the following elements of the characterization process are adequate:

- the *number* of samples and surveys;
- the *types* of samples and surveys;
- the sampling/survey process as implemented "in the field"; and,
- the laboratory analytical process, relative to accuracy and precision considerations.

Details of the DOA are provided in Attachment E, Data Quality Assessment Detail.

#### 7 DECOMMISSIONING WASTE TYPES AND VOLUME ESTIMATES

The demolition and disposal of Building 460 will generate sanitary waste suitable for disposal at an RFETS-approved sanitary waste landfill. Estimated waste volumes are presented below. All waste can be disposed of as sanitary waste, there is no radioactive or hazardous waste.

| Waste Volume Estimates and Material Types – Building 460 |         |         |         |         |         |         |             |  |  |  |
|--|---------|---------|---------|---------|---------|---------|-------------|--|--|--|
| Concrete Wood Metal Sheet Metal Wall Board ACM           |         |         |         |         |         |         |             |  |  |  |
| Facility   | (cu ft) | Other Waste |  |  |  |
| 460  | 42,400  | 0       | 73,000  | 24,000  | 20,600  | 100     | NONE        |  |  |  |

#### 8 FACILITY CLASSIFICATION AND CONCLUSIONS

Based on the analysis of radiological, chemical and physical hazards, Building 460 is classified as a RFCA Type 1 facility pursuant to the RFETS Decommissioning Program Plan (DPP; K-H, 1999) and can be demolished. The Type 1 classification is based on a review of historical and process knowledge, and newly acquired RLC data.

The RLC of Building 460 was performed in accordance with the DDCP and PDSP. All PDSP DQOs were met, and all data satisfied the PDSP DQA criteria. Building 460 did not contain radiological or hazardous waste. Category 1 non-friable asbestos containing caulk was also identified on the building exterior flashing between the concrete and metal walls that contain 1.0% asbestos. However, since these materials are Category 1 nonfriable ACM, asbestos abatement is not necessary prior to demolition and the demolition debris can be managed as sanitary waste. Sampling and analysis for RCRA Metals indicated the potential for lead to be above the regulatory limit of 5 ppm. Additional sampling and analysis confirmed the paint is lead-based. However, Environmental Waste Compliance Guidance #27, Lead-based Paint (LBP) and Lead-based paint Debris Disposal, states that LBP debris generated outside of currently identified high contamination areas shall be managed as non-hazardous (solid) waste, and additional analysis for characteristics of hazardous waste derived from LBP is not a requirement for disposal. Because there were no high contamination areas in Building 460, the paint meets unrestricted release criteria and may be disposed of as non-hazardous (solid) waste. Environmental media beneath and surrounding the facility will be addressed at a future date using the Soil Disturbance Permit process and in compliance with RFCA.

To ensure this Type 1 facility remains free of contamination and the RLC data remain valid, Level 2 Isolation Controls have been established and the facility posted accordingly.

#### 9 REFERENCES

DOE/RFFO, CDPHE, EPA, 1996. Rocky Flats Cleanup Agreement (RFCA), July 19, 1996.

DOE Order 5400.5, "Radiation Protection of the Public and the Environment."

EPA, 1994. "The Data Quality Objective Process," EPA QA/G-4.

K-H, 1999. Decommissioning Program Plan, June 21, 1999.

MAN-131-QAPM, Kaiser-Hill Team Quality Assurance Program, Rev. 1, November 1, 2001.

MAN-076-FDPM, Facility Disposition Program Manual, Rev. 3, January 1, 2002.

MAN-077-DDCP, Decontamination and Decommissioning Characterization Protocol, Rev. 3, July 15, 2002.

MAN-127-PDSP, Pre-Demolition Survey Plan for D&D Facilities, Rev. 1, July 15, 2002.

MARSSIM - Multi-Agency Radiation Survey and Site Investigation Manual, December 1997 (NUREG-1575, EPA 402-R-97-016).

PRO-475-RSP-16.01, Radiological Survey/Sampling Package Design, Preparation, Control, Implementation, and Closure, Rev. 1, May 22, 2001.

PRO-476-RSP-16.02, *Pre-Demolition (Final Status) Radiological Surveys of Surfaces and Structures*, Rev. 1, May 22, 2001.

PRO-477-RSP-16.03, Radiological Samples of Building Media, Rev. 1, May 22, 2001.

PRO-478-RSP-16.04, Radiological Survey/Sample Data Analysis for Final Status Survey, Rev. 1, May 22, 2001.

PRO-479-RSP-16.05, Radiological Survey/Sample Quality Control for Final Status Survey, Rev. 1, May 22, 2001.

PRO-563-ACPR, Asbestos Characterization Procedure, Revision 0, August 24, 1999.

PRO-536-BCPR, Beryllium Characterization Procedure, Revision 0, August 24, 1999.

RFETS, Environmental Waste Compliance Guidance #25, Management of Polychlorinated Biphenyls (PCBs) in Paint and Other Bulk Product Waste During Facility Disposition.


RFETS, Environmental Waste Compliance Guidance #27, Lead-Based Paint (LBP) and Lead-Based Paint Debris Disposal.

RFCA Standard Operation Protocol for Recycling Concrete, September 28, 1999.

Historical Site Assessment Report for the Area 5 - Group 7 Facilities, Dated October 2002, Revision 0.

# ATTACHMENT A

Facility Location Map



# ATTACHMENT B

# Historical Site Assessment Report

#### Facility ID: (AREA 5 - Group 7) Buildings 460, 439, 462, 668, and T664A.

Anticipated Facility Type (1, 2, or 3): Buildings 460, 439, 668, 462 and T664A are anticipated Type 1 facilities.

This facility-specific Historical Site Assessment (HSA) has been performed in accordance with: D&D Characterization Protocol, RFETS MAN-077-DDCP, latest version, and Facility Disposition Program Manual, RFETS MAN-076-FDPM, latest version

#### **Physical Description**

#### **Building 460**

Building 460 is a 212,980 square foot, two-story structure, built in 1984. The structure is a pre-fabricated building constructed on a concrete foundation. The exterior walls are constructed of insulated metal panels attached to a steel frame. The roof is constructed of metal decking with built-up roofing. Building 460 is configured with the south half of the building as office space and a high-bay area on the north half of the building. The ceilings of the office area are 2-foot by 4-foot acoustical panels with recessed light fixtures. The floors in the offices are mostly carpeted. The ceiling in the high-bay area is the underside of the roof and the floor is concrete.

Building 460 has the following utilities: electrical, plant water, plant sanitary, plant steam, and fire protection is provided by an overhead sprinkler system and wall mounted fire extinguishers. Building 460 was originally connected to the site process waste system. The building's process waste system was isolated in the mid 1990s.

#### **Building 439**

Building 439 is a 5,140 square foot, single story building constructed in 1971. This structure is a pre-fabricated insulated metal building constructed on a concrete slab. This building is configured with a high bay area in the center of the building and several smaller machine rooms and offices on the east and west sides of the building.

Building 439 has the following utilities: electrical, plant water, plant sanitary, and fire protection is provided by an overhead sprinkler system and wall mounted fire extinguishers.

#### **Building 462**

Building 462 is a 590 square foot cooling tower constructed in 1985 and provides cooling water to Building 460. Building 462 is a metal structure elevated above a concrete pad by 8 concrete pedestals.

Building 462 has the following utilities: electrical and plant water.

#### **Building 668**

Building 668 is a 1,540 square foot single-story building constructed in 1957. The exterior walls are Transite® panels and fiberglass panels, the floor is a concrete pad pour on grade. Building 668 is not a heated building and does not have a ventilation system. The building was once wire for electricity but is currently disconnected. The building was also fitted with fire protection sprinkler heads, but these heads were never activated.

Building 668 currently has no utility hook-ups.

#### Trailer T664A

Trailer T664A is a 4,392 square foot general office trailer acquired in 1991. This trailer has corrugated metal siding with corrugated metal skirting. The entrances have wooden stairs leading to a wooded enclosure. The interiors are primarily a cubical layout, but have several hard-walled offices, conference rooms, and rest rooms. Interior walls are wallboard, the ceiling is a drop ceiling with acoustical tiles and recessed lights. The floors are primarily covered with carpet except in the bathrooms, which are covered with vinyl tile.

Trailer T664A has the following utilities: electrical, plant water, plant sanitary, and fire protection is provided by an overhead sprinkler system and wall mounted fire extinguishers.

#### **Historical Operations**

#### **Building 460**

Building 460 was originally constructed as a manufacturing facility designed to fabricate stainless steel and other non-nuclear parts such as reservoirs, tubes, and non-fissile trigger components. Building 460 housed fabrication operations such as Mechanical Machining in Room 134, Electrochemical machining and Grinding in Room 141, Electro Discharge machining is room 141, and Crush grinding in room 142. Assembly machining in room 143, welding in rooms 122A, 122C, 132, 132B, 132C and 135, Grit Blasting in room 135B, Cleaning in rooms 156, 156C, and 157. Inspection operation in rooms 115A, 115H, 121, 122B, 123, 151A, 151S, and 163. A metallurgical laboratory was operated in Room 135. Room 141B housed a Hexavalant Chrome reduction process which was not part of the RCRA permit due to its classification as a recycling operation and this equipment still remain. Building 460 also had a cafeteria on the second floor until the mid 1990s

Non-radioactive process wastes were collected in 4 sump tanks. Sump Tank ST1 was located in room 141B, ST2 was located in Room 151, ST3 was located in Room 156, and T4 was located in room 156C. All these tanks have been closed in accordance with the "RCRA Closure Plan for the B460". The facility's process wastewater collection and filtration system was located in Room 140 and consisted of 2 holding tanks and a sump tank. Wastewater was filtered prior to being transported to Building 374 for treatment. These tanks have also been closed in accordance with the "RCRA Closure Plan for the B460". Most of the process waste lines were overhead lines and only in a few areas were they located in the concrete floor slab. Much of the process waste lines and process waste equipment were removed during the closure process. Waste streams handled in Building 460 included solvents, metals, and acids. See the building 460 WSRIC for a more complete list of process that occurred in Building 460.

In the mid 1990 manufacturing operation ended in Building 460 and most of the process equipment was removed. The building was then used as an administrative office building housing primarily DOE personnel. Building 460 begin storing low level radioactive, RCRA and TSCA wastes in September 2002. Building 460 is currently a containerized waste storage facility, and does not perform any waste repackaging or waste treatment.

#### **Building 439**

Building 439 was originally a fabrication and machine shop, which supported Building 440 operations as well as other R&D operations. Historically, this building housed such operations as an organic coating lab in the southeast corner of the building. A machine shop located on the west side of the building, quality assurance testing equipment such as NDT, ultrasonic density testing and tinsel testing equipment on the north side of the facility. Other operation housed in Building 439 include electronic equipment services, Gamma Survey instrument maintenance, silver recovery related to electronic equipment, Radiological counting and survey operations, and PU&D equipment release operations. Currently Building 439 is currently used to store equipment, as a break room, and general offices in support of Building 440 operations.

#### **Building 462**

Building 462 is the evaporative cooling tower for Building 460. The cooling system consists of both an open loop and closed loop system interconnected by a heat exchanger. Nalco 2536 is added to the cooling water to prevent rust build-up and Nalco 2590 is added to the cooling water for alga control. Sodium Hypochlorite is used as a fungicide and biocide.

#### **Building 668**

Building 668 is the Drum Certification Building. Building 668 was originally used to seal fiberglass-coated wood waste crates after being filled with low level waste. The crates were sealed using fiberglass matting and sprayed on fiberglass resin. This operation was moved to Building 664 in the 1980's and the building was then used to inspect, number, label, and certify new waste crates and waste drums prior to being sent to the production buildings to be filled with waste. Although the waste crates sealing operations that occurred in the early days of operation did contain radioactive waste, the waste containers where never opened, they were only permanently sealed prior to shipment. There is no evidence of any radiological contamination related to this event. Polyester resins and cleaning solvents where used in the fiberglass operations.

#### Trailer T664A

Trailer T664 is a general office trailer, which has historically, be used to house management and administrative personnel in support of waste storage and shipping operation conducted in Buildings 440 and 664.

#### **Current Operational Status**

Buildings 460, 439, 462 and Trailer T664A are all operational. Building 668 is not operational, but has some old equipment and supplies related to past operation, which need to be cleaned out.

#### **Contaminants of Concern**

#### Asbestos

Describe any potential, likely, or known sources of Asbestos:

Building 668 is posted as containing asbestos, T664A is posted as possibly containing asbestos.

The Industrial Hygiene Group (IH) has collected some asbestos data on Building 460. Contact IH for a copy of this information.

#### Beryllium (Be)

Describe any potential, likely, or known Be production or storage locations:

The only facility on the List of Historic and Present Be Areas is the High Bay area of Building 460. The High Bay area is list based on historical information that beryllium copper plates where occasionally polished in the high bay area. The UBC section of the HRR states that Be may have occasionally been handled in Building 439. No evidence of this was found.

Summarize any recent Be sampling results:

There have been no recent Be samples collected on any of these facilities.

#### Lead

Describe any potential, likely, or known sources of Lead (e.g., paint, shielding, etc.):

Based on the age of some of the facilities addressed in this HSA, lead in paint may be a concern. No processes containing lead were conducted in these facilities.

#### RCRA/CERCLA Constituents

Describe any potential, likely, or known sources of RCRA/CERCLA constituents (e.g., chemical storage, waste storage, and processes):

Building 460 was a major non-nuclear manufacturing facility and used chemicals such as acids, bases and solvents. Metals contamination of these chemicals did occur as part of the machining and fabrication operations (i.e. chromium). Building 460 had several permitted RCRA units associated with these activities. These RCRA units have been closed. Building 460 is currently a permitted LLW and mixed waste Storage facility. Historically, Building 439 was used as a machine shop to support Building 440 operations and other maintenance operations in the 400 area. No significant amounts of RCRA or CERCLA Constituents were handled in this facility. See the Historical operations section above for a more detailed listing of the operations which occurred in the facilities addressed in this HSA.

Building 460 had the following permitted storage areas. All RCRA units have been closed in accordance with the "RCRA Closure Plan for the B460 Process Waste System"

- 39.03 Fabric Filtration Unit
- 40.08 Process Waste Tank T-1
- 40.09 Process Waste Tank T-2
- 40.10 Filter System Collection Tank T-4
- 40.11 Sump Tank ST-1
- 40.12 Sump Tank ST-2
- 40.13 Sump Tank ST-3
- 40.14 Sump Tank ST-4
- 40.15 Sump Tank ST-5

Building 460 has the following current permit - MS001- B460 Containerized Storage. This permit is a temporary permit. The final permit is expected to be approved later this year.

Describe any potential, likely, or known spill locations (and sources, if any):

See the Environmental Concerns section below for information about RCRA/CERCLA spills.

Describe methods in which spills were mitigated, if any:

See the Environmental Concerns section below for information about RCRA/CERCLA spills.

#### **PCBs**

Describe any potential, likely, or known sources of PCBs (e.g., light ballasts, paints, equipment, etc.):

No PCB containing process where housed in any of the facilities addressed in this HSA. Based on the age of construction of some of these facilities, PCBs in paint may be a concern.

Describe any potential, likely, or known spill locations (and sources, if any):

No PCB spills occurred in any of the facilities addressed in this HSA.

Describe methods in which spills were mitigated, if any:

No PCB spills occurred in any of the facilities addressed in this HSA.

#### Radiological Contaminants

Describe any potential, likely, or known radiological production or storage locations:

Building 460 recently became a LLW storage facility. In the past Building 668 housed fiberglass operations used to seal LLW waste crates. Historically, Building 439 was primarily a machine shop in support of Building 440 operation. The UBC section of the HRR states that uranium, on limited occasions, may have been handled in Building 439. No evidence of this was found. See the Historical operations section above for a more detailed listing of the operations which occurred in the facilities addressed in this HSA.

Describe any potential, likely, or known spill locations (e.g., known leaking sealed radioactive sources, leaking waste drums, potentially contaminated drains, etc.):

None of the facilities in this HSA have had a radiological spill.

Describe methods in which spills were mitigated, f any:

None of the facilities in this HSA have had a radiological spill.

Describe any potential, likely, or known isotopes of concern (e.g., weapons grade plutonium, uranium isotopes, pure beta emitters, mixed fission products, etc.):

Isotopes of concern include uranium and plutonium.

Describe any potential, likely, or known external facility contamination (e.g., stack release points, unfiltered ventilation, facility's physical location to known site releases, etc.):

See section below for information on IHSSs PACs, and UBCs.

#### **Environmental Restoration Concerns**

Describe any ER concerns that could affect facility characterization (e.g., IHSSs, PACs, UBCs):

Building 460 is associated with or located near the following IHSSs, PACs, or UBCs. See individual IHSS, PAC, or UBC report for additional information.

- 1) 400-136.1, "Cooling Tower Pond East of Building 444", Active.
- 2) 400-157.2, "Radioactive site South Area", Active.
- 3) 400-205, "Building 460 Sump No. 3, Acid Side". Active.
- 4) 400-804, "Road North of Building 460", Active.
- 5) 400-812, "Tank T-2 Spill in Building 460, Proposed NFA in 2001.
- 6) 400-813, "RCRA Tank Leak in Building 460, Active.
- 7) 400-815, "RCRA Tank Leak in Building 460, Active.

Building 439 is associated with or located near the following IHSSs, PACs, or UBCs. See individual IHSS, PAC, or UBC report for additional information.

1) 400-157.2, "Radioactive site South Area", Active.

Building 439 is identified as a UBC because it housed modification and machining operations, which may have involved deleted uranium or beryllium.

Building 668 is associated with or located near the following IHSSs, PACs, or UBCs. See individual IHSS, PAC, or UBC report for additional information.

1) 600-120.1, "Fiberglass area north of Building 664", Active.

Building 462, and Trailer T664A are not associated any IHSS, PAC, or UBC

#### **Additional Information**

Describe any additional information that may be useful during facility characterization (e.g., contaminant migration routes, waste handling operations, physical hazards, Historical Release Reports, WSRIC data, etc.):

None

#### References

Provide all sources of information utilized to gather data for facility history (e.g., documents, files, interviews):

Sources reviewed to complete this HSA were the RFETS Facility List, the Historical Release Report, Site Master List of RCRA Units, and the Site IHSS, PAC, and UBC databases. The WSRIC for those buildings with a WSRIC. In addition, a facility walkdown and interviews were performed.

| Waste Volume Estimates and Material Types |                  |                 |                  |                                |                       |             |                        |  |  |  |
|---|------------------|-----------------|------------------|--------------------------------|-----------------------|-------------|------------------------|--|--|--|
| Facility                                  | Concrete (cu ft) | Wood<br>(cu ft) | Metal<br>(cu ft) | Corrugated Sheet Metal (cu ft) | Wall Board<br>(cu ft) | ACM (cu ft) | Other Waste<br>(cu ft) |  |  |  |
| Building 460                              | 42,400           | 0               | 73,000           | 24,000                         | 20,600                | TBD         | N/A                    |  |  |  |
| Building 439                              | 2500             | 0               | 1200             | 1600                           | 300                   | TBD         | N/A                    |  |  |  |
| Building 462                              | 250              | 0               | 1000             | 0                              | 0                     | TBD         | N/A                    |  |  |  |
| Building 668                              | 750              | 1000            | 100              | 0                              | 0                     | TBD         | N/A                    |  |  |  |
| Trailer T664A                             | 0                | 1,100           | 800              | 1000                           | 1,500                 | TBD         | N/A                    |  |  |  |

#### **Further Actions**

Recommend any further actions, if any (e.g., characterization, decontamination, special handling, etc.):

Begin the RLC/PDS process.

#### Note:

This HSA was performed prior to SME walkdowns, and chemical and radiological characterization package preparations. SMEs should evaluate and/or verify all information during the RLC/PDS process. SMEs may need to review additional documentation and perform additional interviews. Information contained in this HSA only represents a "snapshot" in time. Subsequent data may be obtained during SME walkdowns and chemical and radiological characterization package preparations, which may conflict with this report. However, this report will not be amended, and the newer data will take precedence over the data in this report. Newer Data will appear in the RLCR/PDSR.

| Prepared By: | Doug Bryant | /                                       | /s/       | / | October 2002 |  |
|--------------|-------------|---|-----------|---|--------------|--|
| -            | Name        | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | Signature |   | Date         |  |

# ATTACHMENT C

# Radiological Data Summaries and Survey Maps

Survey Area: 5

Survey Unit: 460002

Building: 460

Description: Building 460 Interior - North Offices, High Bay & Loading Dock Areas

## **Rocky Flats Environmental Technology Site Final Radiological Survey Summary Results**

#### **Total Surface Activity Measurements**

Nbr Random Measurements Required: 151

Nbr Biased Measurements Required: 45

Nbr QC Required: 8

Nbr Random Measurements Performed: 151

Nbr Biased Measurements Performed: 51

Nbr QC Performed: 9

#### Alpha

Maximum:

83.6 dpm/100cm<sup>2</sup>

Minimum:

-13.3 dpm/100cm<sup>2</sup>

Mean:

15.7 dpm/100cm<sup>2</sup>

Standard Deviation:

18.7

QC Maximum:

42.2 dpm/100cm<sup>2</sup>

QC Minimum:

16.9 dpm/100cm<sup>2</sup>

QC Mean:

33.2 dpm/100cm<sup>2</sup>

Transuranic DCGLw:

100.0 dpm/100cm<sup>2</sup>

Transuranic DCGLEMC:

300.0 dpm/100cm<sup>2</sup>

#### **Removable Surface Activity Measurements**

Nbr Random Measurements Required: 151

Nbr Biased Measurements Required: 45

Nbr Random Measurements Performed: 151

Nbr Biased Measurements Performed: 51

#### Alpha

Maximum:

6.4 dpm/100cm<sup>2</sup>

Minimum:

-1.8 dpm/100cm<sup>2</sup>

Mean:

0.3 dpm/100cm<sup>2</sup>

Standard Deviation:

1.4

Transuranic DCGLw:

20.0 dpm/100cm<sup>2</sup>

#### Media Sample Results

Nbr Random Required: 0

Nbr Biased Required: 0

Nbr Random Collected: 0

Nbr Biased Collected: 0

Conclusion - A comparison of the random, biased and QC measurement results against the PDSP Table 7-1 Surface Contamination Guideline limits was conducted: the comparison demonstrates that this survey unit passes the criterion specified in the PDSP.

Printed On: 04/07/05 06:56

Page: 1 of 19

Survey Unit: 460002 Building: 460

Description: Building 460 Interior - North Offices, High Bay & Loading Dock Areas

### **Instrument Data Sheet**

| Inst/RC | T RCT  | Analysis | Instr   | Instru | Probe | Calibration | Instru Ef | ficiency | A-Prio<br>(dpm/1 |      | Survey |
|---------|--------|----------|---------|--------|-------|-------------|-----------|----------|------------------|------|--------|
| Number  | r ID   | Date     | Model   | S/N    | Туре  | Due Dt      | Alpha     | Beta     | Alpha            | Beta | Туре   |
| 1       | 711447 | 03/02/05 | Electra | 657    | AP-6  | 06/13/05    | 0.184     | NA       | 48.0             | NA   | s      |
| 2       | 712467 | 03/02/05 | Electra | 673    | AP-6  | 07/24/05    | 0.173     | NA       | 48.0             | NA   | s      |
| 3       | 711447 | 03/03/05 | Electra | 657    | AP-6  | 06/13/05    | 0.184     | NA       | 48.0             | NA   | s      |
| 4       | 712467 | 03/03/05 | Electra | 2340   | DP-6  | 05/15/05    | 0.222     | NA       | 48.0             | NA   | Ŧ      |
| 5       | 712467 | 03/03/05 | SAC-4   | 767    | NA    | 08/03/05    | 0.330     | NA       | 10.0             | NA   | R      |
| 6       | 712467 | 03/03/05 | SAC-4   | 1130   | NA    | 07/03/05    | 0.330     | NA       | 10.0             | NA   | R      |
| 7       | 712467 | 03/15/05 | Electra | 3102   | DP-6  | 06/16/05    | 0.216     | NA       | 48.0             | NA   | T/S    |
| 8       | 511390 | 03/15/05 | Electra | 1366   | DP-6  | 04/05/05    | 0.212     | NA       | 48.0             | NA   | T/S    |
| 9       | 511390 | 03/16/05 | SAC-4   | 767    | NA    | 08/03/05    | 0.330     | NA       | 10.0             | NA   | R      |
| 10      | 511390 | 03/16/05 | SAC-4   | 1130   | NA    | 07/03/05    | 0.330     | NA       | 10.0             | NA   | R      |
| 11      | 711447 | 03/08/05 | Electra | 3102   | DP-6  | 06/16/05    | 0.216     | NA       | 48.0             | NA   | T/S    |
| 12      | 712193 | 03/08/05 | Electra | 1366   | DP-6  | 04/05/05    | 0.212     | NA       | 48.0             | NA   | T/S    |
| 13      | 511390 | 03/09/05 | Electra | 2340   | DP-6  | 05/15/05    | 0.222     | NA       | 48.0             | NA   | T/S    |
| 14      | 511390 | 03/09/05 | SAC-4   | 767    | NA    | 08/03/05    | 0.330     | NA       | 10.0             | NA   | R      |
| 15      | 511390 | 03/09/05 | SAC-4   | 1130   | NA    | 07/03/05    | 0.330     | NA       | 10.0             | NA   | Ř      |
| 16      | 511390 | 03/23/05 | Electra | 3109   | DP-6  | 06/13/05    | 0.215     | NA       | 48.0             | NA   | T/S    |
| 17      | 515538 | 03/23/05 | Electra | 3102   | DP-6  | 06/16/05    | 0.216     | NA       | 48.0             | NA   | T/S    |
| 18      | 701418 | 03/23/05 | Electra | 2352   | DP-6  | 06/09/05    | 0.221     | NA       | 48.0             | NA   | T/S    |
| 19      | 515538 | 03/23/05 | SAC-4   | 767    | NA    | 08/03/05    | 0.330     | NA       | 10.0             | NA   | R      |
| 20      | 511390 | 03/28/05 | Electra | 3370   | DP-6  | 07/27/05    | 0.213     | NA       | 48.0             | NA   | T/S    |
| 21      | 515538 | 03/28/05 | Electra | 2352   | DP-6  | 06/09/05    | 0.221     | NA       | 48.0             | NA   | T/S    |
| 22      | 511390 | 03/28/05 | SAC-4   | 767    | NA    | 08/03/05    | 0.330     | NA       | 10.0             | NA   | R      |
| 23      | 511390 | 03/28/05 | SAC-4   | 1130   | NA    | 07/03/05    | 0.330     | NA       | 10.0             | NA   | R      |
| 24      | 511390 | 03/29/05 | Electra | 657    | AP-6  | 06/13/05    | 0.184     | NA       | 48.0             | NA   | s      |
| 25      | 701418 | 03/29/05 | Electra | 673    | AP-6  | 07/24/05    | 0.173     | NA       | 48.0             | NA   | s      |
| 26      | 515538 | 03/29/05 | Electra | 3109   | DP-6  | 06/13/05    | 0.215     | NA       | 48.0             | NA   | т      |
| 27      | 511390 | 03/29/05 | Electra | 3254   | DP-6  | 07/04/05    | 0.225     | NA       | 48.0             | NA   | T/Q    |
| 28      | 701418 | 03/29/05 | SAC-4   | 767    | NA    | 08/03/05    | 0.330     | NA       | 10.0             | NA   | R      |
| 29      | 701418 | 03/29/05 | SAC-4   | 1130   | NA    | 07/03/05    | 0.330     | NA       | 10.0             | NA   | R      |

Survey Types:

T = Total Surface Activity, Q = TSA QC, S = Scan, R = Removable Surface Activity, I = Investigation

Printed On: 04/07/05 06:56 Page: 2 of 19

Survey Area: 5 Survey Unit: 460002 Building: 460 Description: Building 460 Interior - North Offices, High Bay & Loading Dock Areas kom Jagan **Comments Sheet** General 1. Locations 152-173 were taken inside the overhead supply ventilation ducts. Comments: 2. Locations 174-176 were taken inside the machine exhaust duct. 3. Locations 177-182 were taken inside the exhaust plenum in Room 226 and are not shown on the map. 4. Locations 185-189, 197 and 198 were taken on roof ventilation openings and are not shown on the map. 5. Locations 190-196, and 199-202 were taken on loading docks. TSA N/A Comments: RSA N/A Comments: Media N/A Comments:

Printed On: 04/07/05 06:56

Page: 3 of 19

Description: Building 460 Interior - North Offices, High Bay & Loading Dock Areas

## **Random Removable Surface Activity Data Sheet**

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) | ·   |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460002PRP-N001                 | 9                 | -0.3                      | N/A                      | N/A |
| 460002PRP-N002                 | 22                | -0.6                      | N/A                      | N/A |
| 460002PRP-N003                 | 19                | 0.3                       | N/A                      | N/A |
| 460002PRP-N004                 | 19                | -1.2                      | N/A                      | N/A |
| 460002PRP-N005                 | 10                | 1.2                       | N/A                      | N/A |
| 460002PRP-N006                 | 28                | 0.6                       | N/A                      | N/A |
| 460002PRP-N007                 | 5                 | -0.3                      | N/A                      | N/A |
| 460002PRP-N008                 | 19                | -1.2                      | N/A                      | N/A |
| 460002PRP-N009                 | 22                | -0.6                      | N/A                      | N/A |
| 460002PRP-N010                 | 22                | -0.6                      | N/A                      | N/A |
| 460002PRP-N011                 | 9                 | 1.2                       | N/A                      | N/A |
| 460002PRP-N012                 | 19                | -1.2                      | N/A                      | N/A |
| 460002PRP-N013                 | 23                | -1.2                      | N/A                      | N/A |
| 460002PRP-N014                 | 6                 | 2.1                       | N/A                      | N/A |
| 460002PRP-N015                 | 19                | -1.2                      | N/A                      | N/A |
| 460002PRP-N016                 | 28                | -0.9                      | N/A                      | N/A |
| 460002PRP-N017                 | 6                 | 0.6                       | N/A                      | N/A |
| 460002PRP-N018                 | 19                | 1.8                       | N/A                      | N/A |
| 460002PRP-N019                 | 19                | 0.3                       | N/A                      | N/A |
| 460002PRP-N020                 | 5                 | 1.2                       | N/A                      | N/A |
| 460002PRP-N021                 | 6                 | -0.9                      | N/A                      | N/A |
| 460002PRP-N022                 | 28                | -0.9                      | N/A                      | N/A |
| 460002PRP-N023                 | 5                 | -0.3                      | N/A                      | N/A |
| 460002PRP-N024                 | 6                 | -0.9                      | N/A                      | N/A |
| 460002PRP-N025                 | 22                | -0.6                      | N/A                      | N/A |
| 460002PRP-N026                 | 10                | -0.3                      | N/A                      | N/A |
| 460002PRP-N027                 | 19                | -1.2                      | N/A                      | N/A |
| 460002PRP-N028                 | 9                 | 1.2                       | N/A                      | N/A |
| 460002PRP-N029                 | 10                | 1.2                       | N/A                      | N/A |

Printed On: 04/07/05 06:56

Page: 4 of 19

| Survey Unit: 460002   | Building: 460 |
|---|---------------|
| Description: Building 460 Interior - North Offices, High Bay & Loading Dock Areas |               |

## **Random Removable Surface Activity Data Sheet**

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460002PRP-N030                 | 23                | -1.2                      | N/A                      | N/A |
| 460002PRP-N031                 | 19                | 3.3                       | N/A                      | N/A |
| 460002PRP-N032                 | 9                 | 4.2                       | N/A                      | N/A |
| 460002PRP-N033                 | 19                | 1.8                       | N/A                      | N/A |
| 460002PRP-N034                 | 6                 | 2.1                       | N/A                      | N/A |
| 460002PRP-N035                 | 19                | 1.8                       | N/A                      | N/A |
| 460002PRP-N036                 | 22                | -0.6                      | N/A                      | N/A |
| 460002PRP-N037                 | 19                | -1.2                      | N/A                      | N/A |
| 460002PRP-N038                 | 5                 | -0.3                      | N/A                      | N/A |
| 460002PRP-N039                 | 10                | -0.3                      | N/A                      | N/A |
| 460002PRP-N040                 | 6                 | 0.6                       | N/A                      | N/A |
| 460002PRP-N041                 | 5                 | -0.3                      | N/A                      | N/A |
| 460002PRP-N042                 | 5                 | 1.2                       | N/A                      | N/A |
| 460002PRP-N043                 | 28                | 0.6                       | N/A                      | N/A |
| 460002PRP-N044                 | 5                 | 1.2                       | N/A                      | N/A |
| 460002PRP-N045                 | 6                 | -0.9                      | N/A                      | N/A |
| 460002PRP-N046                 | 9                 | 2.7                       | N/A                      | N/A |
| 460002PRP-N047                 | 6                 | 0.6                       | N/A                      | N/A |
| 460002PRP-N048                 | 28                | -0.9                      | N/A                      | N/A |
| 460002PRP-N049                 | 5                 | -0.3                      | N/A                      | N/A |
| 460002PRP-N050                 | 5                 | -0.3                      | N/A                      | N/A |
| 460002PRP-N051                 | 10                | -0.3                      | N/A                      | N/A |
| 460002PRP-N052                 | 5                 | 2.7                       | N/A                      | N/A |
| 460002PRP-N053                 | 6                 | 0.6                       | N/A                      | N/A |
| 460002PRP-N054                 | 19                | 0.3                       | N/A                      | N/A |
| 460002PRP-N055                 | 9                 | -0.3                      | N/A                      | N/A |
| 460002PRP-N056                 | 10                | -0.3                      | N/A                      | N/A |
| 460002PRP-N057                 | 19                | -1.2                      | N/A                      | N/A |
| 460002PRP-N058                 | 9                 | 4.2                       | N/A                      | N/A |

Printed On: 04/07/05 06:56

Page: 5 of 19

Description: Building 460 Interior - North Offices, High Bay & Loading Dock Areas

## **Random Removable Surface Activity Data Sheet**

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460002PRP-N059                 | 19                | 1.8                       | N/A                      | N/A |
| 460002PRP-N060                 | 5                 | -0.3                      | N/A                      | N/A |
| 460002PRP-N061                 | 6                 | -0.9                      | N/A                      | N/A |
| 460002PRP-N062                 | 28                | -0.9                      | N/A                      | N/A |
| 460002PRP-N063                 | 22                | -0.6                      | N/A                      | N/A |
| 460002PRP-N064                 | 19                | 0.3                       | N/A                      | N/A |
| 460002PRP-N065                 | 29                | 0.3                       | N/A                      | N/A |
| 460002PRP-N066                 | 6                 | -0.9                      | N/A                      | N/A |
| 460002PRP-N067                 | 5                 | -0.3                      | N/A                      | N/A |
| 460002PRP-N068                 | 6                 | -0.9                      | N/A                      | N/A |
| 460002PRP-N069                 | 5                 | 1.2                       | N/A                      | N/A |
| 460002PRP-N070                 | 22                | -0.6                      | N/A                      | N/A |
| 460002PRP-N071                 | 6                 | 2.1                       | N/A                      | N/A |
| 460002PRP-N072                 | 10                | -0.3                      | N/A                      | N/A |
| 460002PRP-N073                 | 6                 | -0.9                      | N/A                      | N/A |
| 460002PRP-N074                 | 22                | -0.6                      | N/A                      | N/A |
| 460002PRP-N075                 | 9                 | 1.2                       | N/A                      | N/A |
| 460002PRP-N076                 | 23                | -1.2                      | N/A                      | N/A |
| 460002PRP-N077                 | 5                 | 1.2                       | N/A                      | N/A |
| 460002PRP-N078                 | 10                | -1.8                      | N/A                      | N/A |
| 460002PRP-N079                 | 22                | -0.6                      | N/A                      | N/A |
| 460002PRP-N080                 | 19                | -1.2                      | N/A                      | N/A |
| 460002PRP-N081                 | 22                | -0.6                      | N/A                      | N/A |
| 460002PRP-N082                 | 22                | -0.6                      | N/A                      | N/A |
| 460002PRP-N083                 | 23                | 1.8                       | N/A                      | N/A |
| 460002PRP-N084                 | 9                 | 1.2                       | N/A                      | N/A |
| 460002PRP-N085                 | 6                 | -0.9                      | N/A                      | N/A |
| 460002PRP-N086                 | 22                | -0.6                      | N/A                      | N/A |
| . 460002PRP-N087               | 19                | -1.2                      | N/A                      | N/A |

Printed On: 04/07/05 06:56

Page: 6 of 19

Description: Building 460 Interior - North Offices, High Bay & Loading Dock Areas

## **Random Removable Surface Activity Data Sheet**

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460002PRP-N088                 | 5                 | -0.3                      | N/A                      | N/A |
| 460002PRP-N089                 | 29                | 6.4                       | N/A                      | N/A |
| 460002PRP-N090                 | 6                 | -0.9                      | N/A                      | N/A |
| 460002PRP-N091                 | 23                | -1.2                      | N/A                      | N/A |
| 460002PRP-N092                 | 19                | 0.3                       | N/A                      | N/A |
| 460002PRP-N093                 | 10                | -1.8                      | N/A                      | N/A |
| 460002PRP-N094                 | 23                | -1.2                      | N/A                      | N/A |
| 460002PRP-N095                 | 23                | -1.2                      | N/A                      | N/A |
| 460002PRP-N096                 | 22                | -0.6                      | N/A                      | N/A |
| 460002PRP-N097                 | 19                | -1.2                      | N/A                      | N/A |
| 460002PRP-N098                 | 19                | 0.3                       | N/A                      | N/A |
| 460002PRP-N099                 | 9                 | 1.2                       | N/A                      | N/A |
| 460002PRP-N100                 | 10                | -1.8                      | N/A                      | N/A |
| 460002PRP-N101                 | 19                | 1.8                       | N/A                      | N/A |
| 460002PRP-N102                 | 9                 | 2.7                       | N/A                      | N/A |
| 460002PRP-N103                 | 19                | 1.8                       | N/A                      | N/A |
| 460002PRP-N104                 | 19                | -1.2                      | N/A                      | N/A |
| 460002PRP-N105                 | 5                 | -0.3                      | N/A                      | N/A |
| 460002PRP-N106                 | 10                | -0.3                      | N/A                      | N/A |
| 460002PRP-N107                 | 19                | -1.2                      | N/A                      | N/A |
| 460002PRP-N108                 | 6                 | -0.9                      | N/A                      | N/A |
| 460002PRP-N109                 | 19                | -1.2                      | . N/A                    | N/A |
| 460002PRP-N110                 | 6                 | 0.6                       | N/A                      | N/A |
| 460002PRP-N111                 | 5                 | -0.3                      | N/A                      | N/A |
| 460002PRP-N112                 | 6                 | -0.9                      | N/A                      | N/A |
| 460002PRP-N113                 | 19                | -1.2                      | N/A                      | N/A |
| 460002PRP-N114                 | 29                | 0.3                       | N/A                      | N/A |
| 460002PRP-N115                 | 5                 | 2.7                       | N/A                      | N/A |
| 460002PRP-N116                 | 5                 | -0.3                      | N/A                      | N/A |

Printed On: 04/07/05 06:56

Page: 7 of 19

Description: Building 460 Interior - North Offices, High Bay & Loading Dock Areas

## **Random Removable Surface Activity Data Sheet**

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460002PRP-N117                 | 23                | 1.8                       | N/A                      | N/A |
| 460002PRP-N118                 | 22                | -0.6                      | N/A                      | N/A |
| 460002PRP-N119                 | 6                 | -0.9                      | N/A                      | N/A |
| 460002PRP-N120                 | 5                 | -0.3                      | N/A                      | N/A |
| 460002PRP-N121                 | 9                 | -0.3                      | N/A                      | N/A |
| 460002PRP-N122                 | 29                | -1.2                      | N/A                      | N/A |
| 460002PRP-N123                 | 19                | -1.2                      | N/A                      | N/A |
| 460002PRP-N124                 | · 10              | -0.3                      | N/A                      | N/A |
| 460002PRP-N125                 | 23                | 1.8                       | N/A                      | N/A |
| 460002PRP-N126                 | 9                 | -0.3                      | N/A                      | N/A |
| 460002PRP-N127                 | 6                 | 0.6                       | N/A                      | N/A |
| 460002PRP-N128                 | 5                 | -0.3                      | N/A                      | N/A |
| 460002PRP-N129                 | 10                | -0.3                      | N/A                      | N/A |
| 460002PRP-N130                 | 29                | -1.2                      | N/A                      | N/A |
| 460002PRP-N131                 | 23                | -1.2                      | N/A                      | N/A |
| 460002PRP-N132                 | 23                | -1.2                      | N/A                      | N/A |
| 460002PRP-N133                 | 9                 | 2.7                       | N/A                      | N/A |
| 460002PRP-N134                 | 19                | -1.2                      | N/A                      | N/A |
| 460002PRP-N135                 | 19                | 3.3                       | N/A                      | N/A |
| 460002PRP-N136                 | 23                | -1.2                      | N/A                      | N/A |
| 460002PRP-N137                 | 29                | -1.2                      | N/A                      | N/A |
| 460002PRP-N138                 | 10                | 1.2                       | N/A                      | N/A |
| 460002PRP-N139                 | 19                | 1.8                       | N/A                      | N/A |
| 460002PRP-N140                 | 6                 | 0.6                       | N/A                      | N/A |
| 460002PRP-N141                 | 19                | 3.3                       | N/A                      | N/A |
| 460002PRP-N142                 | 5                 | -0.3                      | N/A                      | N/A |
| 460002PRP-N143                 | 23                | -1.2                      | N/A                      | N/A |
| 460002PRP-N144                 | 9                 | 1.2                       | N/A                      | N/A |
| 460002PRP-N145                 | 23                | -1.2                      | N/A                      | N/A |

Printed On: 04/07/05 06:56

Page: 8 of 19

|                                  |                      |                                 | 5 - 12 - 12 - 12 - 12 - 12 - 12 - 12 - 1 |            | The second secon |
|----------------------------------|----------------------|---------------------------------|--|------------|--|
| Survey Area: 5                   | S                    | Survey Unit: 460002             | Bui                                      | lding: 460 |  |
| Description: Building 460 Interi | ior - North Offices. | . High Bay & Loading Dock Areas |  |            |  |

# **Random Removable Surface Activity Data Sheet**

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460002PRP-N146                 | 6                 | -0.9                      | N/A                      | N/A |
| 460002PRP-N147                 | 5                 | -0.3                      | N/A                      | N/A |
| 460002PRP-N148                 | 19                | -1.2                      | N/A                      | N/A |
| 460002PRP-N149                 | 6                 | 0.6                       | N/A                      | N/A |
| 460002PRP-N150                 | 5                 | 1.2                       | N/A                      | N/A |
| 460002PRP-N151                 | 23                | -1.2                      | N/A                      | N/A |

Printed On: 04/07/05 06:56

Page: 9 of 19

Description: Building 460 Interior - North Offices, High Bay & Loading Dock Areas

# **Biased Removable Surface Activity Data Sheet**

| Biased Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm <sup>2</sup> ) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|--|--------------------------|-----|
| 460002PBP-N152                 | 14                | 1.5                                    | N/A                      | N/A |
| 460002PBP-N153                 | 15                | 0.3                                    | N/A                      | N/A |
| 460002PBP-N154                 | 14                | 1.5                                    | N/A                      | N/A |
| 460002PBP-N155                 | 15                | -1.2                                   | N/A                      | N/A |
| 460002PBP-N156                 | 14                | 0.0                                    | N/A                      | N/A |
| 460002PBP-N157                 | 15                | 0.3                                    | N/A                      | N/A |
| 460002PBP-N158                 | 14                | 1.5                                    | N/A                      | N/A |
| 460002PBP-N159                 | 15                | -1.2                                   | N/A                      | N/A |
| 460002PBP-N160                 | 14                | 3.0                                    | N/A                      | N/A |
| 460002PBP-N161                 | 15                | 0.3                                    | N/A                      | N/A |
| 460002PBP-N162                 | 14                | 3.0                                    | N/A                      | N/A |
| 460002PBP-N163                 | 15                | 0.3                                    | N/A                      | N/A |
| 460002PBP-N164                 | 14                | 3.0                                    | N/A                      | N/A |
| 460002PBP-N165                 | 15                | 0.3                                    | N/A                      | N/A |
| 460002PBP-N166                 | 14                | 1.5                                    | N/A                      | N/A |
| 460002PBP-N167                 | 15                | -1.2                                   | N/A                      | N/A |
| 460002PBP-N168                 | 14                | 1.5                                    | N/A                      | N/A |
| 460002PBP-N169                 | 15                | 0.3                                    | N/A                      | N/A |
| 460002PBP-N170                 | 14                | 0.0                                    | N/A                      | N/A |
| 460002PBP-N171                 | 15                | -1.2                                   | N/A                      | N/A |
| 460002PBP-N172                 | 14                | 0.0                                    | N/A                      | N/A |
| 460002PBP-N173                 | 15                | -1.2                                   | N/A                      | N/A |
| 460002PBP-N174                 | 14                | 1.5                                    | N/A                      | N/A |
| 460002PBP-N175                 | 15                | 0.3                                    | N/A                      | N/A |
| 460002PBP-N176                 | 14                | 1.5                                    | N/A                      | N/A |
| 460002PBP-N177                 | 15                | 1.8                                    | N/A                      | N/A |
| 460002PBP-N178                 | 14                | 3.0                                    | N/A                      | N/A |

Printed On: 04/07/05 06:56

Page: 10 of 19

Description: Building 460 Interior - North Offices, High Bay & Loading Dock Areas

## **Biased Removable Surface Activity Data Sheet**

| Biased Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460002PBP-N179                 | 15                | 0.3                       | N/A                      | N/A |
| 460002PBP-N180                 | 14                | 3.0                       | N/A                      | N/A |
| 460002PBP-N181                 | 15                | 1.8                       | N/A                      | N/A |
| 460002PBP-N182                 | 14                | 3.0                       | N/A                      | N/A |
| 460002PBP-N183                 | 19                | -1.2                      | N/A                      | N/A |
| 460002PBP-N184                 | 19                | -1.2                      | N/A                      | N/A |
| 460002PBP-N185                 | 28                | -0.9                      | N/A                      | N/A |
| 460002PBP-N186                 | 29                | 1.8                       | N/A                      | N/A |
| 460002PBP-N187                 | 29                | 1.8                       | N/A                      | N/A |
| 460002PBP-N188                 | 29                | 1.8                       | N/A                      | N/A |
| 460002PBP-N189                 | 28                | 0.6                       | N/A                      | N/A |
| 460002PBP-N190                 | 29                | 1.8                       | N/A                      | N/A |
| 460002PBP-N191                 | 28                | -0.9                      | N/A                      | N/A |
| 460002PBP-N192                 | 28                | 0.6                       | N/A                      | N/A |
| 460002PBP-N193                 | 28                | 0.6                       | N/A                      | N/A |
| 460002PBP-N194                 | 29                | 1.8                       | N/A                      | N/A |
| 460002PBP-N195                 | 28                | 0.6                       | N/A                      | N/A |
| 460002PBP-N196                 | 29                | 0.3                       | N/A                      | N/A |
| 460002PBP-N197                 | 28                | -0.9                      | N/A                      | N/A |
| 460002PBP-N198                 | 29                | -1.2                      | N/A                      | N/A |
| 460002PBP-N199                 | 29                | 1.8                       | N/A                      | N/A |
| 460002PBP-N200                 | 28                | -0.9                      | N/A                      | N/A |
| 460002PBP-N201                 | 29                | 1.8                       | N/A                      | N/A |
| 460002PBP-N202                 | 28                | 5.2                       | N/A                      | N/A |

Printed On: 04/07/05 06:56

Page: 11 of 19

| o ocialisti dalli il e | 1.00 | Circulate Halles 40 | 0000 | Buildi | 400     |
|------------------------|------|---------------------|------|--------|---------|
| Survey Area: 5         |      | Survey Unit: 46     | 0002 | Dullui | ng: 460 |

Description: Building 460 Interior - North Offices, High Bay & Loading Dock Areas

# Random/QC Total Surface Activity Data Sheet

| Random Measurement<br>Location |    |      | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|----|------|--------------------------|-----|
| 460002PRP-N001                 | 7  | -3.4 | N/A                      | N/A |
| 460002PRP-N002                 | 20 | 37.6 | N/A                      | N/A |
| 460002PRP-N003                 | 18 | 14.3 | N/A                      | N/A |
| 460002PRP-N004                 | 18 | 26.5 | N/A                      | N/A |
| 460002PRP-N005                 | 7  | 3.1  | N/A                      | N/A |
| 460002PRP-N006                 | 4  | 21.8 | N/A                      | N/A |
| 460002PRP-N007                 | 4  | 35.4 | N/A                      | N/A |
| 460002PRP-N008                 | 18 | 17.5 | N/A                      | N/A |
| 460002PRP-N009                 | 20 | -9.3 | N/A                      | N/A |
| 460002PRP-N010                 | 20 | 22.1 | N/A                      | N/A |
| 460002PRP-N011                 | 7  | 9.1  | N/A                      | N/A |
| 460002PRP-N012                 | 16 | 37.1 | N/A                      | N/A |
| 460002PRP-N013                 | 20 | 12.8 | N/A                      | N/A |
| 460002PRP-N014                 | 4  | 11.5 | N/A                      | N/A |
| 460002PRP-N015                 | 16 | 15.3 | N/A                      | N/A |
| 460002PRP-N016                 | 27 | 2.2  | N/A                      | N/A |
| 460002PRP-N017                 | 4  | 47.5 | N/A                      | N/A |
| 460002QRP-N017                 | 27 | 30.2 | N/A                      | N/A |
| 460002PRP-N018                 | 18 | 35.6 | N/A                      | N/A |
| 460002PRP-N019                 | 18 | 20.7 | N/A                      | N/A |
| 460002PRP-N020                 | 4  | -9.7 | N/A                      | N/A |
| 460002PRP-N021                 | 4  | 38.5 | N/A                      | N/A |
| 460002QRP-N021                 | 27 | 27.1 | N/A                      | N/A |
| 460002PRP-N022                 | 18 | 35.6 | N/A                      | N/A |
| 460002QRP-N022                 | 27 | 30.2 | N/A                      | N/A |
| 460002PRP-N023                 | 4  | 8.3  | N/A                      | N/A |
| 460002PRP-N024                 | 4  | -3.8 | N/A                      | N/A |

Printed On: 04/07/05 06:56

Page: 12 of 19

Description: Building 460 Interior - North Offices, High Bay & Loading Dock Areas

## Random/QC Total Surface Activity Data Sheet

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460002PRP-N025 20              |                   | 47.0                      | N/A                      | N/A |
| 460002PRP-N026                 | 7                 | -6.2                      | N/A                      | N/A |
| 460002PRP-N027                 | 18                | 23.4                      | N/A                      | N/A |
| 460002PRP-N028                 | 8                 | 15.7                      | N/A                      | N/A |
| 460002PRP-N029                 | 8                 | 0.2                       | N/A                      | N/A |
| 460002PRP-N030                 | 21                | 16.1                      | N/A                      | N/A |
| 460002PRP-N031                 | 16                | 37.1                      | N/A                      | N/A |
| 460002PRP-N032                 | 7                 | 12.3                      | N/A                      | N/A |
| 460002PRP-N033                 | 18                | 35.6                      | N/A                      | N/A |
| 460002PRP-N034                 | 4                 | 5.2                       | N/A                      | N/A |
| 460002PRP-N035                 | 18                | 38.8                      | N/A                      | N/A |
| 460002PRP-N036                 | 20                | 6.2                       | N/A                      | N/A |
| 460002PRP-N037                 | 18                | 26.5                      | N/A                      | N/A |
| 460002PRP-N038                 | 4                 | -0.7                      | N/A                      | N/A |
| 460002PRP-N039                 | 8                 | -6.0                      | N/A                      | N/A |
| 460002PRP-N040                 | 4                 | 8.3                       | N/A                      | N/A |
| 460002PRP-N041                 | 4                 | 14.2                      | N/A                      | N/A |
| 460002PRP-N042                 | 4                 | 53.4                      | N/A                      | N/A |
| 460002PRP-N043                 | 26                | 83.6                      | N/A                      | N/A |
| 460002PRP-N044                 | 4                 | -0.7                      | N/A                      | N/A |
| 460002PRP-N045                 | 4                 | 2.5                       | N/A                      | N/A |
| 460002PRP-N046                 | 8                 | 9.6                       | N/A                      | N/A |
| 460002PRP-N047                 | 4                 | -0.7                      | N/A                      | N/A |
| 460002PRP-N048                 | 26                | 52.5                      | N/A                      | N/A |
| 460002PRP-N049                 | 4                 | 11.5                      | N/A                      | N/A |
| 460002PRP-N050                 | 4                 | 32.2                      | N/A                      | N/A |
| 460002PRP-N051                 | 8                 | -3.1                      | N/A                      | N/A |

Printed On: 04/07/05 06:56

Page: 13 of 19

| Survey Area: 5 Survey Unit: 460002  | Building: 460 | . S |
|---|---------------|-----|
| Description: Building 460 Interior - North Offices, High Bay & Loading Dock Areas | •             |     |

# Random/QC Total Surface Activity Data Sheet

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |       |
|--------------------------------|-------------------|---------------------------|--------------------------|-------|
| 460002PRP-N052                 | 4                 | 14.2                      | N/A                      | . N/A |
| 460002PRP-N053                 | 4                 | 14.2                      | N/A                      | N/A   |
| 460002PRP-N054                 | 18                | 23.4                      | N/A                      | N/A   |
| 460002PRP-N055                 | 8                 | 3.5                       | N/A                      | N/A   |
| 460002PRP-N056                 | 7                 | -3.4                      | N/A                      | N/A   |
| 460002PRP-N057                 | 18                | -0.6                      | N/A                      | N/A   |
| 460002PRP-N058                 | 7                 | -0.2                      | N/A                      | N/A   |
| 460002PRP-N059                 | 18                | 35.6                      | N/A                      | N/A   |
| 460002PRP-N060                 | 4                 | 8.3                       | N/A                      | N/A   |
| 460002PRP-N061                 | 4                 | 5.2                       | N/A                      | N/A   |
| 460002PRP-N062                 | 21                | 26.5                      | N/A                      | N/A   |
| 460002PRP-N063                 | 21                | -0.6                      | N/A                      | N/A   |
| 460002PRP-N064                 | 16                | 23.2                      | N/A                      | N/A   |
| 460002PRP-N065                 | 16                | 37.1                      | N/A                      | N/A   |
| 460002PRP-N066                 | 4                 | 11.5                      | N/A                      | N/A   |
| 460002PRP-N067                 | 4                 | -0.7                      | N/A                      | N/A   |
| 460002PRP-N068                 | 4                 | 5.2                       | N/A                      | N/A   |
| 460002PRP-N069                 | 4                 | 2.5                       | N/A                      | N/A   |
| 460002PRP-N070                 | 4                 | 30.8                      | N/A                      | N/A   |
| 460002PRP-N071                 | 20                | 15.6                      | N/A                      | N/A   |
| 460002PRP-N072                 | 8                 | 22.3                      | N/A                      | N/A   |
| 460002PRP-N073                 | 4                 | 74.5                      | N/A                      | N/A   |
| 460002PRP-N074                 | 21                | 14.3                      | N/A                      | N/A   |
| 460002QRP-N074                 | 27                | 42.2                      | N/A                      | N/A   |
| 460002PRP-N075                 | 8                 | 15.7                      | N/A                      | N/A   |
| 460002PRP-N076                 | 21                | 11.6                      | N/A                      | N/A   |
| 460002PRP-N077                 | 4                 | -0.7                      | N/A                      | N/A   |

Printed On: 04/07/05 06:56 Page: 14 of 19 Survey Unit: 460002 Building: 460

Description: Building 460 Interior - North Offices, High Bay & Loading Dock Areas.

## Random/QC Total Surface Activity Data Sheet

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460002PRP-N078                 | 8                 | 9.6                       | N/A                      | N/A |
| 460002PRP-N079                 | 20                | 25.0                      | N/A                      | N/A |
| 460002PRP-N080                 | 16                | 33.9                      | N/A                      | N/A |
| 460002PRP-N081                 | 21                | 11.6                      | N/A                      | N/A |
| 460002PRP-N082                 | 20                | 0.1                       | N/A                      | N/A |
| 460002PRP-N083                 | 21                | 2.6                       | N/A                      | N/A |
| 460002PRP-N084                 | 8                 | 12.9                      | N/A                      | N/A |
| 460002PRP-N085                 | 4                 | 14.2                      | N/A                      | N/A |
| 460002PRP-N086                 | 20                | 42.3                      | N/A                      | N/A |
| 460002PRP-N087                 | 17                | 47.5                      | N/A                      | N/A |
| 460002QRP-N087                 | 27                | 33.4                      | N/A                      | N/A |
| 460002PRP-N088                 | 4                 | 32.2                      | N/A                      | N/A |
| 460002PRP-N089                 | 26                | 40.4                      | N/A                      | N/A |
| 460002PRP-N090                 | 4                 | 8.3                       | N/A                      | N/A |
| 460002PRP-N091                 | 21                | 8.4                       | N/A                      | N/A |
| 460002PRP-N092                 | 18                | 5.3                       | N/A                      | N/A |
| 460002PRP-N093                 | 8                 | 12.9                      | N/A                      | N/A |
| 460002PRP-N094                 | 20                | 12.8                      | N/A                      | N/A |
| 460002PRP-N095                 | 20                | 6.2                       | N/A                      | N/A |
| 460002PRP-N096                 | 20                | 34.4                      | N/A                      | N/A |
| 460002PRP-N097                 | 17                | -0.2                      | N/A                      | N/A |
| 460002PRP-N098                 | 16                | 18.5                      | N/A                      | N/A |
| 460002PRP-N099                 | 7                 | -0.2                      | N/A                      | N/A |
| 460002PRP-N100                 | 7                 | 5.8                       | N/A                      | N/A |
| 460002PRP-N101                 | 18                | 44.6                      | N/A                      | N/A |
| 460002PRP-N102                 | 8                 | 6.3                       | N/A                      | N/A |
| 460002PRP-N103                 | 18                | 65.9                      | N/A                      | N/A |

Printed On: 04/07/05 06:56

Page: 15 of 19

Description: Building 460 Interior - North Offices, High Bay & Loading Dock Areas

## Random/QC Total Surface Activity Data Sheet

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460002PRP-N104                 | 18                | -3.8                      | N/A                      | N/A |
| 460002PRP-N105 4               |                   | 5.2                       | N/A                      | N/A |
| 460002PRP-N106                 | 8                 | 3.5                       | N/A                      | N/A |
| 460002PRP-N107                 | 18                | 11.6                      | N/A                      | N/A |
| 460002PRP-N108                 | 4                 | 38.5                      | N/A                      | N/A |
| 460002QRP-N108                 | 27                | 36.0                      | N/A                      | N/A |
| 460002PRP-N109                 | 16                | 6.0                       | N/A                      | N/A |
| 460002PRP-N110                 | 4                 | 32.2                      | N/A                      | N/A |
| 460002QRP-N110                 | 27                | 16.9                      | N/A                      | N/A |
| 460002PRP-N111                 | 4                 | -3.8                      | N/A                      | N/A |
| 460002PRP-N112                 | 4                 | 29.5                      | N/A                      | N/A |
| 460002PRP-N113                 | 18                | 22.0                      | N/A                      | N/A |
| 460002PRP-N114                 | 27                | 16.9                      | N/A                      | N/A |
| 460002PRP-N115                 | 4                 | 11.5                      | N/A                      | N/A |
| 460002PRP-N116                 | 4                 | 20.5                      | N/A                      | N/A |
| 460002PRP-N117                 | 20                | 3.4                       | N/A                      | N/A |
| 460002PRP-N118                 | 20                | 4.8                       | N/A                      | N/A |
| 460002PRP-N119                 | 4                 | 11.5                      | N/A                      | N/A |
| 460002PRP-N120                 | 4                 | 53.4                      | N/A                      | N/A |
| 460002PRP-N121                 | 8                 | 15.7                      | N/A                      | N/A |
| 460002PRP-N122                 | 27                | 11.1                      | N/A                      | N/A |
| 460002PRP-N123                 | 18                | 25.2                      | N/A                      | N/A |
| 460002PRP-N124                 | 7                 | 3.1                       | N/A                      | N/A |
| 460002PRP-N125                 | 20                | -4.6                      | N/A                      | N/A |
| 460002PRP-N126                 | 7                 | 12.3                      | N/A                      | N/A |
| 460002PRP-N127                 | 4                 | 56.5                      | N/A                      | N/A |
| 460002QRP-N127                 | 27                | 40.5                      | N/A                      | N/A |

Printed On: 04/07/05 06:56

Page: 16 of 19

Description: Building 460 Interior - North Offices, High Bay & Loading Dock Areas

### Random/QC Total Surface Activity Data Sheet

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460002PRP-N128                 | 4                 | 23.2                      | N/A                      | N/A |
| 460002PRP-N129                 | 8                 | 0.2                       | N/A                      | N/A |
| 460002PRP-N130                 | 27                | 46.6                      | N/A                      | N/A |
| 460002PRP-N131                 | 20                | 12.8                      | N/A                      | N/A |
| 460002PRP-N132                 | 21                | 35.6                      | N/A                      | N/A |
| 460002PRP-N133                 | 7                 | 5.8                       | N/A                      | N/A |
| 460002PRP-N134                 | 16                | 3.2                       | N/A                      | N/A |
| 460002PRP-N135                 | 18                | 17.5                      | N/A                      | N/A |
| 460002PRP-N136                 | 20                | 12.8                      | N/A                      | N/A |
| 460002PRP-N137                 | 27                | 58.2                      | N/A                      | N/A |
| 460002PRP-N138                 | 8                 | 12.9                      | N/A                      | N/A |
| 460002PRP-N139                 | 18                | 8.4                       | N/A                      | N/A |
| 460002PRP-N140                 | 4                 | -6.5                      | N/A                      | N/A |
| 460002PRP-N141                 | 18                | 44.6                      | N/A                      | N/A |
| 460002PRP-N142                 | 4                 | 14.2                      | N/A                      | N/A |
| 460002PRP-N143                 | 21                | -0.6                      | N/A                      | N/A |
| 460002PRP-N144                 | 7                 | 12.3                      | N/A                      | N/A |
| 460002PRP-N145                 | 21                | 17.5                      | N/A                      | N/A |
| 460002PRP-N146                 | 4                 | 23.2                      | N/A                      | N/A |
| 460002PRP-N147                 | 4                 | -6.5                      | N/A                      | N/A |
| 460002PRP-N148                 | 18                | 2.6                       | N/A                      | N/A |
| 460002PRP-N149                 | 4                 | 11.5                      | N/A                      | N/A |
| 460002PRP-N150                 | 4                 | 17.3                      | N/A                      | N/A |
| 460002PRP-N151                 | 21                | 35.6                      | N/A                      | N/A |
| 460002QRP-N151                 | 27                | 42.2                      | N/A                      | N/A |

Printed On: 04/07/05 06:56

Page: 17 of 19

| _ |                |          |                                   |  |
|---|----------------|----------|-----------------------------------|--|
|   | Survey Area: 5 |          | Survey Unit: 460002 Building: 460 |  |
|   |                | <u> </u> |                                   |  |

Description: Building 460 Interior - North Offices, High Bay & Loading Dock Areas

## **Biased Total Surface Activity Data Sheet**

| Biased Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |  |  |  |  |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|--|--|--|--|
| 460002PBP-N152                 | 11                | 0.8                       | N/A                      | N/A |  |  |  |  |
| 460002PBP-N153                 | 12                | 1.3                       | N/A                      | N/A |  |  |  |  |
| 460002PBP-N154                 | 11                | -13.1                     | N/A                      | N/A |  |  |  |  |
| 460002PBP-N155                 | 12                | 1.3                       | N/A                      | N/A |  |  |  |  |
| 460002PBP-N156                 | 11                | -1.9                      | N/A                      | N/A |  |  |  |  |
| 460002PBP-N157                 | 12                | 10.7                      | N/A                      | N/A |  |  |  |  |
| 460002PBP-N158                 | 11                | 22.6                      | N/A                      | N/A |  |  |  |  |
| 460002PBP-N159                 | 12                | -4.8                      | N/A                      | N/A |  |  |  |  |
| 460002PBP-N160                 | 11                | -1.9                      | N/A                      | N/A |  |  |  |  |
| 460002PBP-N161                 | 12                | 14.0                      | N/A                      | N/A |  |  |  |  |
| 460002PBP-N162                 | 11                | -1.9                      | N/A                      | N/A |  |  |  |  |
| 460002PBP-N163                 | 12                | -8.1                      | N/A                      | N/A |  |  |  |  |
| 460002PBP-N164                 | 11                | -1.9                      | N/A                      | N/A |  |  |  |  |
| 460002PBP-N165                 | 12                | -1.5                      | N/A                      | N/A |  |  |  |  |
| 460002PBP-N166                 | 11                | -1.9                      | N/A                      | N/A |  |  |  |  |
| 460002PBP-N167                 | 12                | -3.4                      | N/A                      | N/A |  |  |  |  |
| 460002PBP-N168                 | 11                | 7.3                       | N/A                      | N/A |  |  |  |  |
| 460002PBP-N169                 | 12                | -4.8                      | N/A                      | N/A |  |  |  |  |
| 460002PBP-N170                 | 13                | -13.3                     | N/A                      | N/A |  |  |  |  |
| 460002PBP-N171                 | 13                | 4.7                       | N/A                      | N/A |  |  |  |  |
| 460002PBP-N172                 | 13                | 3.3                       | N/A                      | N/A |  |  |  |  |
| 460002PBP-N173                 | 13                | -8.8                      | N/A                      | N/A |  |  |  |  |
| 460002PBP-N174                 | 13                | 0.2                       | N/A                      | N/A |  |  |  |  |
| 460002PBP-N175                 | 13                | 12.3                      | N/A                      | N/A |  |  |  |  |
| 460002PBP-N176                 | 13                | 3.3                       | N/A                      | N/A |  |  |  |  |
| 460002PBP-N177                 | 13                | 12.3                      | N/A                      | N/A |  |  |  |  |
| 460002PBP-N178                 | 13                | 15.5                      | N/A                      | N/A |  |  |  |  |

Printed On: 04/07/05 06:56

Page: 18 of 19


Description: Building 460 Interior - North Offices, High Bay & Loading Dock Areas


### **Biased Total Surface Activity Data Sheet**

| Biased Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |       |
|--------------------------------|-------------------|---------------------------|--------------------------|-------|
| 460002PBP-N179                 | 13                | -7.0                      | N/A                      | N/A   |
| 460002PBP-N180                 | 13                | 15.5                      | N/A                      | N/A   |
| 460002PBP-N181                 | 13                | 56.0                      | N/A                      | N/A   |
| 460002PBP-N182                 | 13                | 18.2                      | N/A                      | N/A   |
| 460002PBP-N183                 | 18                | 9.3                       | N/A                      | N/A   |
| 460002PBP-N184                 | 18                | 6.6                       | N/A                      | N/A   |
| 460002PBP-N185                 | 26                | 28.9                      | N/A                      | N/A   |
| 460002PBP-N186                 | 27                | 7.4                       | N/A                      | N/A   |
| 460002PBP-N187                 | 26                | 36.8                      | N/A                      | N/A   |
| 460002PBP-N188                 | 27                | 65.2                      | N/A                      | N/A   |
| 460002PBP-N189                 | 26                | 69.3                      | N/A                      | N/A   |
| 460002PBP-N190                 | 27                | 20.7                      | N/A                      | N/A   |
| 460002PBP-N191                 | 26                | 22.8                      | N/A                      | . N/A |
| 460002PBP-N192                 | 27                | 59.4                      | N/A                      | N/A   |
| 460002PBP-N193                 | 26                | 64.7                      | N/A                      | N/A   |
| 460002PBP-N194                 | 27                | 16.3                      | N/A                      | N/A   |
| 460002PBP-N195                 | 26                | 4.2                       | N/A                      | N/A   |
| 460002PBP-N196                 | 27                | 34.1                      | N/A                      | N/A   |
| 460002PBP-N197                 | 26                | -5.1                      | N/A                      | N/A   |
| 460002PBP-N198                 | 27                | -10.4                     | N/A                      | N/A   |
| 460002PBP-N199                 | 26                | 12.1                      | N/A                      | N/A   |
| 460002PBP-N200                 | 27                | -2.8                      | N/A                      | N/A   |
| 460002PBP-N201                 | 26                | -1.8                      | N/A                      | N/A   |
| 460002PBP-N202                 | 27                | -1.5                      | N/A                      | N/A   |

Printed On: 04/07/05 06:56

Page: 19 of 19





Survey Area: 5 Building: 460


Survey Unit: 460002


Classification: 3

Survey Unit Description: 460 Interior - North Offices, High Bay & Loading Dock Areas
Total Area: 27,496 sq. m. Total Floor Area: 10,041 sq. m.

Total Area: 27,496 sq. m.

**PAGE 1 OF 17** 





Survey Area: 5

Survey Unit: 460002


Classification: 3

Building: 460

Survey Unit Description: 460 Interior - North Offices, High Bay & Loading Dock Areas

Total Area: 27,496 sq. m. Total Floor Area: 10,041 sq. m.

**PAGE 2 OF 17** 





Survey Area: 5 Building: 460 Survey Unit: 460002

Classification: 3

Survey Unit Description: 460 Interior - North Offices, High Bay & Loading Dock Areas Total Area: 27,496 sq. m. Total Floor Area: 10,041 sq. m.

**PAGE 3 OF 17** 





Survey Area: 5

Survey Unit: 460002


Classification: 3

Building: 460

Survey Unit Description: 460 Interior - North Offices, High Bay & Loading Dock Areas Total Floor Area: 10,041 sq. m.

Total Area: 27,496 sq. m.

**PAGE 4 OF 17** 



Survey Area: 5 Building: 460

Smear, TSA & Sample Location

Scan Survey Information

Survey Instrument ID #(s) & RCT ID #(s):

1-3, 7, 8, 11-13, 16-18, 20, 21, 24, 25

Open/Inaccessible Area

Area in Another Survey Unit


Survey Unit: 460002

Classification: 3

Survey Unit Description: 460 Interior - North Offices, High Bay & Loading Dock Areas Total Floor Area: 10,041 sq. m.

Total Area: 27,496 sq. m.

PAGE 5 OF 17



**METERS** 

1 inch = 24 feet 1 grid sq. = 1 sq. m.

10

CH2MHILL

MAP ID: 03-0138\460\_HB\_5\_SC

AISER HILL

Apr. 4, 2005

Survey Area: 5

Survey Unit: 460002


Classification: 3


**Building: 460** 


Survey Unit Description: 460 Interior - North Offices, High Bay & Loading Dock Areas Total Area: 27,496 sq. m. Total Floor Area: 10,041 sq. m.

**PAGE 6 OF 17** 

#### Room 151







Survey Area: 5 Building: 460

Survey Unit: 460002


Classification: 3

Survey Unit Description: 460 Interior - North Offices, High Bay & Loading Dock Areas Total Floor Area: 10,041 sq. m.

Total Area: 27,496 sq. m.

PAGE 8 OF

#### Walls for Room 134



Smear & TSA Location

Smear, TSA & Sample Location


Open/Inaccessible Area

Area in Another Survey Unit

Neither the United States Government not Kaiser Hill Co. not CH2MHill, nor any agency thereof, nor any of their employees, makes any warrany, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights.



Scan Survey Information Survey Instrument ID #(s) & RCT ID #(s): 1-3, 7, 8, 11-13, 16-18, 20, 21, 24, 25



1 inch = 36 feet 1 grid sq. = 1 sq. m.

Rocky Flats Environmental Technology Site

Prepared by: GIS Dept. 303-966-7707

Prepared for:



MAP ID: 03-0138/460\_HB\_8\_SC

AISER HILL Apr. 4, 2005

Survey Area: 5

Survey Unit: 460002


Classification: 3

Total Area: 27,496 sq. m.

Building: 460 Survey Unit Description: 460 Interior - North Offices, High Bay & Loading Dock Areas

Total Floor Area: 10,041 sq. m.

#### Room Mezzanine



#### **SURVEY MAP LEGEND**

Smear & TSA Location


Smear, TSA & Sample Location

Open/Inaccessible Area

Area in Another Survey Unit

Neither the United States Government nor Kaiser Hill Co Neither the United States Government nor Kaiser Hill Go-nor DynCorp I&ET, nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights.

Scan Survey Information Survey Instrument ID #(s) & RCT ID #(s): 1-3, 7, 8, 11-13, 16-18, 20, 21, 24, 25



1 inch = 36 feet 1 grid sq. = 1 sq. m.

U.S. Department of Energy Rocky Flats Environmental Technology Site

repared by: GIS Dept. 303-966-7707

Scan Area



Communications Group MAP ID: 03-0138\460\_HB\_9\_SC



Apr. 4, 2005

Survey Area: 5 Building: 460

1-3, 7, 8, 11-13, 16-18, 20, 21, 24, 25

Survey Unit: 460002

Classification: 3

Survey Unit Description: 460 Interior - North Offices, High Bay & Loading Dock Areas
Total Area: 27,496 sq. m. Total Floor Area: 10,041 sq. m.

PAGE 10 OF 17

### Room Mezzanine (52) (27) (33) (141) Ceiling (inverted) 35 135 101 Room 143 **113** Room 144 Room 143A Room 143B Wall 1 Wall 1 Ceiling (inverted) Ceiling (inverted) Wall : ોવાઇઇ Wall 4 **139** Wall 3 82 Ceiling 145 Ceiling Scan Area Neither the United States Government nor Kaiser Hill Co U.S. Department of Energy SURVEY MAP LEGEND nor DynCorp l&ET, nor any agency thereof, nor any of their employees, makes any warranty, express or implied FEET 45 Rocky Flats Environmental Technology Site Smear & TSA Location or assumes any legal liability or responsibility for the repared by: GIS Dept. 303-966-7707 of assumes any regar factority on tresponsionary for un-accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Smear, TSA & Sample Locatio **METERS** 15 Open/Inaccessible Area CH2MHILL Scan Survey Information Area in Another Survey Unit Communications Group Survey Instrument ID #(s) & RCT ID #(s):

1 inch = 36 feet 1 grid sq. = 1 sq. m.

MAP ID: 03-0138\460\_HB\_10\_SC

Apr. 4, 2005

Survey Area: 5 Building: 460


Survey Unit: 460002


Classification: 3

Survey Unit Description: 460 Interior - North Offices, High Bay & Loading Dock Areas Total Floor Area: 10,041 sq. m.

Total Area: 27,496 sq. m.

**PAGE 11 OF 17** 






Survey Area: 5 Building: 460 Survey Unit: 460002

Classification: 3

Survey Unit Description: 460 Interior - North Offices, High Bay & Loading Dock Areas Total Area: 27,496 sq. m. Total Floor Area: 10,041 sq. m.

PAGE 12 OF 17



Survey Area: 5 Building: 460 Survey Unit: 460002


Classification: 3


Total Area: 27,496 sq. m.

Survey Unit Description: 460 Interior - North Offices, High Bay & Loading Dock Areas

Total Floor Area: 10,041 sq. m.

PAGE 13 OF 17







Survey Area: 5 Building: 460 Survey Unit: 460002

Classification: 3

Survey Unit Description: 460 Interior - North Offices, High Bay & Loading Dock Areas Total Area: 27,496 sq. m. Total Floor Area: 10,041 sq. m.

**PAGE 14 OF 17** 






Survey Area: 5 **Building: 460** 

Survey Unit: 460002

Classification: 3

Survey Unit Description: 460 Interior - North Offices, High Bay & Loading Dock Areas Total Area: 27,496 sq. m. Total Floor Area: 10,041 sq. m.

**PAGE 15 OF 17** 



Survey Area: 5 Building: 460


Survey Unit: 460002

Classification: 3

Survey Unit Description: 460 Interior - North Offices, High Bay & Loading Dock Areas Total Area: 27,496 sq. m.

Total Floor Area: 10,041 sq. m.

PAGE 16 OF 17




### PRE-DEMOLITION SURVEY FOR BUILDING 460


Survey Area: 5 Survey Unit: 460002 Classification: 3
Building: 460
Survey Unit Description: Interior - North Offices, High Bay & Loading Dock Areas
Total Area: 27,496 sq. m. Total Floor Area: 10,041 sq. m.


PAGE 17 OF 17



























Survey Area: 5

Survey Unit: 460003

Building: 460

Description: Building 460 Interior - First Floor South Offices

### **Rocky Flats Environmental Technology Site Final Radiological Survey Summary Results**

### **Total Surface Activity Measurements**

Nbr Random Measurements Required: 70

Nbr Biased Measurements Required: 25

Nbr QC Required: 4

Nbr Random Measurements Performed: 70

Nbr Biased Measurements Performed: 25

Nbr QC Performed: 4

#### **Alpha**

Maximum:

75.0 dpm/100cm<sup>2</sup>

Minimum:

-13.3 dpm/100cm<sup>2</sup>

Mean:

12.5 dpm/100cm<sup>2</sup> 14.5

Standard Deviation:

36.3 dpm/100cm<sup>2</sup>

QC Maximum: QC Minimum:

29.8 dpm/100cm<sup>2</sup>

QC Mean:

32.2 dpm/100cm<sup>2</sup>

Transuranic DCGLw:

100.0 dpm/100cm<sup>2</sup>

Transuranic DCGLEMC:

300.0 dpm/100cm<sup>2</sup>

### **Removable Surface Activity Measurements**

Nbr Random Measurements Required: 70

Nbr Biased Measurements Required: 25

Nbr Random Measurements Performed: 70

Nbr Biased Measurements Performed: 25

#### Alpha

Maximum:

6.1 dpm/100cm<sup>2</sup>

Minimum:

-1.5 dpm/100cm<sup>2</sup>

Mean:

0.2 dpm/100cm<sup>2</sup>

Standard Deviation:

1.5

Transuranic DCGLw:

20.0 dpm/100cm<sup>2</sup>

#### Media Sample Results

Nbr Random Required: 0

Nbr Biased Required: 0

Nbr Random Collected: 0

Nbr Biased Collected: 0

Conclusion - A comparison of the random, biased and QC measurement results against the PDSP Table 7-1 Surface Contamination Guideline limits was conducted; the comparison demonstrates that this survey unit passes the criterion specified in the PDSP.

Printed On: 04/05/05 08:08

of 11 Page: 1

Survey Area: 5

Survey Unit: 460003

Building: 460

Description: Building 460 Interior - First Floor South Offices

### **Instrument Data Sheet**

| Inst/RC | T RCT  | Analysis | Instr   | Instru | Probe | Calibration | Instru Eff | ficiency |       | ri MDA<br>00cm²) | Survey |
|---------|--------|----------|---------|--------|-------|-------------|------------|----------|-------|------------------|--------|
| Number  |        | Date     | Model   | S/N    | Туре  | Due Dt      | Alpha      | Beta     | Alpha | Beta             | Type   |
| 1       | 711447 | 02/08/05 | Electra | 1235   | DP-6  | 03/16/05    | 0.222      | NA       | 48.0  | NA               | Т      |
| 2       | 712467 | 02/10/05 | Electra | 657    | AP-6  | 06/13/05    | 0.184      | NA       | 48.0  | NA               | S      |
| 3       | 711447 | 02/12/05 | Electra | 3370   | DP-6  | 07/27/05    | 0.213      | NA       | 48.0  | NA               | Т      |
| 4       | 712467 | 02/12/05 | Electra | 673    | AP-6  | 07/24/05    | 0.173      | NA       | 48.0  | NA               | S      |
| 5       | 712467 | 02/12/05 | Electra | 1366   | DP-6  | 04/05/05    | 0.212      | NA       | 48.0  | NA               | S      |
| 6       | 711447 | 02/14/05 | SAC-4   | 767    | NA    | 08/03/05    | 0.330      | NA       | 10.0  | NA               | R      |
| 7       | 711447 | 02/14/05 | SAC-4   | 1130   | NA    | 07/03/05    | 0.330      | NA       | 10.0  | NA               | R      |
| 8       | 511390 | 02/28/05 | Electra | 3254   | DP-6  | 07/04/05    | 0.225      | NA       | 48.0  | NA               | T/S    |
| 9       | 711447 | 02/28/05 | Electra | 1366   | DP-6  | 04/05/05    | 0.212      | NA       | 48.0  | NA               | T/S    |
| 10      | 712467 | 02/28/05 | Electra | 673    | AP-6  | 07/24/05    | 0.173      | NA       | 48.0  | NA               | S      |
| 11      | 711447 | 03/07/05 | Electra | 1366   | DP-6  | 04/05/05    | 0.212      | NA       | 48.0  | NA               | T/S    |
| 12      | 712467 | 03/07/05 | Electra | 3370   | DP-6  | 07/27/05    | 0.213      | NA       | 48.0  | NA               | T/S    |
| 13      | 712467 | 03/07/05 | SAC-4   | 1130   | NA    | 07/03/05    | 0.330      | NA       | 10.0  | NA               | R      |
| 14      | 511390 | 03/17/05 | Electra | 1366   | DP-6  | 04/05/05    | 0.212      | NA       | 48.0  | NA               | T/S    |
| 15      | 515538 | 03/17/05 | Electra | 3102   | DP-6  | 06/16/05    | 0.216      | NA       | 48.0  | NA               | T/S    |
| 16      | 515538 | 03/17/05 | SAC-4   | 767    | NA    | 08/03/05    | 0.330      | NA       | 10.0  | NA               | R      |
| 17      | 511390 | 03/17/05 | Electra | 3102   | DP-6  | 06/16/05    | 0.216      | NA       | 48.0  | NA               | Q/S    |

Survey Types: T = Total Surface Activity, Q = TSA QC, S = Scan, R = Removable Surface Activity, I = Investigation

Printed On: 04/05/05 08:08

Page: 2 of 11

| Survey Area          | a: 5    |                | Sui               | rvey Unit: | 460003 |           | Buildi | ng: 460  |   |
|----------------------|---------|----------------|-------------------|------------|--------|-----------|--------|----------|---|
| Description: B       | uilding | 460 Interior - | First Floor South | Offices    |        |           |        |          |   |
|                      |         |                |                   |            |        |           |        | <u> </u> |   |
|                      |         |                |                   | (          | Commer | nts Sheet |        |          | İ |
| General<br>Comments: | N/A     |                |                   |            |        |           |        |          |   |
| TSA<br>Comments:     | N/A     |                |                   |            |        |           |        |          |   |
| RSA<br>Comments:     | N/A     |                |                   |            |        |           |        |          |   |
| Media<br>Comments:   | N/A     |                |                   |            |        |           |        |          |   |
|                      |         |                |                   |            |        |           |        |          |   |
|                      |         |                |                   |            |        |           |        |          |   |
|                      |         |                |                   |            |        |           |        |          |   |
|                      |         |                |                   |            |        |           |        |          |   |
|                      |         |                |                   |            |        |           |        |          |   |
|                      |         |                |                   |            |        |           |        |          |   |
|                      |         |                |                   |            |        |           |        |          |   |
|                      |         |                |                   |            |        |           |        | ·        |   |
|                      |         |                |                   |            |        |           |        |          |   |
|                      |         |                |                   |            |        |           |        |          |   |
|                      |         |                |                   |            |        |           |        |          |   |
|                      |         |                |                   |            |        |           |        | •        |   |
|                      |         |                |                   |            |        |           |        |          |   |
| 1                    |         |                |                   |            |        |           |        |          |   |

Printed On: 04/05/05 08:08

Page: 3 of 11

| Surve | y Area: 5 | Survey Unit: 460003 | Building: 460 |  |
|-------|-----------|---------------------|---------------|--|
|       |           |                     |               |  |

Description: Building 460 Interior - First Floor South Offices

## **Random Removable Surface Activity Data Sheet**

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |       |
|--------------------------------|-------------------|---------------------------|--------------------------|-------|
| 460003PRP-N001                 | 7                 | 0.3                       | N/A                      | N/A   |
| 460003PRP-N002                 | 13                | -1.5                      | N/A                      | N/A   |
| 460003PRP-N003                 | 6                 | 1.2                       | N/A                      | N/A . |
| 460003PRP-N004                 | 7                 | 1.8                       | N/A                      | N/A   |
| 460003PRP-N005                 | 7                 | 0.3                       | N/A                      | N/A   |
| 460003PRP-N006                 | 7                 | 0.3                       | N/A                      | N/A   |
| 460003PRP-N007                 | 7                 | -1.2                      | N/A                      | N/A   |
| 460003PRP-N008                 | 7                 | -1.2                      | N/A                      | N/A   |
| 460003PRP-N009                 | 7                 | -1.2                      | N/A                      | N/A   |
| 460003PRP-N010                 | 7                 | -1.2                      | N/A                      | N/A   |
| 460003PRP-N011                 | 6                 | 1.2                       | N/A                      | N/A   |
| 460003PRP-N012                 | 6                 | 2.7                       | N/A                      | N/A   |
| 460003PRP-N013                 | 7                 | 0.3                       | N/A                      | N/A   |
| 460003PRP-N014                 | 6                 | -0.3                      | N/A                      | N/A   |
| 460003PRP-N015                 | 7                 | 0.3                       | N/A                      | N/A   |
| 460003PRP-N016                 | 6                 | -0.3                      | N/A                      | N/A   |
| 460003PRP-N017                 | 16                | -1.5                      | N/A                      | N/A   |
| 460003PRP-N018                 | 6                 | -0.3                      | N/A                      | N/A   |
| 460003PRP-N019                 | 13                | 1.5                       | N/A                      | N/A   |
| 460003PRP-N020                 | 6                 | 4.2                       | N/A                      | N/A   |
| 460003PRP-N021                 | 6                 | 2.7                       | N/A                      | N/A   |
| 460003PRP-N022                 | 7                 | 0.3                       | N/A                      | N/A   |
| 460003PRP-N023                 | 7                 | 0.3                       | N/A                      | N/A   |
| 460003PRP-N024                 | 6                 | -0.3                      | N/A                      | N/A   |
| 460003PRP-N025                 | 7                 | -1.2                      | N/A                      | N/A   |
| 460003PRP-N026                 | 6                 | 1.2                       | N/A                      | N/A   |
| 460003PRP-N027                 | 7                 | 0.3                       | N/A                      | N/A   |
| 460003PRP-N028                 | 6                 | 1.2                       | N/A                      | N/A   |
| 460003PRP-N029                 | 7                 | 0.3                       | N/A                      | N/A   |

Printed On: 04/05/05 08:08
Page: 4 of 11

Description: Building 460 Interior - First Floor South Offices

# **Random Removable Surface Activity Data Sheet**

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460003PRP-N030                 | 6                 | -0.3                      | N/A                      | N/A |
| 460003PRP-N031                 | 13                | -1.5                      | N/A                      | N/A |
| 460003PRP-N032                 | 6                 | 1.2                       | N/A                      | N/A |
| 460003PRP-N033                 | 6                 | -0.3                      | N/A                      | N/A |
| 460003PRP-N034                 | 6                 | -0.3                      | N/A                      | N/A |
| 460003PRP-N035                 | 7                 | -1.2                      | N/A                      | N/A |
| 460003PRP-N036                 | 7                 | 3.3                       | N/A                      | N/A |
| 460003PRP-N037                 | 7                 | -1.2                      | N/A                      | N/A |
| 460003PRP-N038                 | 7                 | 4.9                       | N/A                      | N/A |
| 460003PRP-N039                 | 6                 | -0.3                      | N/A                      | N/A |
| 460003PRP-N040                 | 6                 | -0.3                      | N/A                      | N/A |
| 460003PRP-N041                 | 7                 | 0.3                       | N/A                      | N/A |
| 460003PRP-N042                 | 7                 | -1.2                      | N/A                      | N/A |
| 460003PRP-N043                 | 7                 | 0.3                       | N/A                      | N/A |
| 460003PRP-N044                 | 7                 | 1.8                       | N/A                      | N/A |
| 460003PRP-N045                 | 7                 | 0.3                       | N/A                      | N/A |
| 460003PRP-N046                 | 7                 | 0.3                       | N/A                      | N/A |
| 460003PRP-N047                 | 7                 | -1.2                      | N/A                      | N/A |
| 460003PRP-N048                 | 7                 | -1.2                      | N/A                      | N/A |
| 460003PRP-N049                 | 6                 | -0.3                      | N/A                      | N/A |
| 460003PRP-N050                 | 13                | 0.0                       | N/A                      | N/A |
| 460003PRP-N051                 | 6                 | -0.3                      | N/A                      | N/A |
| 460003PRP-N052                 | 6                 | -0.3                      | N/A                      | N/A |
| 460003PRP-N053                 | 13                | 0.0                       | N/A                      | N/A |
| 460003PRP-N054                 | 6                 | 1.2                       | N/A                      | N/A |
| 460003PRP-N055                 | 6                 | -0.3                      | N/A                      | N/A |
| 460003PRP-N056                 | 6                 | 1.2                       | N/A                      | N/A |
| 460003PRP-N057                 | 6                 | 2.7                       | N/A                      | N/A |
| 460003PRP-N058                 | 13                | -1.5                      | N/A                      | N/A |

Printed On: 04/05/05 08:08

Page: 5 of 11

Description: Building 460 Interior - First Floor South Offices

## **Random Removable Surface Activity Data Sheet**

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460003PRP-N059                 | 13                | 0.0                       | N/A                      | N/A |
| 460003PRP-N060                 | 6                 | -0.3                      | N/A                      | N/A |
| 460003PRP-N061                 | 7                 | 0.3                       | N/A                      | N/A |
| 460003PRP-N062                 | 6                 | 1.2                       | N/A                      | N/A |
| 460003PRP-N063                 | 16                | -1.5                      | N/A                      | N/A |
| 460003PRP-N064                 | 6                 | -0.3                      | N/A                      | N/A |
| 460003PRP-N065                 | 7                 | 1.8                       | N/A                      | N/A |
| 460003PRP-N066                 | 13                | 0.0                       | N/A                      | N/A |
| 460003PRP-N067                 | 6                 | -0.3                      | N/A                      | N/A |
| 460003PRP-N068                 | 13                | 3.0                       | N/A                      | N/A |
| 460003PRP-N069                 | 7                 | 1.8                       | N/A                      | N/A |
| 460003PRP-N070                 | 13                | -1.5                      | N/A                      | N/A |

Printed On: 04/05/05 08:08

Page: 6 of 11

Description: Building 460 Interior - First Floor South Offices

# **Biased Removable Surface Activity Data Sheet**

| Biased Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |       |
|--------------------------------|-------------------|---------------------------|--------------------------|-------|
| 460003PBP-N071                 | 6                 | -0.3                      | N/A                      | N/A   |
| 460003PBP-N072                 | 7                 | 0.3                       | N/A                      | N/A   |
| 460003PBP-N073                 | 13                | 1.5                       | N/A                      | N/A   |
| 460003PBP-N074                 | 13                | -1.5                      | N/A                      | N/A   |
| 460003PBP-N075                 | 16                | -1.5                      | N/A                      | N/A   |
| 460003PBP-N076                 | 16                | -1.5                      | N/A                      | N/A   |
| 460003PBP-N077                 | 16                | -1.5                      | N/A                      | N/A   |
| 460003PBP-N078                 | 16                | 0.0                       | N/A                      | N/A   |
| 460003PBP-N079                 | 16                | -1.5                      | N/A                      | N/A   |
| 460003PBP-N080                 | 16                | 0.0                       | N/A                      | N/A   |
| 460003PBP-N081                 | 16                | 0.0                       | N/A                      | N/A   |
| 460003PBP-N082                 | 16                | 1.5                       | N/A                      | N/A   |
| 460003PBP-N083                 | 16                | -1.5                      | N/A                      | N/A   |
| 460003PBP-N084                 | 16                | 0.0                       | N/A                      | N/A   |
| 460003PBP-N085                 | 16                | -1.5                      | N/A                      | N/A   |
| 460003PBP-N086                 | 16                | 0.0                       | N/A                      | N/A   |
| 460003PBP-N087                 | 16                | -1.5                      | N/A                      | N/A   |
| 460003PBP-N088                 | 13                | -1.5                      | N/A                      | N/A   |
| 460003PBP-N089                 | 13                | -1.5                      | N/A                      | N/A   |
| 460003PBP-N090                 | 13                | 0.0                       | N/A                      | N/A   |
| 460003PBP-N091                 | 13                | 0.0                       | N/A                      | N/A   |
| 460003PBP-N092                 | 13                | 0.0                       | N/A                      | N/A   |
| 460003PBP-N093                 | 13                | 1.5                       | N/A                      | N/A   |
| 460003PBP-N094                 | 13                | 6.1                       | N/A                      | N/A . |
| 460003PBP-N095                 | 13                | 1.5                       | N/A                      | N/A   |

Printed On: 04/05/05 08:08

Page: 7 of 11

Description: Building 460 Interior - First Floor South Offices

# Random/QC Total Surface Activity Data Sheet

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460003PRP-N001                 | 3                 | 15.9                      | N/A                      | N/A |
| 460003PRP-N002                 | 11                | 22.1                      | N/A                      | N/A |
| 460003PRP-N003                 | 9                 | 18.8                      | N/A                      | N/A |
| 460003PRP-N004                 | 8                 | 25.7                      | N/A                      | N/A |
| 460003PRP-N005                 | 3                 | 15.9                      | N/A                      | N/A |
| 460003PRP-N006                 | 3                 | 40.7                      | N/A                      | N/A |
| 460003PRP-N007                 | 9                 | 16.0                      | N/A                      | N/A |
| 460003PRP-N008                 | 3                 | 3.2                       | N/A                      | N/A |
| 460003PRP-N009                 | 3                 | -0.1                      | N/A                      | N/A |
| 460003PRP-N010                 | 3                 | 6.5                       | N/A                      | N/A |
| 460003PRP-N011                 | 9                 | 28.3                      | N/A                      | N/A |
| 460003PRP-N012                 | 9                 | 16.0                      | N/A                      | N/A |
| 460003PRP-N013                 | 1                 | 15.9                      | N/A                      | N/A |
| 460003PRP-N014                 | 3                 | 25.2                      | N/A                      | N/A |
| 460003PRP-N015                 | 3                 | 18.7                      | N/A                      | N/A |
| 460003PRP-N016                 | 9                 | 3.3                       | N/A                      | N/A |
| 460003PRP-N017                 | 9                 | 12.7                      | N/A                      | N/A |
| 460003PRP-N018                 | 8                 | 23.1                      | N/A                      | N/A |
| 460003PRP-N019                 | 11                | 16.0                      | N/A                      | N/A |
| 460003PRP-N020                 | 9                 | -2.9                      | N/A                      | N/A |
| 460003PRP-N021                 | 9                 | 18.8                      | N/A                      | N/A |
| 460003PRP-N022                 | 3                 | 28.1                      | N/A                      | N/A |
| 460003PRP-N023                 | 3                 | 15.9                      | N/A                      | N/A |
| 460003PRP-N024                 | 3                 | 40.7                      | N/A                      | N/A |
| 460003QRP-N024                 | 17                | 29.8                      | N/A                      | N/A |
| 460003PRP-N025                 | 3                 | 6.5                       | N/A                      | N/A |
| 460003PRP-N026                 | 1                 | 8.3                       | N/A                      | N/A |

Printed On: 04/05/05 08:08 Page: 8 of 11

| Survey Area: 5 | Survey Unit: | 460003 |      | Building: 460 |      |
|----------------|--------------|--------|------|---------------|------|
|                |              |        | <br> |               | <br> |

Description: Building 460 Interior - First Floor South Offices

# Random/QC Total Surface Activity Data Sheet

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460003PRP-N027                 | 11                | 9.4                       | N/A                      | N/A |
| 460003PRP-N028                 | 8                 | 14.2                      | N/A                      | N/A |
| 460003PRP-N029                 | 1                 | -3.4                      | N/A                      | N/A |
| 460003PRP-N030                 | 3                 | 17.3                      | N/A                      | N/A |
| 460003PRP-N031                 | 11                | -6.2                      | N/A                      | N/A |
| 460003PRP-N032                 | 8                 | 14.2                      | N/A                      | N/A |
| 460003PRP-N033                 | 8                 | -9.8                      | N/A                      | N/A |
| 460003PRP-N034                 | 3                 | 15.9                      | N/A                      | N/A |
| 460003PRP-N035                 | 1                 | 8.3                       | N/A                      | N/A |
| 460003PRP-N036                 | 9                 | 12.7                      | N/A                      | N/A |
| 460003PRP-N037                 | 9                 | 37.7                      | N/A                      | N/A |
| 460003QRP-N037                 | 17                | 33.1                      | N/A                      | N/A |
| 460003PRP-N038                 | 9                 | 44.3                      | N/A                      | N/A |
| 460003QRP-N038                 | 17                | 36.3                      | N/A                      | N/A |
| 460003PRP-N039                 | 14                | 16.0                      | N/A                      | N/A |
| 460003PRP-N040                 | 1                 | 11.4                      | N/A                      | N/A |
| 460003PRP-N041                 | 9                 | 9.4                       | N/A                      | N/A |
| 460003PRP-N042                 | 3                 | 18.7                      | N/A                      | N/A |
| 460003PRP-N043                 | 9                 | -2.9                      | N/A                      | N/A |
| 460003PRP-N044                 | 9                 | -6.2                      | N/A                      | N/A |
| 460003PRP-N045                 | 1                 | 17.3                      | N/A                      | N/A |
| 460003PRP-N046                 | 8                 | -3.6                      | N/A                      | N/A |
| 460003PRP-N047                 | 9                 | 9.4                       | N/A                      | N/A |
| 460003PRP-N048                 | 3                 | 46.8                      | N/A                      | N/A |
| 460003QRP-N048                 | 17                | 29.8                      | N/A                      | N/A |
| 460003PRP-N049                 | 9                 | 12.7                      | N/A                      | N/A |
| 460003PRP-N050                 | 11                | -0.0                      | N/A                      | N/A |

Printed On: 04/05/05 08:08
Page: 9 of 11

Description: Building 460 Interior - First Floor South Offices

## Random/QC Total Surface Activity Data Sheet

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460003PRP-N051                 | 8                 | 16.8                      | N/A                      | N/A |
| 460003PRP-N052                 | 8                 | 11.1                      | N/A                      | N/A |
| 460003PRP-N053                 | 11                | 3.3                       | N/A                      | N/A |
| 460003PRP-N054                 | 1                 | -6.6                      | N/A                      | N/A |
| 460003PRP-N055                 | 3                 | 11.2                      | N/A                      | N/A |
| 460003PRP-N056                 | 3                 | 18.7                      | N/A                      | N/A |
| 460003PRP-N057                 | 9                 | 18.8                      | N/A                      | N/A |
| 460003PRP-N058                 | 11                | -9.5                      | N/A                      | N/A |
| 460003PRP-N059                 | 11                | -6.2                      | N/A                      | N/A |
| 460003PRP-N060                 | 3                 | -0.1                      | N/A                      | N/A |
| 460003PRP-N061                 | 3                 | -2.9                      | N/A                      | N/A |
| 460003PRP-N062                 | 3                 | -0.1                      | N/A                      | N/A |
| 460003PRP-N063                 | 14                | 22.1                      | N/A                      | N/A |
| 460003PRP-N064                 | 3                 | 9.3                       | N/A                      | N/A |
| 460003PRP-N065                 | 9                 | 9.4                       | N/A                      | N/A |
| 460003PRP-N066                 | 11                | 18.8                      | N/A                      | N/A |
| 460003PRP-N067                 | 3                 | 3.2                       | N/A                      | N/A |
| 460003PRP-N068                 | 11                | -0.0                      | N/A                      | N/A |
| 460003PRP-N069                 | 9                 | 14.1                      | N/A                      | N/A |
| 460003PRP-N070                 | 11                | 9.4                       | N/A                      | N/A |

Printed On: 04/05/05 08:08 Page: 10 of 11


| Survey Area: 5 | Survey Unit: | 460003 | Building: | 460 | 100 |  |
|----------------|--------------|--------|-----------|-----|-----|--|
|                | <br>         | ŵ      | J         |     | •   |  |

Description: Building 460 Interior - First Floor South Offices

# **Biased Total Surface Activity Data Sheet**

| Biased Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460003PBP-N071                 | 8                 | 7.3                       | N/A                      | N/A |
| 460003PBP-N072                 | 8                 | 21.9                      | N/A                      | N/A |
| 460003PBP-N073                 | 11                | -0.5                      | N/A                      | N/A |
| 460003PBP-N074                 | 11                | 5.6                       | N/A                      | N/A |
| 460003PBP-N075                 | 15                | 30.1                      | N/A                      | N/A |
| 460003PBP-N076                 | 14                | 2.8                       | N/A                      | N/A |
| 460003PBP-N077                 | 15                | 17.6                      | N/A                      | N/A |
| 460003PBP-N078                 | 14                | 15.0                      | N/A                      | N/A |
| 460003PBP-N079                 | 15                | 30.1                      | N/A                      | N/A |
| 460003PBP-N080                 | 14                | 33.9                      | N/A                      | N/A |
| 460003PBP-N081                 | 15                | 32.9                      | N/A                      | N/A |
| 460003PBP-N082                 | 14                | 29.2                      | N/A                      | N/A |
| 460003PBP-N083                 | 15                | -0.9                      | N/A                      | N/A |
| 460003PBP-N084                 | 14                | -0.5                      | N/A                      | N/A |
| 460003PBP-N085                 | 15                | 2.4                       | N/A                      | N/A |
| 460003PBP-N086                 | 14                | 15.0                      | N/A                      | N/A |
| 460003PBP-N087                 | 15                | 8.4                       | N/A                      | N/A |
| 460003PBP-N088                 | 12                | -3.9                      | N/A                      | N/A |
| 460003PBP-N089                 | 12                | 21.4                      | N/A                      | N/A |
| 460003PBP-N090                 | 12                | -10.0                     | N/A                      | N/A |
| 460003PBP-N091                 | 12                | 75.0                      | N/A                      | N/A |
| 460003PBP-N092                 | 12                | -3.9                      | N/A                      | N/A |
| 460003PBP-N093                 | 12                | -13.3                     | N/A                      | N/A |
| 460003PBP-N094                 | 12                | -6.7                      | N/A                      | N/A |
| 460003PBP-N095                 | 12                | 16.8                      | N/A                      | N/A |

Printed On: 04/05/05 08:08 Page: 11 of 11



Survey Area: 5

Survey Unit: 460003

Classification: 3


Building: 460

Survey Unit Description: 460 Interior 1st Floor South Offices

Total Area: 18,117 sq. m.

Total Floor Area: 4,655 sq. m.

PAGE 1 OF 22



Survey Area: 5 Building: 460


Survey Unit: 460003

Classification: 3

Survey Unit Description: 460 Interior 1st Floor South Offices

Total Floor Area: 4,655 sq. m. Total Area: 18,117 sq. m.

PAGE 2 OF 22



Survey Area: 5

Survey Unit: 460003

Classification: 3


Building: 460

Survey Unit Description: 460 Interior 1st Floor South Offices

Total Area: 18,117 sq. m.

Total Floor Area: 4,655 sq. m.

**PAGE 3 OF 22** 



Survey Area: 5

Survey Unit: 460003

Classification: 3


Building: 460


Survey Unit Description: 460 Interior 1st Floor South Offices


Total Area: 18,117 sq. m.

Total Floor Area: 4,655 sq. m.

**PAGE 4 OF 22** 







Survey Area: 5

Survey Unit: 460003

Classification: 3

Building: 460


Survey Unit Description: 460 Interior 1st Floor South Offices


Total Area: 18,117 sq. m.


Total Floor Area: 4,655 sq. m.

**PAGE 5 OF 22** 

Scan Area







Survey Area: 5

Survey Unit: 460003


Classification: 3

Building: 460
Survey Unit Description: 460 Interior 1st Floor South Offices

Total Area: 18,117 sq. m.

Total Floor Area: 4,655 sq. m.

PAGE 6 OF 22



Survey Area: 5 Building: 460 Survey Unit: 460003


Classification: 3

Survey Unit Description: 460 Interior 1st Floor South Offices

Total Area: 18,117 sq. m.

Total Floor Area: 4,655 sq. m.

PAGE 7 OF 22



Survey Area: 5


Survey Unit: 460003


Classification: 3


Building: 460
Survey Unit Description: 460 Interior 1st Floor South Offices Total Floor Area: 4,655 sq. m.

Total Area: 18,117 sq. m.

**PAGE 8 OF 22** 







Survey Area: 5 Building: 460 Survey Unit: 460003

Classification: 3


Survey Unit Description: 460 Interior 1st Floor South Offices


Total Area: 18,117 sq. m.

Total Floor Area: 4,655 sq. m.

PAGE 9 OF 22

#### Room 133






Classification: 3

Survey Area: 5 Survey Unit: 460003 Class Building: 460
Survey Unit Description: 460 Interior 1st Floor South Offices

Total Area: 18,117 sq. m.

Total Floor Area: 4,655 sq. m.

PAGE 10 OF 22




Classification: 3


Survey Area: 5 Survey Unit: 460003 Class Building: 460
Survey Unit Description: 460 Interior 1st Floor South Offices


Total Area: 18,117 sq. m.

Total Floor Area: 4,655 sq. m.

PAGE 11 OF 22







Survey Area: 5 Building: 460 Survey Unit: 460003


Classification: 3


Survey Unit Description: 460 Interior 1st Floor South Offices


Total Area: 18,117 sq. m.

Total Floor Area: 4,655 sq. m.

PAGE 12 OF 22







Survey Area: 5 Building: 460 Survey Unit: 460003


Classification: 3


Survey Unit Description: 460 Interior 1st Floor South Offices

Total Area: 18,117 sq. m.

Total Floor Area: 4,655 sq. m.

PAGE 13 OF 22





Survey Area: 5

Survey Unit: 460003

Classification: 3


Building: 460

Survey Unit Description: 460 Interior 1st Floor South Offices

Total Area: 18,117 sq. m.

Total Floor Area: 4,655 sq. m.

PAGE 14 OF 22



#### Neither the United States Government nor Kaiser Hill Co, nor CH2MHill, nor any agency thereof, nor any of their employees, makes any warrany, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infininge privately owned rights. U.S. Department of Energy **SURVEY MAP LEGEND** FEET 25 Rocky Flats Environmental Technology Site Smear & TSA Location Prepared by: GIS Dept. 303-966-7707 Prepared for: Smear, TSA & Sample Location Open/Inaccessible Area **METERS** CH2MHILL Scan Survey Information Area in Another Survey Unit KAISER HILL iomankations Graud Survey Instrument ID #(s) & RCT ID #(s): 1 inch = 18 feet 1 grid sq. = 1 sq. m. 2, 4, 5, 8-12, 14, 15, 17 MAP ID: 03-0138/460\_p14\_SC Mar. 23, 2005

Survey Area: 5


Survey Unit: 460003


Classification: 3

Survey Unit Description: 460 Interior 1st Floor South Offices

Total Area: 18,117 sq. m.

Total Floor Area: 4,655 sq. m.





Survey Area: 5

Survey Unit: 460003


Classification: 3

Building: 460

Survey Unit Description: 460 Interior 1st Floor South Offices Total Area: 18,117 sq. m. Total Floor Ar

Total Floor Area: 4,655 sq. m.

PAGE 16 OF 22



Survey Area: 5 Building: 460 Survey Unit: 460003


Classification: 3


Survey Unit Description: 460 Interior 1st Floor South Offices

Total Area: 18,117 sq. m.

Total Floor Area: 4,655 sq. m.

PAGE 17 OF 22





Survey Area: 5

Smcar & TSA Location

Smear, TSA & Sample Location Open/Inaccessible Area

Area in Another Survey Unit

Scan Survey Information

2, 4, 5, 8-12, 14, 15, 17

Survey Instrument ID #(s) & RCT ID #(s):

Survey Unit: 460003

Classification: 3


Building: 460

Survey Unit Description: 460 Interior 1st Floor South Offices

Total Área: 18,117 sq. m.

Total Floor Area: 4,655 sq. m.

PAGE 18 OF 22



FEET

**METERS** 

1 inch = 18 feet 1 grid sq. = 1 sq. m.

25

Rocky Flats Environmental Technology Site

Prepared for:

KAISER HILL

Mar. 23, 2005

Prepared by: GIS Dept. 303-966-7707

MAP ID: 03-0138/460\_p18\_SC

CH2MHILL

Communications Group

Survey Area: 5 Building: 460 Survey Unit: 460003

Classification: 3


Survey Unit Description: 460 Interior 1st Floor South Offices


T-4-1 Floor Acces

Total Area: 18,117 sq. m.

Total Floor Area: 4,655 sq. m.

**PAGE 19 OF 22** 





Survey Area: 5 Building: 460 Survey Unit: 460003


Classification: 3


Survey Unit Description: 460 Interior 1st Floor South Offices

Total Floor Area: 4,655 sq. m.

Total Area: 18,117 sq. m.

PAGE 20 OF 22





Survey Area: 5 Building: 460 Survey Unit: 460003


Classification: 3


Survey Unit Description: 460 Interior 1st Floor South Offices

Total Area: 18,117 sq. m.

Total Floor Area: 4,655 sq. m.

PAGE 21 OF 22





Survey Area: 5

Survey Unit: 460003

Classification: 3

Building: 460


Survey Unit Description: 460 Interior 1st Floor South Offices

Total Area: 18,117 sq. m.


Total Floor Area: 4,655 sq. m.


PAGE 22 OF 22

#### Room 107



#### Room 102





Survey Area: 5

Survey Unit: 460504

Building: 460

Description: Building 460, 2nd Floor Office Area Interior, all surfaces

### **Rocky Flats Environmental Technology Site Final Radiological Survey Summary Results**

#### **Total Surface Activity Measurements**

Nbr Random Measurements Required: 64

Nbr Biased Measurements Required: 25

Nbr QC Required: 4

Nbr Random Measurements Performed: 64

Nbr Biased Measurements Performed: 25

Nbr QC Performed: 4

#### **Alpha**

Maximum:

64.1 dpm/100cm<sup>2</sup>

Minimum:

-12.8 dpm/100cm<sup>2</sup>

Mean:

17.2 dpm/100cm<sup>2</sup>

Standard Deviation:

14.8

QC Maximum:

22.2 dpm/100cm<sup>2</sup>

QC Minimum:

-14.0 dpm/100cm<sup>2</sup>

QC Mean:

6.2 dpm/100cm<sup>2</sup>

Transuranic DCGLw:

100.0 dpm/100cm<sup>2</sup>

Transuranic DCGLemc:

300.0 dpm/100cm<sup>2</sup>

#### **Removable Surface Activity Measurements**

Nbr Random Measurements Required: 64

Nbr Biased Measurements Required: 25

Nbr Random Measurements Performed: 64

Nbr Biased Measurements Performed: 25

#### **Alpha**

Maximum:

5.8 dpm/100cm<sup>2</sup>

Minimum:

-1.8 dpm/100cm<sup>2</sup>

Mean:

0.5 dpm/100cm<sup>2</sup>

Standard Deviation:

1.8

Transuranic DCGLw:

20.0 dpm/100cm<sup>2</sup>

#### Media Sample Results

Nbr Random Required: 0

Nbr Biased Required: 0

Nbr Random Collected: 0

Nbr Biased Collected: 0

Conclusion - A comparison of the random, biased and QC measurement results against the PDSP Table 7-1 Surface Contamination Guideline limits was conducted; the comparison demonstrates that this survey unit passes the criterion specified in the PDSP.

Printed On: 04/05/05 08:32

Page: 1

of 11

Survey Area: 5

Survey Unit: 460504

Building: 460

Description: Building 460, 2nd Floor Office Area Interior, all surfaces

### **Instrument Data Sheet**

| Inst/RC | T RCT  | Analysis | Instr   | Instru | Probe | Calibration | Instru Ef | ficiency |       | ri MDA<br>00cm²) | Survey |
|---------|--------|----------|---------|--------|-------|-------------|-----------|----------|-------|------------------|--------|
| Number  |        | Date     | Model   | S/N    | Туре  | Due Dt      | Alpha     | Beta     | Alpha | Beta             | Туре   |
| 1       | 511390 | 03/21/05 | Electra | 3109   | DP-6  | 06/13/05    | 0.215     | NA       | 48.0  | NA               | T/S    |
| 2       | 701418 | 03/21/05 | Electra | 2352   | DP-6  | 06/09/05    | 0.221     | NA       | 48.0  | NA               | T/S    |
| 3       | 515538 | 03/21/05 | Electra | 673    | AP-6  | 07/24/05    | 0.173     | NA       | 48.0  | NA               | S      |
| 4       | 701418 | 03/21/05 | Electra | 3102   | DP-6  | 06/16/05    | 0.216     | NA       | 48.0  | NA               | T/S    |
| 5       | 515538 | 03/21/05 | Electra | 3102   | DP-6  | 06/16/05    | 0.216     | NA       | 48.0  | NA               | T/S    |
| 6       | 511390 | 03/21/05 | SAC-4   | 767    | NA    | 08/03/05    | 0.330     | NA       | 10.0  | NA               | R      |
| 7       | 511390 | 03/21/05 | SAC-4   | 1130   | NA NA | 07/03/05    | 0.330     | NA       | 10.0  | NA               | R      |
| 8       | 511390 | 03/22/05 | Electra | 3109   | DP-6  | 06/13/05    | 0.215     | NA       | 48.0  | NA               | T/S    |
| 9       | 515538 | 03/22/05 | Electra | 3102   | DP-6  | 06/16/05    | 0.216     | NA       | 48.0  | NA               | T/S    |
| 10      | 701418 | 03/22/05 | Electra | 3102   | DP-6  | 06/16/05    | 0.216     | NA       | 48.0  | NA               | T/S    |
| 11      | 515538 | 03/22/05 | Electra | 673    | AP-6  | 07/24/05    | 0.173     | NA       | 48.0  | NA               | S      |
| 12      | 511390 | 03/22/05 | SAC-4   | 767    | NA    | 08/03/05    | 0.330     | NA       | 10.0  | NA               | R .    |
| 13      | 511390 | 03/22/05 | SAC-4   | 1130   | NA    | 07/03/05    | 0.330     | NA       | 10.0  | NA               | R      |
| 14      | 515538 | 03/22/05 | Electra | 2352   | DP-6  | 06/09/05    | 0.221     | NA       | 48.0  | NA               | Q      |

Survey Types: T = Total Surface Activity, Q = TSA QC, S = Scan, R = Removable Surface Activity, I = Investigation

Printed On: 04/05/05 08:32

Page: 2 of 11

| Survey Area          | 1: 5    |                  | S             | urvey Uni       | <b>t:</b> 460504 |          | Build | l <b>ing:</b> 460 |  | * . |
|----------------------|---------|------------------|---------------|-----------------|------------------|----------|-------|-------------------|--|-----|
| Description: Bu      | ıilding | 9 460, 2nd Floor | Office Area I | nterior, all su | rfaces           |          |       |                   |  |     |
|                      |         |                  |               |                 |                  |          |       |                   |  |     |
|                      |         |                  |               |                 | Comme            | ents She | et    |                   |  |     |
| General<br>Comments: | N/A     |                  |               |                 |                  |          |       |                   |  |     |
| TSA<br>Comments:     | N/A     |                  |               |                 |                  |          |       |                   |  |     |
| RSA<br>Comments:     | N/A     |                  |               |                 |                  |          |       |                   |  |     |
| Media<br>Comments:   | N/A     |                  |               |                 |                  |          |       |                   |  |     |
|                      |         |                  |               |                 |                  |          |       |                   |  |     |
|                      |         |                  |               |                 |                  |          |       |                   |  |     |
|                      |         |                  |               |                 |                  |          |       |                   |  |     |
|                      |         |                  |               |                 |                  |          |       |                   |  |     |
|                      |         |                  |               |                 |                  |          |       |                   |  |     |
|                      |         |                  |               |                 |                  |          |       |                   |  |     |
|                      |         |                  |               |                 |                  |          |       |                   |  |     |
|                      |         |                  |               |                 |                  |          |       |                   |  |     |
|                      |         |                  |               |                 |                  |          |       |                   |  |     |
|                      |         |                  |               |                 |                  |          |       |                   |  | :   |
|                      |         |                  |               |                 |                  |          |       |                   |  |     |
|                      |         |                  |               |                 |                  |          |       |                   |  |     |
|                      |         |                  |               |                 |                  |          |       |                   |  |     |
|                      |         |                  |               |                 |                  |          |       |                   |  |     |

Printed On: 04/05/05 08:32
Page: 3 of 11

| Survey Area: 5 | Survey Unit:           | 460504   | Building: 460 |     |      |
|----------------|------------------------|--|---------------|-----|------|
|                | diamental and a second | and the state of t | <br>4.4       | , , | <br> |

Description: Building 460, 2nd Floor Office Area Interior, all surfaces

## **Random Removable Surface Activity Data Sheet**

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta (dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|-----------------------|-----|
| 460504PRP-N001                 | 12                | 1.5                       | N/A                   | N/A |
| 460504PRP-N002                 | 13                | -1.8                      | N/A                   | N/A |
| 460504PRP-N003                 | 12                | 0.0                       | N/A                   | N/A |
| 460504PRP-N004                 | 6                 | 2.1                       | N/A                   | N/A |
| 460504PRP-N005                 | 7                 | -1.8                      | N/A                   | N/A |
| 460504PRP-N006                 | 13                | -1.8                      | N/A                   | N/A |
| 460504PRP-N007                 | 6                 | -0.9                      | N/A                   | N/A |
| 460504PRP-N008                 | 13                | -0.3                      | N/A                   | N/A |
| 460504PRP-N009                 | 6                 | -0.9                      | N/A                   | N/A |
| 460504PRP-N010                 | 6                 | -0.9                      | N/A                   | N/A |
| 460504PRP-N011                 | 7                 | 1.2                       | N/A                   | N/A |
| 460504PRP-N012                 | 13                | 1.2                       | N/A                   | N/A |
| 460504PRP-N013                 | 6                 | 0.6                       | N/A                   | N/A |
| 460504PRP-N014                 | 6                 | 0.6                       | N/A                   | N/A |
| 460504PRP-N015                 | 12                | 0.0                       | N/A                   | N/A |
| 460504PRP-N016                 | 12                | 1.5                       | N/A                   | N/A |
| 460504PRP-N017                 | 6                 | -0.9                      | N/A                   | N/A |
| 460504PRP-N018                 | 12                | 0.0                       | N/A                   | N/A |
| 460504PRP-N019                 | 13                | -0.3                      | N/A                   | N/A |
| 460504PRP-N020                 | 13                | -1.8                      | N/A                   | N/A |
| 460504PRP-N021                 | 12                | 0.0                       | N/A                   | N/A |
| 460504PRP-N022                 | 12                | 0.0                       | N/A                   | N/A |
| 460504PRP-N023                 | 6                 | -0.9                      | N/A                   | N/A |
| 460504PRP-N024                 | 7                 | -1.8                      | N/A                   | N/A |
| 460504PRP-N025                 | 7                 | 1.2                       | N/A                   | N/A |
| 460504PRP-N026                 | . 13              | -0.3                      | N/A                   | N/A |
| 460504PRP-N027                 | 13                | -1.8                      | N/A                   | N/A |
| 460504PRP-N028                 | 7                 | 4.3                       | N/A                   | N/A |
| 460504PRP-N029                 | 7                 | 5.8                       | N/A                   | N/A |

Printed On: 04/05/05 08:32 Page: 4 of 11

Description: Building 460, 2nd Floor Office Area Interior, all surfaces

### **Random Removable Surface Activity Data Sheet**

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |       |
|--------------------------------|-------------------|---------------------------|--------------------------|-------|
| 460504PRP-N030                 | 6                 | 0.6                       | N/A                      | N/A   |
| 460504PRP-N031                 | 6                 | -0.9                      | N/A                      | N/A   |
| 460504PRP-N032                 | 12                | 1.5                       | N/A                      | N/A   |
| 460504PRP-N033                 | 7                 | -1.8                      | N/A                      | N/A   |
| 460504PRP-N034                 | 12                | 0.0                       | N/A                      | . N/A |
| 460504PRP-N035                 | 7                 | 2.7                       | N/A                      | N/A   |
| 460504PRP-N036                 | 7                 | -0.3                      | N/A                      | N/A   |
| 460504PRP-N037                 | 12                | 0.0                       | N/A                      | N/A   |
| 460504PRP-N038                 | 7                 | 1.2                       | N/A                      | N/A   |
| 460504PRP-N039                 | 12                | 0.0                       | N/A                      | N/A   |
| 460504PRP-N040                 | 13                | 1.2                       | N/A                      | N/A   |
| 460504PRP-N041                 | 6                 | 0.6                       | N/A                      | N/A   |
| 460504PRP-N042                 | 6                 | 5.2                       | N/A                      | N/A   |
| 460504PRP-N043                 | 6                 | -0.9                      | N/A                      | N/A   |
| 460504PRP-N044                 | 6                 | -0.9                      | N/A                      | N/A   |
| 460504PRP-N045                 | 6                 | 0.6                       | N/A                      | N/A   |
| 460504PRP-N046                 | 12                | 0.0                       | N/A                      | N/A   |
| 460504PRP-N047                 | 6                 | -0.9                      | N/A                      | N/A   |
| 460504PRP-N048                 | 7                 | 4.3                       | N/A                      | N/A   |
| 460504PRP-N049                 | 13                | -0.3                      | N/A                      | N/A   |
| 460504PRP-N050                 | 7                 | -1.8                      | N/A                      | N/A   |
| 460504PRP-N051                 | 12                | 0.0                       | N/A                      | N/A   |
| 460504PRP-N052                 | 7                 | -0.3                      | N/A                      | N/A   |
| 460504PRP-N053                 | 13                | -1.8                      | N/A                      | N/A   |
| 460504PRP-N054                 | 6                 | -0.9                      | N/A                      | N/A   |
| 460504PRP-N055                 | 7                 | 5.8                       | N/A                      | N/A   |
| 460504PRP-N056                 | 13                | 2.7                       | N/A                      | N/A   |
| 460504PRP-N057                 | 7                 | 1.2                       | N/A                      | N/A   |
| 460504PRP-N058                 | 12                | 0.0                       | N/A                      | N/A   |

Printed On: 04/05/05 08:32

Page: 5 of 11

| Survey Area: 5 | Survey Unit: 460504 | Building: 460 |  |
|----------------|---------------------|---------------|--|
|                |                     |               |  |

Description: Building 460, 2nd Floor Office Area Interior, all surfaces

# **Random Removable Surface Activity Data Sheet**

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460504PRP-N059                 | 7                 | 1.2                       | N/A                      | N/A |
| 460504PRP-N060                 | 12                | 0.0                       | N/A                      | N/A |
| 460504PRP-N061                 | 13                | -1.8                      | N/A                      | N/A |
| 460504PRP-N062                 | 13                | -0.3                      | N/A                      | N/A |
| 460504PRP-N063                 | 7                 | 1.2                       | N/A                      | N/A |
| 460504PRP-N064                 | 13                | -0.3                      | N/A                      | N/A |

Printed On: 04/05/05 08:32

Page: 6 of 11

Description: Building 460, 2nd Floor Office Area Interior, all surfaces

## **Biased Removable Surface Activity Data Sheet**

| Biased Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460504PBP-N065                 | 6                 | 3.6                       | N/A                      | N/A |
| 460504PBP-N066                 | 7                 | -0.3                      | N/A                      | N/A |
| 460504PBP-N067                 | 6                 | -0.9                      | N/A                      | N/A |
| 460504PBP-N068                 | 7                 | 1.2                       | N/A                      | N/A |
| 460504PBP-N069                 | 7                 | 2.7                       | N/A                      | N/A |
| 460504PBP-N070                 | 13                | -1.8                      | N/A                      | N/A |
| 460504PBP-N071                 | 13                | -0.3                      | N/A                      | N/A |
| 460504PBP-N072                 | 12                | 3.0                       | N/A                      | N/A |
| 460504PBP-N073                 | 13                | 2.7                       | N/A                      | N/A |
| 460504PBP-N074                 | 12                | 0.0                       | N/A                      | N/A |
| 460504PBP-N075                 | 13                | -1.8                      | N/A                      | N/A |
| 460504PBP-N076                 | 12                | 3.0                       | N/A                      | N/A |
| 460504PBP-N077                 | 13                | 1.2                       | N/A                      | N/A |
| 460504PBP-N078                 | 12                | 1.5                       | N/A                      | N/A |
| 460504PBP-N079                 | 13                | -1.8                      | N/A                      | N/A |
| 460504PBP-N080                 | 12                | 0.0                       | N/A                      | N/A |
| 460504PBP-N081                 | 13                | -0.3                      | N/A                      | N/A |
| 460504PBP-N082                 | 12                | 0.0                       | N/A                      | N/A |
| 460504PBP-N083                 | 13                | 4.3                       | N/A                      | N/A |
| 460504PBP-N084                 | 12                | 0.0                       | N/A                      | N/A |
| 460504PBP-N085                 | 13                | 1.2                       | N/A                      | N/A |
| 460504PBP-N086                 | 12                | 1.5                       | N/A                      | N/A |
| 460504PBP-N087                 | 13                | -0.3                      | N/A                      | N/A |
| 460504PBP-N088                 | 12                | 0.0                       | N/A                      | N/A |
| 460504PBP-N089                 | 13                | 4.3                       | N/A                      | N/A |

Printed On: 04/05/05 08:32

Page: 7 of 11

Description: Building 460, 2nd Floor Office Area Interior, all surfaces

# Random/QC Total Surface Activity Data Sheet

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460504PRP-N001                 | 8                 | 8.7                       | N/A                      | N/A |
| 460504PRP-N002                 | 8                 | 15.2                      | N/A                      | N/A |
| 460504PRP-N003                 | 8                 | 27.3                      | N/A                      | N/A |
| 460504QRP-N003                 | 14                | 9.5                       | N/A                      | N/A |
| 460504PRP-N004                 | 1                 | 18.0                      | N/A                      | N/A |
| 460504PRP-N005                 | 4                 | 39.5                      | N/A                      | N/A |
| 460504QRP-N005                 | 14                | -14.0                     | N/A                      | N/A |
| 460504PRP-N006                 | 10                | -8.2                      | N/A                      | N/A |
| 460504PRP-N007                 | 4                 | 8.5                       | N/A                      | N/A |
| 460504PRP-N008                 | 8                 | -10.0                     | N/A                      | N/A |
| 460504PRP-N009                 | 1                 | 11.9                      | N/A                      | N/A |
| 460504PRP-N010                 | 5                 | -6.8                      | N/A                      | N/A |
| 460504PRP-N011                 | 5                 | 2.5                       | N/A                      | N/A |
| 460504PRP-N012                 | 9                 | 15.0                      | N/A                      | N/A |
| 460504PRP-N013                 | 1                 | 21.2                      | N/A                      | N/A |
| 460504PRP-N014                 | 1                 | 30.5                      | N/A                      | N/A |
| 460504PRP-N015                 | 9                 | 30.3                      | N/A                      | N/A |
| 460504PRP-N016                 | 8                 | 18.0                      | N/A                      | N/A |
| 460504PRP-N017                 | 1                 | 2.6                       | N/A                      | N/A |
| 460504PRP-N018                 | 8                 | 2.6                       | N/A                      | N/A |
| 460504PRP-N019                 | 8                 | 27.3                      | N/A                      | N/A |
| 460504PRP-N020                 | 8                 | 21.2                      | N/A                      | N/A |
| 460504PRP-N021                 | 9                 | 11.7                      | N/A                      | N/A |
| 460504PRP-N022                 | 9                 | 21.0                      | N/A                      | N/A |
| 460504PRP-N023                 | 1                 | 21.2                      | · N/A                    | N/A |
| 460504PRP-N024                 | 5                 | 2.5                       | N/A                      | N/A |
| 460504PRP-N025                 | 4                 | 64.1                      | N/A                      | N/A |

Printed On: 04/05/05 08:32

Page: 8 of 11

Description: Building 460, 2nd Floor Office Area Interior, all surfaces

# Random/QC Total Surface Activity Data Sheet

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |       |
|--------------------------------|-------------------|---------------------------|--------------------------|-------|
| 460504QRP-N025                 | 14                | 22.2                      | N/A                      | N/A   |
| 460504PRP-N026                 | 8                 | 8.7                       | N/A                      | N/A   |
| 460504PRP-N027                 | 9                 | 11.7                      | N/A                      | · N/A |
| 460504PRP-N028                 | 4                 | 33.5                      | N/A                      | N/A   |
| 460504PRP-N029                 | 4                 | 30.3                      | N/A                      | N/A   |
| 460504PRP-N030                 | 4                 | 17.8                      | N/A                      | N/A   |
| 460504PRP-N031                 | 1                 | 2.6                       | N/A                      | N/A   |
| 460504PRP-N032                 | 9                 | 21.0                      | N/A                      | N/A   |
| 460504PRP-N033                 | 9                 | -12.8                     | N/A                      | N/A   |
| 460504PRP-N034                 | 9                 | 39.5                      | N/A                      | N/A   |
| 460504PRP-N035                 | 1                 | 27.3                      | N/A                      | N/A   |
| 460504PRP-N036                 | 1                 | 33.8                      | N/A                      | N/A   |
| 460504PRP-N037                 | 9                 | 17.8                      | N/A                      | N/A   |
| 460504PRP-N038                 | 4                 | 21.0                      | N/A                      | N/A   |
| 460504PRP-N039                 | 8                 | 5.9                       | N/A                      | N/A   |
| 460504PRP-N040                 | 9                 | 33.5                      | N/A                      | N/A   |
| 460504PRP-N041                 | 2                 | 16.8                      | N/A                      | N/A   |
| 460504PRP-N042                 | 4                 | 36.3                      | N/A                      | N/A   |
| 460504PRP-N043                 | 1                 | 2.6                       | N/A                      | N/A   |
| 460504PRP-N044                 | 4                 | 30.3                      | N/A                      | N/A   |
| 460504PRP-N045                 | 1                 | -3.4                      | N/A                      | N/A   |
| 460504PRP-N046                 | 8                 | -10.0                     | N/A                      | N/A   |
| 460504PRP-N047                 | 1                 | 27.3                      | N/A                      | N/A   |
| 460504PRP-N048                 | 1                 | 2.6                       | N/A                      | N/A   |
| 460504PRP-N049                 | 9                 | 24.2                      | N/A                      | N/A   |
| 460504PRP-N050                 | 2                 | -1.3                      | N/A                      | N/A   |
| 460504PRP-N051                 | 10                | 36.3                      | N/A                      | N/A   |

Printed On: 04/05/05 08:32

Page: 9 of 11

Description: Building 460, 2nd Floor Office Area Interior, all surfaces

# Random/QC Total Surface Activity Data Sheet

| Random Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460504PRP-N052                 | 1                 | 11.9                      | N/A                      | N/A |
| 460504PRP-N053                 | 8                 | 11.9                      | N/A                      | N/A |
| 460504PRP-N054                 | 1                 | 8.7                       | N/A                      | N/A |
| 460504PRP-N055                 | 1                 | -3.4                      | N/A                      | N/A |
| 460504PRP-N056                 | 9                 | 5.7                       | N/A                      | N/A |
| 460504PRP-N057                 | 1                 | 21.2                      | N/A                      | N/A |
| 460504PRP-N058                 | 10                | 52.0                      | N/A                      | N/A |
| 460504PRP-N059                 | 4                 | 48.8                      | N/A                      | N/A |
| 460504QRP-N059                 | 14                | 6.8                       | N/A                      | N/A |
| 460504PRP-N060                 | 8                 | 24.5                      | N/A                      | N/A |
| 460504PRP-N061                 | 9                 | 21.0                      | N/A                      | N/A |
| 460504PRP-N062                 | 10                | 5.7                       | N/A                      | N/A |
| 460504PRP-N063                 | 4                 | 17.8                      | N/A                      | N/A |
| 460504PRP-N064                 | 9                 | 11.3                      | N/A                      | N/A |

Printed On: 04/05/05 08:32

Page: 10 of 11


| Survey Area: 5                | Survey Unit: 46                            | 0504 | Building: 460 |
|-------------------------------|--|------|---------------|
| Description: Building 460, 2r | d Floor Office Area Interior, all surfaces | s    |               |
|                               |  |      |               |


# **Biased Total Surface Activity Data Sheet**


| Biased Measurement<br>Location | Inst / RCT<br>Nbr | Net Alpha<br>(dpm/100cm²) | Net Beta<br>(dpm/100cm²) |     |
|--------------------------------|-------------------|---------------------------|--------------------------|-----|
| 460504PBP-N065                 | 1                 | -6.6                      | N/A                      | N/A |
| 460504PBP-N066                 | 1                 | 28.8                      | N/A                      | N/A |
| 460504PBP-N067                 | 1                 | 16.7                      | N/A                      | N/A |
| 460504PBP-N068                 | 5                 | 22.5                      | N/A                      | N/A |
| 460504PBP-N069                 | 5                 | 13.2                      | N/A                      | N/A |
| 460504PBP-N070                 | 8                 | 13.4                      | N/A                      | N/A |
| 460504PBP-N071                 | 8                 | 28.8                      | N/A                      | N/A |
| 460504PBP-N072                 | 8                 | 16.7                      | N/A                      | N/A |
| 460504PBP-N073                 | 8                 | 7.4                       | N/A                      | N/A |
| 460504PBP-N074                 | 8                 | 33.4                      | N/A                      | N/A |
| 460504PBP-N075                 | 10                | 47.0                      | N/A                      | N/A |
| 460504PBP-N076                 | 8                 | 32.0                      | N/A                      | N/A |
| 460504PBP-N077                 | 10                | 25.7                      | N/A                      | N/A |
| 460504PBP-N078                 | 8                 | 18.1                      | N/A                      | N/A |
| 460504PBP-N079                 | 9                 | 12.8                      | N/A                      | N/A |
| 460504PBP-N080                 | 8                 | 4.1                       | N/A                      | N/A |
| 460504PBP-N081                 | 10                | 13.2                      | N/A                      | N/A |
| 460504PBP-N082                 | 8                 | 10.2                      | N/A                      | N/A |
| 460504PBP-N083                 | 9                 | 4.0                       | N/A                      | N/A |
| 460504PBP-N084                 | 10                | 4.0                       | N/A                      | N/A |
| 460504PBP-N085                 | 8                 | 7.4                       | N/A                      | N/A |
| 460504PBP-N086                 | 10                | 25.7                      | N/A                      | N/A |
| 460504PBP-N087                 | 10                | 35.0                      | N/A                      | N/A |
| 460504PBP-N088                 | 10                | 28.5                      | N/A                      | N/A |
| 460504PBP-N089                 | 8                 | 4.1                       | N/A                      | N/A |

Printed On: 04/05/05 08:32

Page: 11 of 11







Survey Area: 5

Survey Unit: 460504

Classification: 3


Building: 460


Survey Unit Description: 460 Interior - 2nd Floor Offices

Total Area: 11,453 sq. m.

Total Floor Area: 4,207 sq. m.

**PAGE 2 OF 22** 





Survey Area: 5

Survey Unit: 460504


Classification: 3

Building: 460

Survey Unit Description: 460 Interior - 2nd Floor Offices
Total Area: 11,453 sq. m. Total Floor

Total Floor Area: 4,207 sq. m.

PAGE 3 OF 22



Survey Area: 5 Building: 460

Survey Unit: 460504


Classification: 3


Survey Unit Description: 460 Interior - 2nd Floor Offices

Total Area: 11,453 sq. m.

Total Floor Area: 4,207 sq. m.

**PAGE 4 OF 22** 





Survey Area: 5

Survey Unit: 460504


Classification: 3

Building: 460

Survey Unit Description: 460 Interior - 2nd Floor Offices Total Area: 11,453 sq. m. Total Floor

Total Floor Area: 4,207 sq. m.

**PAGE 5 OF 22** 



Survey Area: 5

Survey Unit: 460504

Classification: 3


Building: 460

Survey Unit Description: 460 Interior - 2nd Floor Offices

Total Area: 11,453 sq. m.

Total Floor Area: 4,207 sq. m.

PAGE 6 OF 22



Survey Area: 5

Survey Unit: 460504

Classification: 3


Building: 460

Survey Unit Description: 460 Interior - 2nd Floor Offices

Total Área: 11,453 sq. m.

Total Floor Area: 4,207 sq. m.

**PAGE 7 OF 22** 



#### **RLC FOR 460**

Survey Area: 5

Survey Unit: 460504

Classification: 3


Building: 460

Survey Unit Description: 460 Interior - 2nd Floor Offices

Total Area: 11,453 sq. m.

Total Floor Area: 4,207 sq. m.

PAGE 8 OF 22



Survey Area: 5

Survey Unit: 460504

Classification: 3

Building: 460

Survey Unit Description: 460 Interior- 2nd Floor Offices


Total Area: 11,453 sq. m.


Total Floor Area: 4,207 sq. m.


PAGE 9 OF 22



















Room 216














#### SURVEY MAP LEGEND




Smear, TSA & Sample Location

Area in Another Survey Unit

Neither the United States Government nor Kaiser Hill Co, nor DynCorp I&ET, nor any agency thereof, nor any of their employees, makes any warrany, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or terpresents that its use would not infringe privately owned rights. Open/Inaccessible Area

Scan Survey Information Survey Instrument ID #(s) & RCT ID #(s): 1-5, 8-11









Scan Area

1 inch = 18 feet 1 grid sq. = 1 sq. m. MAP ID: 03-0138\460\_sht9\_SC

Survey Area: 5 Building: 460


Survey Unit: 460504


Classification: 3


Survey Unit Description: 460 Interior - 2nd Floor Interior Total Area: 11,453 sq. m. Total Floo

Total Floor Area: 4,207 sq. m.

PAGE 10 OF 22







Survey Area: 5 Building: 460


Survey Unit: 460504


Classification: 3


Survey Unit Description: 460 Interior - 2nd Floor Offices Total Floor Area: 4,207 sq. m.

Total Area: 11,453 sq. m.

**PAGE 11 OF 22** 







Survey Area: 5

Survey Unit: 460504

Classification: 3

Building: 460


Survey Unit Description: 460 Interior - 2nd Floor Offices


Total Área: 11,453 sq. m.

Total Floor Area: 4,207 sq. m.

**PAGE 12 OF 22** 

#### Corridor 3





#### North Wall



#### East Wall



#### West Wall



#### South Wall



#### **SURVEY MAP LEGEND**

Smear & TSA Location


Smcar, TSA & Sample Location

Open/Inaccessible Area

Area in Another Survey Unit

Neither the United States Government nor Kaiser Hill Co. nor DynC orp I&ET. nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process ideoleed, or represents that its use would not infringe privately owned rights.

Scan Survey Information Survey Instrument ID #(s) & RCT ID #(s): 1-5, 8-11



U.S. Department of Energy Rocky Flats Environmental Technology Site Prepared for:

Prepared by: GIS Dept. 303-966-7707



MAP ID: 03-0138\460\_sht12\_SC

Scan Area

Survey Area: 5 Building: 460 Survey Unit: 460504


Classification: 3


Survey Unit Description: 460 Interior - 2nd Floor Offices


Total Área: 11,453 sq. m.

Total Floor Area: 4,207 sq. m.

PAGE 13 OF 22







Survey Area: 5

Survey Unit: 460504

Classification: 3


Building: 460


Survey Unit Description: 460 Interior - 2nd Floor Offices

Total Area: 11,453 sq. m.


Total Floor Area: 4,207 sq. m.

PAGE 14 OF 22







Ceiling (inverted)




East Wall





North Wall




Survey Area: 5

Survey Unit: 460504

Classification: 3


Building: 460

Survey Unit Description: 460 Interior - 2nd Floor Offices Total Area: 11,453 sq. m. Total Floor Total Floor Area: 4,207 sq. m.









# **RLC FOR B460** Survey Unit: 460504 Classification: 3 Survey Area: 5 Building: 460 Survey Unit Description: 460 Interior - 2nd Floor Offices Total Floor Area: 4,207 sq. m. Total Area: 11,453 sq. m. PAGE 16 OF 22 Room 229 B Maintenance Room Wall 1 Wall 1 Wall 2 Wall 4 Wall 3 Ceiling (inverted) Wall 3 Room Service Room Entryway Elevator Wall 1 Wall 1 FICE. Wall 3 Ceiling (inverted) Wall 3 Room 205 Room 204 Wall 2 Wall 2 Wall 2 Wall 2 Scan Area U.S. Department of Energy Neither the United States Government nor Kaiser Hill Co **SURVEY MAP LEGEND** Neither the United States Government nor Kaiser Fills Co-nor DynCop I BET. nor any agency thereof, nor any of their employees, makes any warranty: express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. N FEET Rocky Flats Environmental Technology Site Prepared by: GIS Dept. 303-966-7707 Prepared for: Smear, TSA & Sample Location **METERS** Open/Inaccessible Area CH2MHILL Scan Survey Information Area in Another Survey Unit Communications Group

1 inch = 18 feet | 1 grid sq. = 1 sq. m.

MAP ID: 03-0138/460\_sht16\_SC

Mar. 24, 2005

Survey Instrument ID #(s) & RCT ID #(s):

1-5, 8-11

Survey Area: 5

Survey Unit: 460504

Classification: 3


Building: 460


Survey Unit Description: 460 Interior - 2nd Floor Offices

Total Area: 11,453 sq. m.

Total Floor Area: 4,207 sq. m.

PAGE 17 OF 22





Survey Area: 5 Building: 460 Survey Unit: 460504


Classification: 3

Survey Unit Description: 460 Interior - 2nd Flooor Interior

Total Area: 11,453 sq. m.

Total Floor Area: 4,207 sq. m.

PAGE 18 OF 22



Survey Area: 5 Building: 460

Survey Unit: 460504

Classification: 3


Survey Unit Description: 460 Interior - 2nd Floor Offices


Total Area: 11,453 sq. m.


Total Floor Area: 4,207 sq. m.

PAGE 19 OF 22

#### Room 201







Scan Area U.S. Department of Energy Neither the United States Government nor Kaiser Hill Co SURVEY MAP LEGEND Notifier the United States Obsermment for Kaiser Fill Co-mot DynCorp I&ET. not any agency thereof, no any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. FEET 40 Rocky Flats Environmental Technology Site Smear & TSA Location Prepared by: GIS Dept. 303-966-7707 Prepared for: Smear, TSA & Sample Location Open/Inaccessible Area **METERS** 10 CH2MHILL Scan Survey Information Area in Another Survey Unit Communications Group Survey Instrument ID #(s) & RCT ID #(s): 1 inch = 30 feet 1 grid sq. = 1 sq. m. 1-5, 8-11 MAP ID: 03-0138\460\_sht19\_SC Mar. 24, 2005

Survey Area: 5 Building: 460

Survey Unit: 460504


Classification: 3

Survey Unit Description: 460 Interior -2nd Floor Offices

Total Area: 11,453 sq. m.

Total Floor Area: 4,207 sq. m.

PAGE 20 OF



Survey Area: 5

Survey Unit: 460504

Classification: 3


Building: 460

Survey Unit Description: 460 Interior - 2nd Floor Offices Total Area: 11,453 sq. m. Total Floor

Total Floor Area: 4,207 sq. m.

PAGE 21 OF 22

# Room 227 (Ceiling Inverted)





#### **SURVEY MAP LEGEND**

- Smcar & TSA Location
- Smear, TSA & Sample Location
- Open/Inaccessible Area
- Area in Another Survey Unit


Neither the United States Government on Kaiser From Co. nor DynCorp Idel. To not any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights.

Survey Instrument ID #(s) & RCT ID #(s):

Scan Survey Information

1-5, 8-11





1 inch = 36 feet 1 grid sq. = 1 sq. m.

Rocky Flats Environmental Technology Site

U.S. Department of Energy

Prepared by: GIS Dept. 303-966-7707

Prepared for:



KAISER HILL Communications Group

MAP ID: 03-0138\460\_sht21\_SC

Mar. 24, 2005

Survey Area: 5

Survey Unit: 460504

Classification: 3

Building: 460


Survey Unit Description: 460 Interior - 2nd Floor Offices

Total Area: 11,453 sq. m.


Total Floor Area: 4,207 sq. m.

PAGE 22 OF 22

#### Room 226



#### Room 226A



Scan Area


#### **SURVEY MAP LEGEND**

- Smear & TSA Location
- Smear, TSA & Sample Location
- Open/Inaccessible Area
- Area in Another Survey Unit

nor DynCorp I&ET, nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information,

pparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights.

Scan Survey Information Survey Instrument ID #(s) & RCT ID #(s): 1-5, 8-11



1 inch = 36 feet 1 grid sq. = 1 sq. m.

Rocky Flats Environmental Technology Site Prepared by: GIS Dept. 303-966-7707

U.S. Department of Energy





MAP ID: 03-0138\460\_sht22\_SC


Prepared for:


# ATTACHMENT D

# Chemical Data Summaries and Sample Maps









# **Asbestos Data Summary**

# $Building\ 460-RIN\ 04Z0218$


| Sample Number      | Map<br>Location<br>Point | Room  | Material Sampled & Location             | Analytical Results |
|--------------------|--------------------------|---|---|--------------------|
| 460-10282003-9-501 | 1                        | Room 116 - 1st Floor north/south hall             | Paint and plaster over cinderblock wall | Non-Detect         |
| 460-10282003-9-502 | 2                        | Corridor 2 –<br>Floor, stairwell,<br>east side    | Paint and plaster over cinderblock wall | Non-Detect         |
| 460-10283002-9-503 | 3                        | Room 205 - 2 <sup>nd</sup> Floor north/south hall | Paint and plaster over cinderblock wall | Non-Detect         |

Page 1 of 1

# **CHEMICAL SAMPLE MAP**

#### Building 460 Asbestos


PAGE 1 OF 3




# **CHEMICAL SAMPLE MAP**

#### Building 460 1st Floor Asbestos

PAGE 2 OF 3






# **CHEMICAL SAMPLE MAP**

Building 460 Asbestos

PAGE 3 OF 3



# Beryllium Data Summary Building 460 – RIN 05D0695

| Sample Number        | Map Survey Point Location | Sample Location                         | Result (ug/100 cm <sup>2</sup> )      |
|----------------------|---------------------------|---|---------------------------------------|
| 460-030720005-00-001 | 1                         | Floor                                   | < 0.1                                 |
| 460-030720005-00-001 | 2                         | Overhead ventilation duct               | < 0.1                                 |
| 460-030720005-00-002 | 3                         | Floor                                   | < 0.1                                 |
| 460-030720005-00-003 | 4                         | Overhead cross beam                     | < 0.1                                 |
| 460-030720005-00-004 | 5                         | 1                                       | < 0.1                                 |
|                      | 6                         | Overhead, top of cross beam             |                                       |
| 460-030720005-00-006 | 1                         | Overhead, top of cross beam             | < 0.1                                 |
| 460-030720005-00-007 | 7                         | Floor                                   | < 0.1                                 |
| 460-030720005-00-008 | 8                         | Floor                                   | < 0.1                                 |
| 460-030720005-00-009 | 9                         | Top of condensate line                  | < 0.1                                 |
| 460-030720005-00-010 | 10                        | Overhead, top of cross beam             | < 0.1                                 |
| 460-030720005-00-011 | 11                        | Top of pipe at ceiling                  | < 0.1                                 |
| 460-030720005-00-012 | 12                        | Top of supply duct, overhead            | < 0.1                                 |
| 460-030720005-00-013 | 13                        | Floor                                   | < 0.1                                 |
| 460-030720005-00-014 | 14                        | Fan louvers, overhead                   | < 0.1                                 |
| 460-030720005-00-015 | 15                        | Top of light fixture, overhead          | < 0.1                                 |
| 460-030720005-00-016 | 16                        | Top of fire water line, overhead        | < 0.1                                 |
| 460-030720005-00-017 | 17                        | Top of exhaust duct, overhead           | < 0.1                                 |
| 460-030720005-00-018 | 18                        | Floor                                   | < 0.1                                 |
| 460-030720005-00-019 | 19                        | Floor                                   | < 0.1                                 |
| 460-030720005-00-020 | 20                        | Top of light fixture, overhead          | < 0.1                                 |
| 460-030720005-00-021 | 21                        | Floor                                   | < 0.1                                 |
| 460-030720005-00-022 | 22                        | Top of fire pipe near ceiling           | < 0.1                                 |
| 460-030720005-00-023 | 23                        | Overhead, top of cross beam             | < 0.1                                 |
| 460-030720005-00-024 | 24                        | Floor                                   | < 0.1                                 |
| 460-030720005-00-025 | 25                        | Floor                                   | < 0.1                                 |
| 460-030720005-00-026 | 26                        | Top of duct, overhead                   | < 0.1                                 |
| 460-030720005-00-027 | 27                        | Floor                                   | < 0.1                                 |
| 460-030720005-00-028 | 28                        | Floor                                   | < 0.1                                 |
| 460-030720005-00-029 | 29                        | Floor                                   | < 0.1                                 |
| 460-030720005-00-030 | 30                        | Top of fire pipe, overhead              | < 0.1                                 |
| 460-030720005-00-031 | 31                        | Ceiling                                 | < 0.1                                 |
| 460-030720005-00-032 | 32                        | Floor                                   | < 0.1                                 |
| 460-030720005-00-033 | 33                        | Floor                                   | < 0.1                                 |
| 460-030720005-00-034 | 34                        | Ventilation louvers, overhead           | < 0.1                                 |
| 460-030720005-00-035 | 35                        | Floor                                   | < 0.1                                 |
| 460-030720005-00-036 | 36                        | Top of pipe, overhead                   | < 0.1                                 |
| 460-030720005-00-037 | 37                        | On supply ventilation ducting, overhead | < 0.1                                 |
| 460-030720005-00-038 | 38                        | Floor                                   | < 0.1                                 |
| 460-030720005-00-039 | 39                        | Top of pipe near ceiling                | < 0.1                                 |
| 460-030720005-00-040 | 40                        | Floor                                   | < 0.1                                 |
| 460-030720005-00-041 | 41                        | Floor                                   | < 0.1                                 |
| 460-030720005-00-042 | 42                        | Top of pipe, overhead                   | < 0.1                                 |
| 460-030720005-00-042 | 43                        | Floor                                   | < 0.1                                 |
| 460-030720005-00-044 | 44                        | Top of I-beam, overhead                 | < 0.1                                 |
| 460-030720005-00-045 | 45                        | Top of center beam, overhead            | < 0.1                                 |
| 460-030720005-00-045 | 46                        | Top of false ceiling                    | < 0.1                                 |
| 400-030/20003-00-046 | 40                        | Top of faise centing                    | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ |


Page 1 of 3


| Sample Number                                | Map Survey | Sample Location                            | Result                  |
|--|------------|--|-------------------------|
|  | Point      | Campio Bodanon                             | $(ug/100 \text{ cm}^2)$ |
|  | Location   |  | (8                      |
| 460-030720005-00-047                         | 47         | Top of light fixture, overhead             | < 0.1                   |
| 460-030720005-00-048                         | 48         | Top of exhaust duct in overhead            | < 0.1                   |
| 460-030720005-00-049                         | 49         | Top of false ceiling                       | < 0.1                   |
| 460-030720005-00-050                         | 50         | Room 149 on ceiling pipe                   | < 0.1                   |
| 460-030720005-00-051                         | 51         | Top of electrical box                      | < 0.1                   |
| 460-030720005-00-052                         | 52         | Top of pipe, overhead                      | < 0.1                   |
| 460-030720005-00-053                         | 53         | Top of pipe, overhead                      | < 0.1                   |
| 460-030720005-00-054                         | 54         | Floor                                      | < 0.1                   |
| 460-030720005-00-055                         | 55         | In pan under ceiling vent                  | < 0.1                   |
| 460-030720005-00-056                         | 56         | Ceiling cross beam                         | < 0.1                   |
| 460-030720005-00-057                         | 57         | Floor                                      | < 0.1                   |
| 460-030720005-00-058                         | 58         | Cross bracket, overhead                    | < 0.1                   |
| 460-030720005-00-059                         | 59         | Floor                                      | < 0.1                   |
| 460-030720005-00-060                         | 60         | On pipe                                    | < 0.1                   |
| 460-030720005-00-061                         | 61         | On top of ventilation duct, overhead       | < 0.1                   |
| 460-030720005-00-062                         | 62         | On top of ventilation duct, overhead       | < 0.1                   |
| 460-030720005-00-063                         | 63         | On top of cross beam, overhead             | < 0.1                   |
| 460-030720005-00-064                         | 64         | Top of heater                              | < 0.1                   |
| 460-030720005-00-065                         | 65         | Floor                                      | < 0.1                   |
| 460-030720005-00-066                         | 66         | Floor                                      | < 0.1                   |
| 460-030720005-00-067                         | 67         | On top of light fixture, overhead          | < 0.1                   |
| 460-030720005-00-068                         | 68         | On top of cross beam, overhead             | < 0.1                   |
| 460-030720005-00-069                         | 69         | On top of ventilation duct, overhead       | < 0.1                   |
| 460-030720005-00-070                         | 70         | On ceiling                                 | < 0.1                   |
| 460-030720005-00-071<br>460-030720005-00-072 | 71 72      | On top of light fixture, overhead          | < 0.1                   |
| 460-030720005-00-072                         | 73         | Top of false ceiling Top of electrical box | < 0.1                   |
| 460-030720005-00-074                         | 74         | Top of false ceiling                       | < 0.1                   |
| 460-030720005-00-075                         | 75         | Inside fan                                 | < 0.1                   |
| 460-030720005-00-076                         | 76         | Top of electrical box                      | < 0.1                   |
| 460-030720005-00-077                         | 77         | Top of electrical box                      | < 0.1                   |
| 460-030720005-00-078                         | 78         | On ventilation louver, overhead            | < 0.1                   |
| 460-030720005-00-079                         | 79         | On ventilation louver, overhead            | < 0.1                   |
| 460-030720005-00-080                         | 80         | On ventilation louver, overhead            | < 0.1                   |
| 460-030720005-00-081                         | 81         | On ventilation louver, overhead            | < 0.1                   |
| 460-030720005-00-082                         | 82         | On ventilation louver, overhead            | < 0.1                   |
| 460-030720005-00-083                         | 83         | On ventilation louver, overhead            | < 0.1                   |
| 460-030720005-00-084                         | 84         | On top of light fixture, overhead          | < 0.1                   |
| 460-030720005-00-085                         | 85         | On top of light fixture, overhead          | < 0.1                   |
| 460-030720005-00-086                         | 86         | On ventilation louver, overhead            | < 0.1                   |
| 460-030720005-00-087                         | 87         | On ventilation louver, overhead            | < 0.1                   |
| 460-030720005-00-088                         | 88         | On ventilation louver, overhead            | < 0.1                   |
| 460-030720005-00-089                         | 89         | On ventilation louver, overhead            | < 0.1                   |
| 460-030720005-00-090                         | 90         | Top of electrical box                      | < 0.1                   |
| 460-030720005-00-101                         | 101        | Inside supply ventilation duct, overhead   | < 0.1                   |
| 460-030720005-00-102                         | 102        | Inside supply ventilation duct, overhead   | < 0.1                   |
| 460-030720005-00-103                         | 103        | Inside supply ventilation duct, overhead   | < 0.1                   |
| 460-030720005-00-104                         | 104        | Inside supply ventilation duct, overhead   | < 0.1                   |
| 460-030720005-00-105                         | 105        | Inside supply ventilation duct, overhead   | < 0.1                   |
| 460-030720005-00-106                         | 106        | Inside supply ventilation duct, overhead   | < 0.1                   |
| 460-030720005-00-107                         | 107        | Inside supply ventilation duct, overhead   | < 0.1                   |


| Sample Number        | Map Survey | Sample Location                                     | Result                  |
|----------------------|------------|---|-------------------------|
| ·                    | Point      |   | $(ug/100 \text{ cm}^2)$ |
|                      | Location   |   |                         |
| 460-030720005-00-108 | 108        | Inside supply ventilation duct, overhead            | < 0.1                   |
| 460-030720005-00-109 | 109        | Inside supply ventilation duct, overhead            | < 0.1                   |
| 460-030720005-00-110 | 110        | Inside supply ventilation duct, overhead            | < 0.1                   |
| 460-030720005-00-111 | 111        | Inside supply ventilation duct, overhead            | < 0.1                   |
| 460-030720005-00-112 | 112        | Inside supply ventilation duct, overhead            | < 0.1                   |
| 460-030720005-00-113 | 113        | Inside supply ventilation duct, overhead            | < 0.1                   |
| 460-030720005-00-114 | 114        | Inside supply ventilation duct, overhead            | < 0.1                   |
| 460-030720005-00-115 | 115        | Inside supply ventilation duct, overhead            | < 0.1                   |
| 460-030720005-00-116 | 116        | Inside supply ventilation duct, overhead            | < 0.1                   |
| 460-030720005-00-117 | 117        | Inside supply ventilation duct, overhead            | < 0.1                   |
| 460-030720005-00-118 | 118        | Inside supply ventilation duct, overhead            | < 0.1                   |
| 460-030720005-00-119 | 119        | Inside supply ventilation duct, overhead            | < 0.1                   |
| 460-030720005-00-120 | 120        | Inside supply ventilation duct, overhead            | < 0.1                   |
| 460-030720005-00-121 | 121        | Inside supply ventilation duct, overhead            | < 0.1                   |
| 460-030720005-00-122 | 122        | Inside exhaust ventilation duct, overhead           | < 0.1                   |
| 460-030720005-00-123 | 123        | Inside exhaust ventilation duct, overhead           | < 0.1                   |
| 460-030720005-00-124 | 124        | Inside exhaust ventilation duct, overhead           | < 0.1                   |
| 460-030720005-00-125 | 125        | Inside exhaust ventilation duct, overhead           | < 0.1                   |
| 460-030720005-00-126 | 126        | Inside exhaust ventilation duct, overhead           | < 0.1                   |
| 460-030720005-00-127 | 127        | Inside exhaust ventilation duct, overhead           | < 0.1                   |
| 460-030720005-00-128 | 128        | Inside 2 <sup>nd</sup> stage exhaust plenum, Rm 226 | < 0.1                   |
| 460-030720005-00-129 | 129        | Inside 1 <sup>st</sup> stage exhaust plenum, Rm 226 | < 0.1                   |
| 460-030720005-00-130 | 130        | Inside exhaust ventilation duct, overhead,          | < 0.1                   |
|                      |            | Rm 226  |                         |
| 460-030720005-00-132 | 132        | Inside supply ventilation duct, overhead,           | < 0.1                   |
|                      |            | Rm 226  |                         |
| 460-030720005-00-133 | 133        | Inside fume scrubber, Room 226                      | < 0.1                   |
| 460-030720005-00-134 | 134        | Auxiliary Zone 3 Ventilation Unit, Rm               | < 0.1                   |
|                      |            | 226   |                         |
| 460-030720005-00-135 | 135        | Top of IDEC #6 Ventilation Unit, Rm                 | < 0.1                   |
|                      |            | 226   |                         |
| 460-030720005-00-136 | 136        | Inside IDEC #4 Ventilation Unit, Rm 226             | < 0.1                   |

#### Footnotes:

- 1. Samples 1-75 were randomly generated. Samples 76-90 and 101-136 are biased sample locations.
- 2. Samples 101-136 were collected inside the supply and exhaust ventilation systems.
- 3. Sample numbers 91-100 were not used.
- 4. Sample number 460-030720005-00-131 was a QC blank.







| STOLLER   |                                 | IN OR CUCTODA/CAMPI                       | E ANAL VOIC DECLIECT   | 0020332m001   | Page 1 of 1              |
|---|---------------------------------|---|--|---|--------------------------|
| RFETS   | CHA                             | IN OF CUSTODY/SAMPI                       | LE ANALYSIS REQUEST  | ¶05Z0992#001  |                          |
| Sampler (s) Vir Dhuy 18 Sa  | (time/date)                     | Contact/Requester PODOLSKY, STEWART       | / MYERS, KIM   | Telephone No.<br>7624 / 7106  |                          |
| RIN ()<br>05Z0992   | J                               | Sampling Origin B460                      |  | Purchase Order/Charge Code  |                          |
| Project Title   |                                 | Logbook No. QQ 1/7                        | - 1/2  | Ice Chest No. Temp.   | 2.8                      |
| B460 CONCRETE CORES To (Lab)  | <u> </u>                        | Method of Shipment                        | ip van   | Bill of Lading/Air Bill No.   |                          |
| Severn-Trent Denver   |                                 | Related COC (if any)                      | Deliverey  | N/A   |                          |
| Protocol ST- ASI4-SOP-C   | 201                             | Related COC (II ally)                     | 2  | 050316-K155-002   |                          |
| POSSIBLE SAMPLE HAZARDS/REMARK Are acid preserved samples DOT hazardous per 40 Cl Are other known hazardous substances present? YES | R Part 136.3 Table U? YES       | NO)                                       | SCREENING SPECIAL INSTRU                                     |   |                          |
| Bottle No.   Customer   Number  | Matrix Date/Ti                  | 1   | ntainer  <br>:e/type)   [Field-Filter                        | Sample Analysis ed] LIC (Method Title) [TAT]/{Parameter List}                             | Preservative;<br>Packing |
| 05Z0992 Tank 4 (from -001.001 Front were  | SOLID 3/28/05/                  | / B460 1-S                                | AMPLE MET-A-021 (METALS P/G {See Item 1}                     | 6010/6010B)[14dF]   | None;<br>None            |
| 05Z0992 Tank 5 (Floor)<br>-002.001 Front area   | SOLID                           | B460 1-S                                  | AMPLE MET-A-021 (METALS P/G {See Item I}                     | 6010/6010B) [14dF]  | None;<br>None            |
| 05Z0992 Floor behind  | SOLID                           | 45 B460 1-S                               | AMPLE MET-A-021 (METALS P/G {See [tem 1}                     |   | None;<br>None            |
| TO THE RAPIT A COLL ALTIMOMINAL AND   | TMONIV. ADSENIC: BAR            | HM- BERVII HM- BORON- CA                  | DMIUM; CALCIUM; CHROMIUM; C<br>DIUM; STRONTIUM; THALLIUM; TI | COBALT; COPPER; IRON; LEAD; LITHIUM; MAGNESIUM; M<br>N; TITANIUM; URANIUM; VANADIUM; ZINC | ANGANESE;                |
|   | Date/Time: Received By:         | , 3/28/05 14                              | te/Time Relinquished By:                                     | Date/Time Received By:  728/05 1450 Peff 4 728/05  Date/Time Received By:                 | Date/Time                |
| Relinquished By:  Relinquished By:  | Date/Time Received By:          | 3.29.05 4                                 |  | Date/Time Received By:  | Date/Time                |
| FINAL SAMPLE Disposal Method (e.g., retu  | med to customer, disposed of pe | r lab procedure, used in analytical proce | ss) Disposed By  | Date/Time COC printed: 03/21/05 06:13 (Ve   | sion:coc_r22.rpt)        |



## Total Metals Analysis Data Sheet

Lab Name:

STL DENVER

Client Sample ID:

05Z0992-001.001

Lot/SDG Number:

05Z0992

Lab WorkOrder:

G69AD

Matrix:

SOIL

Lab Sample ID:

D5C290333-001

% Moisture:

Date/Time Collected:

03/28/05 9:50

Units:

MG/KG

Date/Time Received:

| CAS No.   | Analyte                  | Conc. | Q | RL   | Dilution<br>Factor | QC Batch<br>ID | Method | Instrument<br>ID | Analysis<br>Date | Analysis<br>Time |
|-----------|--------------------------|-------|---|------|--------------------|----------------|--------|------------------|------------------|------------------|
| 7429-90-5 | Aluminum                 | 11000 |   | 40   | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 13:39            |
| 7440-36-0 | Antimony                 | 0.37  | U | 12   | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:30            |
| 7440-38-2 | Arsenic                  | 2.9   |   | 2.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:30            |
| 7440-39-3 | Barium                   | 160   |   | 20   | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:30            |
| 7440-41-7 | Beryllium                | 0.44  |   | 0.20 | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 13:39            |
| 7440-42-8 | Boron                    | 8.2   |   | 1.5  | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 13:39            |
| 7440-43-9 | Cadmium                  | 0.039 | υ | 1.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:30            |
| 7440-70-2 | Calcium                  | 60000 |   | 1000 | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 13:39            |
| 7440-47-3 | Chromium                 | 58    |   | 0.40 | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:30            |
| 7440-48-4 | Cobalt                   | 74    |   | 10   | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:30            |
| 7440-50-8 | Copper                   | 16    | : | 5.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:30            |
| 7439-89-6 | lron                     | 14000 |   | 20   | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 13:39            |
| 7439-92-1 | Lead                     | 190   | _ | 0.60 | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:30            |
| 7439-93-2 | Lithium                  | 9.6   | В | 20   | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 13:39            |
| 7439-95-4 | Magnesium                | 2700  |   | 1000 | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 13:39            |
| 7439-96-5 | Manganese                | 240   |   | 3.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:30            |
| 7439-98-7 | Molybdenum               | 2.7   | В | 6.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:30            |
| 7440-02-0 | Nickel                   | 12    |   | 8.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:30            |
| 7440-09-7 | Potassium                | 3900  |   | 1000 | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 13:39            |
| 7782-49-2 | Selenium                 | 0.39  | U | 1.0  | . 1                | 5088571        | 6010B  | 016              | 4/1/2005         | 13:30            |
| 7631-86-9 | Silica as SiO2, Dissolve | 570   |   | 5.0  | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 13:39            |
| 7440-22-4 | Silver                   | 7.5   |   | 1.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:30            |
| 7440-23-5 | Sodium                   | 1100  |   | 1000 | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 13:39            |
| 7440-24-6 | Strontium                | 240   |   | 40   | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:30            |
| 7440-28-0 | Thallium                 | 0.67  | В | 2.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:30            |
| 7440-31-5 | Tin                      | 2.7   | В | 40   | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:30            |
| 7440-32-6 | Titanium                 | 590   |   | 0.20 | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 13:39            |
| 11-09-6   | Uranium                  | 1.6   | υ | 40   | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:30            |
| 7440-62-2 | Vanadium                 | 72    |   | 8.0  | 1                  | 5088571        | ł      | 016              | 4/1/2005         |                  |



#### **Total Metals Analysis Data Sheet**

Lab Name:

STL DENVER

Client Sample 1D:

 $\underline{05Z0992\text{-}001.001}$ 

Lot/SDG Number:

05Z0992

Lab WorkOrder:

<u>G69AD</u>

Matrix:

Units:

SOIL

MG/KG

Lab Sample ID:

D5C290333-001

% Moisture:

03/28/05 9:50

Date/Time Collected:

Date/Time Received:

| CAS No.   | Analyte | Conc. | · Q | RL  | Dilution<br>Factor | QC Batch<br>ID | Method | Instrument<br>ID | Analysis<br>Date | Analysis<br>Time |
|-----------|---------|-------|-----|-----|--------------------|----------------|--------|------------------|------------------|------------------|
| 7440-66-6 | Zinc    | 190   |     | 4.0 | 1                  | 5088571        | 1      | 002              | 4/1/2005         | 13:39            |

υ Result is less than the instrument detection limit (IDL).

В Estimated result. Result is less than RL and greater than or equal to the IDL.



#### **Total Metals Analysis Data Sheet**

Lab Name:

STL DENVER

Client Sample ID:

05Z0992-001.001

Lot/SDG Number: .

05Z0992

Lab WorkOrder:

G69AD

Matrix:

SOIL

Lab Sample ID:

D5C290333-001

% Moisture:

Date/Time Collected:

03/28/05 9:50

Units:

MG/KG

Date/Time Received:

| CAS No.   | Analyte   | Conc.  | Q | RL   | Dilution<br>Factor | QC Batch<br>ID | Method | Instrument<br>ID | Analysis<br>Date | Analysis<br>Time |
|-----------|-----------|--------|---|------|--------------------|----------------|--------|------------------|------------------|------------------|
| 7439-97-6 | Mercury . | 0.0021 |   | 0.20 | 1                  | 5089171        | 7471A  | 019              | 4/4/2005         | 17:25            |

U Result is less than the instrument detection limit (IDL).



## **Total Metals Analysis Data Sheet**

Lab Name:

STL DENVER

Client Sample ID:

 $\underline{05Z0992\text{-}002.001}$ 

Lot/SDG Number:

05Z0992

Lab WorkOrder:

G69AH

Matrix:

<u>SOIL</u>

Lab Sample ID:

D5C290333-002

% Moisture:

Date/Time Collected:

03/28/05 10:25

Units:

MG/KG

Date/Time Received:

| CAS No.   | Analyte                  | Conc.  | Q | RL   | Dilution<br>Factor | QC Batch<br>ID | Method | Instrument<br>ID | Analysis<br>Date | Analysis<br>Time |
|-----------|--------------------------|--------|---|------|--------------------|----------------|--------|------------------|------------------|------------------|
| 7429-90-5 | Aluminum                 | 8800   |   | 40   | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:04            |
| 7440-36-0 | Antimony                 | 0.41   | В | 12   | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:55            |
| 7440-38-2 | Arsenic                  | 3.5    |   | 2.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:55            |
| 7440-39-3 | Barium                   | 130    |   | 20   | 1.                 | 5088571        | 6010B  | 016              | 4/1/2005         | 13:55            |
| 7440-41-7 | Beryllium                | 0.42   |   | 0.20 | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:04            |
| 7440-42-8 | Boron                    | 12     |   | 1.5  | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:04            |
| 7440-43-9 | Cadmium                  | 0.16   | В | 1.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:55            |
| 7440-70-2 | Calcium                  | 100000 |   | 1000 | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:04            |
| 7440-47-3 | Chromium                 | 50     |   | 0.40 | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:55            |
| 7440-48-4 | Cobalt                   | 3.9    | В | 10   | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:55            |
| 7440-50-8 | Copper                   | 15     |   | 5.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:55            |
| 7439-89-6 | Iron                     | 8300   |   | 20   | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:04            |
| 7439-92-1 | Lead                     | 150    |   | 0.60 | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:55            |
| 7439-93-2 | Lithium                  | 8.5    | В | 20   | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:04            |
| 7439-95-4 | Magnesium .              | 3000   |   | 1000 | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:04            |
| 7439-96-5 | Manganese                | 230    |   | 3.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:55            |
| 7439-98-7 | Molybdenum               | 4.0    | В | 6.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:55            |
| 7440-02-0 | Nickel                   | 14     |   | 8.0  | . 1                | 5088571        | 6010B  | 016              | 4/1/2005         | 13:55            |
| 7440-09-7 | Potassium                | 3400   |   | 1000 | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:04            |
| 7782-49-2 | Selenium                 | 0.39   | U | 1.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:55            |
| 7631-86-9 | Silica as SiO2, Dissolve | 470    |   | 5.0  | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:04            |
| 7440-22-4 | Silver                   | 0.050  | U | 1.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:55            |
| 7440-23-5 | Sodium                   | 1100   |   | 1000 | ĵ                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:04            |
| 7440-24-6 | Strontium                | 380    |   | 40   | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:55            |
| 7440-28-0 | Thallium                 | 0.69   | В | 2.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:55            |
| 7440-31-5 | Tin                      | 2.4    | В | 40   | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:55            |
| 7440-32-6 | Titanium                 | 550    |   | 0.20 | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:04            |
| 11-09-6   | Uranium                  | 1.6    | U | 40   | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 13:55            |
| 7440-62-2 | Vanadium                 | 82     |   | 8.0  | 1                  | 5088571        |        | 016              | 4/1/2005         |                  |



# Total Metals Analysis Data Sheet

Lab Name:

STL DENVER

Client Sample ID:

05Z0992-002.001

Lot/SDG Number:

05Z0992

Lab WorkOrder:

<u>G69AH</u>

Matrix:

SOIL

Lab Sample ID:

D5C290333-002

% Moisture:

¥

Date/Time Collected:

03/28/05 10:25

Units:

MG/KG

Date/Time Received:

| CAS No.   | Analyte | Conc. | Q | RL  | Dilution<br>Factor | QC Batch<br>ID | Method | Instrument<br>ID | Analysis<br>Date | Analysis<br>Time |
|-----------|---------|-------|---|-----|--------------------|----------------|--------|------------------|------------------|------------------|
| 7440-66-6 | Zinc    | 140   |   | 4.0 |                    | 5088571        |        | 002              | 4/1/2005         | 14:04            |

U Result is less than the instrument detection limit (IDL).

B Estimated result. Result is less than RL and greater than or equal to the IDL.



#### **Total Metals Analysis Data Sheet**

Lab Name:

STL DENVER

Client Sample ID:

05Z0992-002.001

Lot/SDG Number:

05Z0992

Lab WorkOrder:

<u>G69AH</u>

Matrix:

SOIL

Lab Sample ID:

D5C290333-002

% Moisture:

Date/Time Collected:

03/28/05 10:25

Units:

MG/KG

Date/Time Received:

| CAS No.   | Analyte | Conc.  | Q | RL   | Dilution<br>Factor | QC Batch<br>ID | Method | Instrument<br>ID | Analysis<br>Date | Analysis<br>Time |
|-----------|---------|--------|---|------|--------------------|----------------|--------|------------------|------------------|------------------|
| 7439-97-6 | Mercury | 0.0021 |   | 0.20 | •                  | 5089171        |        | 019              | 4/4/2005         | 1                |

U Result is less than the instrument detection limit (IDL).



## **Total Metals Analysis Data Sheet**

Lab Name:

STL DENVER

Client Sample ID:

05Z0992-003.001

Lot/SDG Number:

05Z0992

Lab WorkOrder:

G69AJ

Matrix:

SOIL

Lab Sample ID:

D5C290333-003

% Moisture:

Date/Time Collected:

03/28/05 10:45

Units:

MG/KG

Date/Time Received:

| CAS No.   | Analyte                  | Солс. | Q   | RL   | Dilution<br>Factor | QC Batch<br>ID | Method | Instrument<br>ID | Analysis<br>Date | Analysis<br>Time |
|-----------|--------------------------|-------|-----|------|--------------------|----------------|--------|------------------|------------------|------------------|
| 7429-90-5 | Aluminum                 | 7500  |     | 40   | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:09            |
| 7440-36-0 | Antimony                 | 0.37  | υ   | 12   | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 14:00            |
| 7440-38-2 | Arsenic                  | 3.0   |     | 2.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 14:00            |
| 7440-39-3 | Barium                   | 110   |     | 20   | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 14:00            |
| 7440-41-7 | Beryllium                | 0.35  |     | 0.20 | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:09            |
| 7440-42-8 | Boron                    | 8.9   |     | 1.5  | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:09            |
| 7440-43-9 | Cadmium                  | 0.10  | В   | 1.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 14:00            |
| 7440-70-2 | Calcium                  | 67000 |     | 1000 | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:09            |
| 7440-47-3 | Chromium                 | 15    | •   | 0.40 | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 14:00            |
| 7440-48-4 | Cobalt                   | 6.5   | В   | 10   | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 14:00            |
| 7440-50-8 | Copper                   | 15    |     | 5.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 14:00            |
| 7439-89-6 | Iron                     | 8000  |     | 20   | 1:                 | 5088571        | 6010B  | 002              | 4/1/2005         | 14:09            |
| 7439-92-1 | Lead                     | 4.7   |     | 0.60 | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 14:00            |
| 7439-93-2 | Lithium                  | 7.3   | В   | 20   | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:09            |
| 7439-95-4 | Magnesium                | 2300  |     | 1000 | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:09            |
| 7439-96-5 | Manganese                | 180   |     | 3.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 14:00            |
| 7439-98-7 | Molybdenum               | 3.1   | В   | 6.0  | 1                  | 5088571        | 6010B  | 016              | - 4/1/2005       | 14:00            |
| 7440-02-0 | Nickel                   | 11    |     | 8.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 14:00            |
| 7440-09-7 | Potassium                | 2100  |     | 1000 | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:09            |
| 7782-49-2 | Selenium                 | 0.39  | U   | 1.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 14:00            |
| 7631-86-9 | Silica as SiO2, Dissolve | 770   |     | 5.0  | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:09            |
| 7440-22-4 | Silver                   | 0.35  | В   | 1.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 14:00            |
| 7440-23-5 | Sodium                   | 300   | В . | 1000 | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:09            |
| 7440-24-6 | Strontium                | 250   |     | 40   | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 14:00            |
| 7440-28-0 | Thallium                 | 0.53  | U   | 2.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 14:00            |
| 7440-31-5 | Tin                      | 2.4   | В   | 40   | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 14:00            |
| 7440-32-6 | Titanium                 | 450   |     | 0.20 | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 14:09            |
| 11-09-6   | Uranium                  | 1.6   | U · | 40   | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         | 14:00            |
| 7440-62-2 | Vanadium                 | 70    |     | 8.0  | 1                  | 5088571        | 6010B  | 016              | 4/1/2005         |                  |



# Total Metals Analysis Data Sheet

Lab Name:

STL DENVER

Client Sample ID:

05Z0992-003.001

Lot/SDG Number:

05Z0992

Lab WorkOrder:

<u>G69AJ</u>

Matrix:

<u>SOIL</u>

Lab Sample ID:

D5C290333-003

% Moisture:

Date/Time Collected:

03/28/05 10;45

Units:

MG/KG

Date/Time Received:

| L | CAS No.   | Analyte | Conc. | Q | RL  | Dilution<br>Factor | QC Batch<br>ID | Method | Instrument<br>ID | Anaļysis<br>Date | Analysis<br>Time |
|---|-----------|---------|-------|---|-----|--------------------|----------------|--------|------------------|------------------|------------------|
| ı | 7440-66-6 | Zinc    | 44    |   | 4.0 | 1                  | 5088571        | 6010B  | 002              | 4/1/2005         | 1                |

U Result is less than the instrument detection limit (IDL).

B Estimated result. Result is less than RL and greater than or equal to the IDL.



# Total Metals Analysis Data Sheet

Lab Name:

STL DENVER

Client Sample ID:

05Z0992-003.001

Lot/SDG Number:

05Z0992

Lab WorkOrder:

<u>G69AJ</u>

Matrix:

SOIL

Lab Sample ID:

D5C290333-003

% Moisture:

Date/Time Collected:

03/28/05 10:45

Units:

MG/KG

Date/Time Received:

| CAS No.   | Analyte | Conc.  | Q | RL   | Dilution<br>Factor | QC Batch<br>ID | Method | Instrument<br>ID | Analysis<br>Date | Analysis<br>Time |
|-----------|---------|--------|---|------|--------------------|----------------|--------|------------------|------------------|------------------|
| 7439-97-6 | Mercury | 0.0025 |   | 0.20 | 1                  | 5089171        | 7471A  | 019              | 4/4/2005         | 1                |

U Result is less than the instrument detection limit (IDL).

B Estimated result. Result is less than RL and greater than or equal to the IDL.

| S                      |  |                    |                                       |         |                            |                          |                          |                               | <b></b>   | <del></del>              |
|------------------------|--|--------------------|---------------------------------------|---------|----------------------------|--------------------------|--------------------------|-------------------------------|---|--------------------------|
| Site: RFETS            |  |                    |                                       | CT LINE | SE CHETODINE               | 4 3 4 D I C   4 N        | Y Vete DEOUEET           |                               | COC: 05Z1155#001  | Page 1 of 1              |
| Sampling Co:           | STOLLER  |                    |                                       | CHAIN   | DE COSTOD 2/5.             | AMPLE AN                 | ALYSIS REQUEST           |                               |   |                          |
| nv                     |  |                    | (time/dat                             |         | /Requeste<br>DOLSKY, STEW/ | ART / MYERS              | . KIM                    | Telephone N                   | do. 303-994-4098 / 7106   |                          |
| RIN: 05Z11             | 55   |                    |                                       |         | g Origin B46               |                          |                          | Purchase<br>Order/            | EHF460CH  |                          |
| Project Title          | B460 PAINT SAMPL   | ES.                |                                       | Logboo  | k Na. 99                   | Stepl                    | tin                      | Ice Chest No                  | · NA  | Temp. QL                 |
| To LAB: ST             | LDEN   |                    |                                       | Shipme  |                            | SULAR                    |                          | Bill of Ladir<br>Air Bill No. | NA VA   |                          |
| Protocol               | TBD  |                    |                                       | Related | coc NA                     | -                        |                          | PRE                           | 50316-RISS-007  | _                        |
| Are acid preserved sar | PLE HAZARDS/REMARKS  mples DOT hazardous per 40 CFR/F rdous substances present? YES No | irt 136.3 Table II | YES (P)                               |         |                            |                          | LAB REQUEST              | 0C 05 21                      | ne  17/05. DATA IS DUE BY COB 3/20/05.  155#001 A for signed on this Coc.  e Analysis |                          |
|                        | Customer   |                    | l. Dat                                | e/Time  | Location                   | Container<br>(size/type) |                          |                               | e Analysis<br>d Title) [TAT]/{Parameter List}   | Preservative;<br>Packing |
| 95Z1155                | Number<br>wests.de   | Matrix<br>SOLID    | · · · · · · · · · · · · · · · · · · · | 1310    | B460                       | 10-G<br>P                | MET-A-022 (METALS (LEAD) |                               |   | None;<br>Box             |
| -001.001<br>05Z1155    | east side  | SOLID              | 1                                     | 1320    | B460                       | 10-G                     | MET-A-022 (METALS        | - 6010/6010B - SIN            | GLE)[3dF]   | None;<br>Box             |
| -002.001               |  |                    |                                       | 1240    |                            | Р                        | {LEAD}                   |                               |   | Box                      |
|                        |  |                    |                                       |         |                            |                          |                          |                               |   |                          |
|                        |  |                    |                                       | 11/     | 1                          |                          |                          | )                             |   |                          |
| Reimahisted By:        | 44 4/15/05   | Date/Time          | Received By:                          | 1/4     | 1/15/04                    | Date/Time                | Relinquished by:         | 4/15/05 10                    | Date Time Receive By:   | Date/Time                |
| Relinquished By:       |  | Date/Time          | Relinguished                          | Ву      |                            | Date/Time                | Relipquished By          |                               | Date/Time   Relinquished By:  | Date/Time                |
| Relinquished By:       |  | Date/Time          | Received By:                          |         |                            | Date/Time                | Ralinquished By:         |                               | Date/Time Received By:  | Date/Time                |
| Relinquished By:       |  | Date/Time          | Received By:                          |         |                            | Date/Time                | Relinquished By:         |                               | Date/Time Received By:  | Date/Time                |
|                        |  |                    |                                       |         |                            |                          |                          |                               | COC Versi   | on: 3 (ASMSCOC_R0.RPT)   |



# **Total Metals Analysis Data Sheet**

Lab Name:

STL DENVER

Client Sample ID:

05Z1155-001.001

Lot/SDG Number:

05Z1155

Lab WorkOrder:

G8HLF

FOUSDG Mailinei.

SOLID

Lab Sample ID:

D5D150389-001

% Moisture:

Date/Time Collected:

04/14/05 13:10

Units:

Matrix:

MG/KG

Date/Time Received:

04/15/05 12:20

| CAS No.   | Analyte | Conc. | Q | RL  | Dilution<br>Factor | QC Batch<br>ID | ;<br>Method | Instrument<br>IĐ | Analysis<br>Date | Analysis<br>Time |
|-----------|---------|-------|---|-----|--------------------|----------------|-------------|------------------|------------------|------------------|
| 7439-92-1 | Lead    | 18000 |   | 6.0 |                    | 5105426        | l           | 020              | 4/18/2005        | , ,              |

U Result is less than the instrument detection limit (IDL).



## Total Metals Analysis Data Sheet

Lab Name:

STL DENVER

Client Sample ID:

05Z1155-002.001

Lot/SDG Number:

05Z1155

Lab WorkOrder:

G8HLH

Matrix:

**SOLID** 

Lab Sample ID:

D5D150389-002

% Moisture:

Date/Time Collected:

04/14/05 13:20

Units:

MG/KG

Date/Time Received:

04/15/05 12:20

|     | CAS No.   | Analyte | Conc. | Q | RL  | Dilution<br>Factor | QC Batch<br>ID | Method | Instrument<br>ID | Analysis<br>Date | Analysis<br>Time |
|-----|-----------|---------|-------|---|-----|--------------------|----------------|--------|------------------|------------------|------------------|
| - 1 | 7439-92-1 | Lead    | 16000 |   | 6.0 | 10                 |                | 6010B  | 020              | 4/18/2005        | 12:35            |

U Result is less than the instrument detection limit (IDL).

# ATTACHMENT E Data Quality Assessment (DQA) Detail

#### DATA QUALITY ASSESSMENT (DQA)

#### **VERIFICATION & VALIDATION OF RESULTS**

V&V of the data confirm that appropriate quality controls are implemented throughout the sampling and analysis process, and that any substandard controls result in qualification or rejection of the data in question. The required quality controls and their implementation are summarized in a tabular, checklist format for each category of data – radiological surveys and chemical analyses (specifically asbestos and beryllium).

DQA criteria and results are provided in a tabular format for each suite of surveys or chemical analyses performed; the radiological survey assessment is provided in Table E-1, Asbestos in Table E-2, Beryllium in Table E-3 and Metals in Table E-4. A data completeness summary for all results is given in Table E-5.

All relevant Quality records supporting this report are maintained in the RISS Characterization Project Files. This report will be submitted to the CERCLA Administrative Record for permanent storage within 30 days of approval by the Regulators. All radiological data are organized into Survey Packages, which correlate to unique (MARSSIM) Survey Units. Chemical data are organized by RIN (Report Identification Number) and are traceable to the sample number and corresponding sample location.

Beta/gamma survey designs were not implemented for Building 460 based on the conservatism of the transuranic limits used as DCGLs in the unrestricted release decision process. Survey designs were implemented based on the transuranic limits used as DCGLs in the unrestricted release decision process. All survey results were evaluated against, and were less than the Transuranic DCGL<sub>w</sub> (100 dpm/100cm<sup>2</sup>) and the Uranium DCGL<sub>w</sub> (5,000 dpm/100cm<sup>2</sup>) unrestricted release limits.

Consistent with EPA's G-4 DQO process, the radiological survey design (for those survey units performed per PDS requirements) was optimized by checking actual measurement results (acquired during pre-demolition surveys) against model output with original estimates. Use of actual sample/survey (result) variances in the MARSSIM DOO model confirms that an adequate number of surveys were acquired.

#### **SUMMARY**

In summary, the data presented in this report have been verified and validated relative to the quality requirements and project decisions as stated in the original DQOs. All data are useable based on qualifications stated herein and are considered satisfactory without qualification. All media surveyed and sampled yielded results less than their associated action levels and with acceptable certainties except the below anomalous condition:

Mixing tanks located in room 141 stored and processed chromium. Because chromium was the only chemical stored in these tanks, only sampling and analysis for RCRA Metals was performed. Two samples plus one duplicate (core samples-RIN05Z0992) were taken and analyzed for RCRA Metals. Initial analytical results indicate a Total Concentration for lead greater than 100 mg/kg. This indicates the potential for lead to be above the regulatory limit of 5 ppm. However, the sample taken from behind the tank did not have this level of lead concentration. The only difference between the sample locations was the type of paint covering the floor. Therefore, two confirmatory samples (RIN#05Z1155) of the paint in front of the tank were taken. The analysis confirmed that the paint is lead-based. However, Environmental Waste Compliance Guidance #27, Lead-based Paint (LBP) and Leadbased paint Debris Disposal, states that LBP debris generated outside of currently identified high contamination areas shall be managed as non-hazardous (solid) waste, and additional analysis for characteristics of hazardous waste derived from LBP is not a requirement for disposal. Because there are no high contamination areas in Building 460, this paint may be disposed of as non-hazardous (solid) waste.

Prior to the completion of the RLC, asbestos sampling performed in 1994 and 2003. The 1994 sampling determined that there is Category 1 non-friable asbestos containing vinyl asbestos floor tile and mastic (1.4%) in the Room 151 area. Category 1 non-friable asbestos containing caulk was also identified on the building exterior flashing between the concrete and metal walls that contain 1.0% asbestos. However, since these materials are Category 1 non-friable ACM, asbestos abatement is not necessary prior to demolition and the demolition debris can be managed as sanitary waste. Since the floor tile and caulking samples were collected in 1994, no sample location maps were available for this report. All 2003 laboratory results were non-detect for asbestos.

Based upon an independent review of the radiological data, it was determined that the original project DQOs satisfied MARSSIM guidance. All facility contamination levels were below applicable unrestricted release levels. Minimum survey requirements were met, sampling/survey protocol was performed in accordance with applicable procedures, survey units were properly designed and bounded, and instrument performance and calibration were within acceptable limits thereby ensuring data accuracy criteria. All results meet the PDS unrestricted release criteria.

Chain of Custody was intact; documentation was complete, hold times were acceptable (where applicable,) and packaging integrity/custody seals were maintained throughout the sampling/analysis process. Level 2 Isolation Controls have been posted to prevent the inadvertent introduction of contamination into the facility. On this basis, Building 460 meets the unrestricted release criteria with the confidences stated herein and can be demolished.

Table E-1 V&V of Radiological - Building 460

| V&V CRITERIA, RADIO | OLGICAL SURVEYS   | K-H RSP 16.00<br>MARSSIM (NU   |                 |   |
|---------------------|---|--|-----------------|---|
|                     | QUALITY REQUIREMENTS  |  |                 |   |
|                     | Parameters  | Measure  | Frequency       | COMMENTS  |
| ACCURACY            | initial calibrations  | 90% <x<110%< td=""><td>≥1</td><td>Multi-point calibration through the measurement range encountered in the field; programmatic records.</td></x<110%<> | ≥1              | Multi-point calibration through the measurement range encountered in the field; programmatic records.   |
|                     | daily source checks   | 80% <x<120%< td=""><td>≥1/day</td><td>Performed daily/within range.</td></x<120%<>   | ≥1/day          | Performed daily/within range.   |
|                     | local area background: Field  | typically < 10 dpm   | ≥1/day          | All local area backgrounds were within expected ranges (i.e., no elevated anomalies.)   |
| PRECISION           | field duplicate measurements for TSA  | ≥5% of real survey points  | ≥10% of reals   | N/A   |
| REPRESENTATIVENESS  | MARSSIM methodology: Survey<br>Units 460002, 460003, 460504<br>(interior) and EXT-B-001 (exterior). | statistical and<br>biased  | NA              | Random w/ statistical confidence.   |
|                     | Survey Maps   | NA   | NA              | Random and biased measurement locations controlled/mapped to ±1m.   |
|                     | Controlling Documents (Characterization Pkg; RSPs)  | qualitative  | NA              | Refer to the Characterization Package (planning document) for field/sampling procedures (located in Project files); thorough documentation of the planning, sampling/analysis process, and data reduction into formats. |
| COMPARABILITY       | units of measure  | dpm/100cm <sup>2</sup>   | NA              | Use of standardized engineering units in the reporting of measurement results.  |
| COMPLETENESS        | Plan vs. Actual surveys usable results vs. unusable   | >95%<br>>95%   | NA              | See Table E-5 for details.  |
| SENSITIVITY         | detection limits  | TSA: ≤50<br>dpm/100cm <sup>2</sup><br>RA: ≤10<br>dpm/100cm <sup>2</sup>  | All<br>measures | MDAs ≤ 50% DCGL <sub>w</sub> per MARSSIM guidelines (RLC performed to PDS requirements).  |

Table E-2 V&V of Asbestos Results - Building 460

| V&V CRITERIA, CHEMIC | AL ANALYSES  | DATA PACKA                         |              |   |
|----------------------|--|------------------------------------|--------------|---|
|                      | METHOD: EPA 600/R-<br>93/116                           |                                    |              |   |
|                      |  | RIN>                               | RIN 04Z0218  |   |
| QUALITY RI           | EQUIREMENT   | Measure                            | Frequency    | COMMENTS  |
| ACCURACY             | Calibrations:<br>Initial/continuing                    | below<br>detectable<br>amounts     | ≥1           | Semi-quantitative, per (microscopic) visual estimation.   |
| PRECISION            | Actual Number Sampled<br>LCSD<br>Lab duplicates        | all below<br>detectable<br>amounts | ≥ 3 samples  | Semi-quantitative, per (microscopic) visual estimation.   |
| REPRESENTATIVENESS   | COC  | Qualitative                        | NA           | Chain-of-Custody intact: completed paperwork, containers w/ custody seals.  |
|                      | Hold times/preservation                                | Qualitative                        | NA           | N/A   |
|                      | Controlling Documents (Plans, Procedures, maps, etc.)  | Qualitative                        | NA           | See original Chemical Characterization Plan (planning document); for field/sampling procedures (located in project file;) thorough documentation of the planning, sampling/analysis process, and data reduction into formats. |
| COMPARABILITY        | Measurement Units                                      | % by bulk volume                   | NA           | Use of standardized engineering units in the reporting of measurement results.  |
| COMPLETENESS         | Plan vs. Actual samples<br>Usable results vs. unusable | Qualitative                        | NA           | See Table E-5: final number of samples at Certified Inspector's discretion.   |
| SENSITIVITY          | Detection limits                                       | <1% by volume                      | All measures | N/A   |

# Table E-3 V&V of Beryllium - Building 460 $\,$


| V&V CRITERIA, CHEM | MICAL ANALYSES  | DATA PACKA                              |  |  |
|--------------------|---|---|--|--|
| BERYLLIUM          | Prep: NMAM 7300<br>METHOD: OSHA ID-125G               | LAB>                                    | Johns Manville Corp.<br>Littleton, Co. |  |
| <u></u>            | TY REQUIREMENTS                                       | RIN>                                    | RIN 05D0695                            |  |
| QUAL               | 11 KBQOIKEMBA15                                       | Measure                                 | Frequency                              | COMMENTS   |
| ACCURACY           | Calibrations<br>Initial                               | linear calibration                      | ≥1                                     | All results were below associated action levels. |
|                    | Continuing  | 80%<%R<120%                             | ≥1                                     |  |
|                    | LCS/MS  | 80%<%R<120%                             | ≥l                                     |  |
|                    | Blanks - lab & field                                  | <mdl< td=""><td>≥1</td><td></td></mdl<> | ≥1                                     |  |
|                    | interference check std (ICP)                          | NA                                      | NA                                     | <u></u>  |
| PRECISION          | LCSD  | 80%<%R<120%<br>(RPD<20%)                | ≥1                                     | -  |
|                    | field duplicate                                       | all results < RL                        | ≥l                                     |  |
| REPRESENTATIVENESS | COC   | Qualitative                             | NA                                     |  |
|                    | hold times/preservation                               | Qualitative                             | NA                                     |  |
|                    | Controlling Documents (Plans, Procedures, maps, etc.) | Qualitative                             | NA                                     |  |
| COMPARABILITY      | measurement units                                     | ug/100cm²                               | NA                                     |  |
| COMPLETENESS       | Plan vs. Actual samples usable results vs. unusable   | >95%<br>>95%                            | NA                                     |  |
| SENSITIVITY        | detection limits                                      | MDL of 0.00084 ug/100cm <sup>2</sup>    | all measures                           |  |

# Table E-4 V&V of Metals – Building 460

| V&V CRITERIA, CHEMI | CAL ANALYSES   |            | DATA PACKAG        | E                        |  |
|---------------------|--|------------|--------------------|--------------------------|--|
|                     |  |            | LAB>               | Severn Trent             |  |
| Metals (total)      | METHOD: SW6010/6020                                      |            |                    | Denver, Co.              |  |
|                     |  |            | RIN>               | RIN05Z0992<br>RIN05Z1155 |  |
|                     | QUALITY REQUIR   | EMENT      |                    |                          | COMMENTS   |
|                     |  |            | Measure            | frequency                | No qualifications significant enough to change project decisions, lead |
| ACCURACY            | calibrations   | Initial    | linear calibration | ≥1/batch                 | paint may be managed and disposed of as sanitary waste.                |
|                     |  | Continuing | 80%<%R<120%        | ≥1/batch                 |  |
|                     | LCS  |            | 80%<%R<120%        |                          |  |
|                     | MS   |            | 75%<%R<125%        | ≥1/batch                 |  |
|                     | blanks   | Lab        | mg/kg              | ≥1/batch                 |  |
|                     | serial dilutions   |            | %D<10%             | ≥1/batch                 |  |
|                     | interference check std (ICP)                             |            | 80%<%R<120%        | bracket batch            |  |
| PRECISION           | MSD  |            | RPD<30%            | ≥1/batch                 |  |
|                     | field duplicate  |            | all results < RL   | ≥1/batch                 |  |
| REPRESENTATIVENES   | COC  |            | Qualitative        | NA                       | -  |
| S                   | hold times/preservation                                  |            | ≤180 days          | NA                       |  |
|                     | Controlling Documents<br>(Plans, Procedures, Maps, etc.) |            | Qualitative        | NA                       |  |
| COMPARABILITY       |  |            | mg/kg              | NA                       |  |
| COMPLETENESS        | Plan vs. Actual samples usable results vs. unusable      |            | >95%<br>>95%       | NA                       |  |
| SENSITIVITY         | detection limits   |            | Various            | all analytes             |  |

| ANALYTE   | Building/Area/<br>Unit     | Sample Number<br>Planned<br>(Real & QC) | Sample Number<br>Taken<br>(Real & QC) | Project Decisions (Conclusions) & Uncertainty   | Comments (RIN, Analytical Method, Qualifications, etc.)   |
|-----------|----------------------------|---|---------------------------------------|---|---|
| Asbestos  | Building 460<br>(interior) | 3 samples<br>(interior)                 | 3 samples<br>(interior)               | No ACM found,<br>all results < 1%<br>by volume  | 40 CFR763.86; 5 CCR 1001-10; EPA 600/R-93/110<br>RIN04Z0218   |
| Beryllium | Building 460<br>(interior) | 100 swipes<br>(75 random/25 biased)     | 125 swipes<br>(75 random/50 biased)   | No beryllium contamination found, all results are below associated action levels      | OSHA ID-125G  RIN 05D0695  No results above action level (0.2ug/100cm²) or investigative level (0.1 ug/100cm²).   |
| Metals    | Building 460 (interior)    | 2 plus I duplicate<br>(solid)           | 4 plus 1 duplicate<br>(solid)         | 'Metal contamination identified potentially greater than the regulatory limit (5 ppm) | RIN05Z0992: sample map locations 1-3 RIN05Z1155: sample map locations 4 and 5 <sup>1</sup> Metal contamination identified potentially greater than the regulatory limit (5 ppm). However, per Environmental Waste Compliance Guidance #27, Lead-based Paint (LBP) and Lead-based paint Debris Disposal, because the area is not a high contamination area, the paint may be managed and disposed of as non-hazardous waste. Refer to secti 4.3 and Attachment E (DQA Detail) for detailed discussion. |

| ANALYTE      | Building/Area/<br>Unit                   | Sample Number<br>Planned<br>(Real & QC)   | Sample Number<br>Taken<br>(Real & QC)     | Project Decisions (Conclusions) & Uncertainty            | Comments (RIN, Analytical Method, Qualifications, etc.) |
|--------------|--|---|---|--|---|
| Radiological | Survey Unit: 460002                      | 202 α TSA<br>(151 random/51 biased)       | 202 α TSA<br>(151 random/51 biased)       | No contamination<br>found at any<br>location; all values | Transuranic DCGLs used.                                 |
|              | Building 460 North Offices, High         | 202 α Smears<br>(151 random/51 biased)    | 202 α Smears<br>(151 random/51 biased)    | below PDS<br>unrestricted release<br>limits              |   |
|              | Bay and Loading<br>Dock Areas - Interior | 9 QC TSA 5% scan of all interior          | 9 QC TSA 5% scan of all interior          |  |   |
|              |  | surfaces                                  | surfaces                                  |  |   |
| Radiological | Survey Unit: 460003                      | 95 α TSA<br>(70 random/25 biased)         | 95 α TSA<br>(70 random/25 biased)         | No contamination<br>found at any<br>location; all values | Transuranic DCGLs used.                                 |
|              | Building 460 First Floor South           | 95 α Smears<br>(70 random/25 biased)      | 95 α Smears<br>(70 random/25 biased)      | below PDS<br>unrestricted release<br>limits              |   |
|              | Offices -Interior                        | 4 QC TSA 5% scan of all interior          | 4 QC TSA 5% scan of all interior          |  |   |
|              |  | surfaces                                  | surfaces                                  |  |   |
| Radiological | Survey Area 5<br>Survey Unit: 460504     | 89 a TSA<br>(64 random/25 biased)         | 89 α TSA<br>(64 random/25 biased)         | No contamination<br>found at any<br>location; all values | Transuranic DCGLs used.                                 |
|              | Building 460<br>Second Floor Office      | 89 α Smears<br>(64 random/25 biased)      | 89 α Smears<br>(64 random/25 biased)      | below PDS<br>unrestricted release<br>limits              |   |
|              | Areas - Interior                         | 4 QC TSA 5% scan of all interior surfaces | 4 QC TSA 5% scan of all interior surfaces |  |   |



## TABLE C-2: BUILDING RCRA/CERCLA DATA SUMMARY

| Sample Location /<br>Media          | Sample Number                                  | Map<br>Number | Result (mg/kg)  |
|-------------------------------------|--|---------------|---|
| Building 460 core samples from slab | 05Z0992-001.001<br>through 05Z0992-<br>003.001 | 1-3           | Lead results in two samples were above 100 mg/kg, indicating results may possibly be above the TCLP regulatory limit of 5 ppm |
| Building 460 paint chip samples     | 05Z1155-001.001 -<br>05Z1155-002.001           | 4-5           | Lead results demonstrate paint is lead-based with total values of 18000 and 16000 mg/kg                                       |

#### **RCRA Toxicity Characteristic Limits**

| Analyte         | Regulatory limit (mg/L) |
|-----------------|-------------------------|
| Arsenic (D004)  | 5.0                     |
| Barium (D005)   | 100.0                   |
| Cadmium (D006)  | 1.0                     |
| Chromium (D007) | 5.0                     |
| Lead (D008)     | 5.0                     |
| Mercury (D009)  | 0.2                     |
| Selenium (D010) | 1.0                     |
| Silver (D011)   | 5.0                     |